

CN MOTORS PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-41 Autobay@Kaki Bukit, Singapore 417883

Email: admin@cnmotorspl.com

Tel: 6509 5545 Fax: 6509 5567

UEN: 202026492W

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

06/01/2020

TP EQ.
VERON.

Accident date: 05/01/2020

Estimated repair cost for vehicle no: YN8028Z MITSUBISHI CANTER FEB21ER3SDEB 15'

CHASSIS: FEB21EA10094

3.0 M '16

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Side Mirror Top Cover		\$80.00
2	1	Front R/H Side Mirror Lower Garnish		\$35.00
3	1	Front R/H Side Mirror Stay		\$270.00
4	1	Front R/H Corner Panel		\$506.00
5	1	Front R/H Head Lamp		\$501.00
6	1	Front R/H Signal Lamp		\$266.00
7	1	Front R/H Side Lamp		\$251.00
8	1	Front Bumper		\$1,060.00
9	1	Front R/H Bumper Side Cover		\$341.00
10	2	Front R/H Door Hinge	\$135.00	\$270.00
11	1	Front R/H Step Panel		\$613.00

2189.

2391.75

Subtotal :- \$4,193.00

Labour charges

To remove & refit front R/H door and door components

\$280.00

To check wiring

\$100.00

Tuff kote

\$100.00

Panel beating

\$800.00

Spray painting

\$800.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Subtotal :- \$2,080.00

Total:- \$6,273.00

(2.7K)

04 Days

total: 3371.75

L/S: 2.7K

04 Days