

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Xiao Tony.

* Claim Type: Third Party
Accident Date: 15/01/2021
TP Veh Reg No: GBE331U

Estimate No: EST2100016
Date: 18 Jan 2021
Veh Reg No: SMM2866H
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3201177951
Reg. Date: 25/06/2019
Your Ref No: GBE331U

Estimate Repair Cost to Vehicle No :SMM2866H

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC FRT FENDER RH <i>Dented</i>	743.20	✓
2	1 PC FRT FENDER COWLING RH <i>dented</i>	275.40	✓
3	1 PC FRT BUMPER <i>New</i>	492.90	x
4	1 PC FRT BUMPER RETAINER RH <i>New</i>	47.30	✓
5	1 PC HEADLAMP RH <i>New</i>	1,144.90	x
6	1 PC FRT SHOCK ABSORBER RH <i>Best</i>	378.90	✓
7	1 PC FRT KNUCKLE ARM RH <i>Dented</i>	544.70	✓
8	1 PC FRT WHEEL HUB RH <i>Best</i>	488.20	✓
9	1 PC STEERING RACK & PINION <i>New</i>	1,603.40	+
10	1 PC FRT LOWER ARM RH <i>Best</i>	1,001.40	✓ 625.
		6,720.30	
	Less 25%	1,680.08	5,040.25
Special Net			
11	1 SET FRT FENDER COWLING CLIPS RH <i>New</i>	40.00	20
12	1 SET FRT BUMPER CLIPS <i>New</i>	40.00	x
13	1 PC FRT SPORTS RIM RH <i>Int</i>	850.00	600
14	1 PC FRT TYRE RH <i>New</i>	300.00	x
		1,230.00	1,230.00
Labour			
15	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	700.00	400
16	1 TO SPRAY PAINTING	600.00	200
17	1 TO SPRAY UNDERSEAL	80.00	x
18	1 TO REMOVE AND REFIT UNDERCARRIAGE	500.00	220
19	1 TO CHECK WIRING	50.00	30
20	1 TO CHECK WHEEL ALIGNMENT	120.00	80
		2,050.00	2,050.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 15/01/2021
TP Veh Reg No: GBE331U

Estimate No: EST2100016
Date: 18 Jan 2021
Veh Reg No: SMM2866H
Make/Model: TOYOTA VIOS 1.5E
AUTO
Chasis No: MR2B23F3201177951
Reg. Date: 25/06/2019
Your Ref No: GBE331U

Estimate Repair Cost to Vehicle No :SMM2866H

Quantity	Description	List Price	Amount
		S\$	S\$
	Total		S\$ 8,320.25
	Add GST @ 7%		582.42
	Total Amount Payable		S\$ 8,902.67

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND NINE HUNDRED AND TWO AND CENTS SIXTY SEVEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Li
4/5 18/01/20 05 days.
total: 3891.55
4/5: 3050.
3050.

MotorMed Pte Ltd

8 Kaki Bukit Ave 4 #02-14/44

Premier @ Kaki Bukit

Singapore 415875

Phone Number: 69777077

Fax Number: 69777080

Customer:			Date: 18/1/2021 11:06 AM			
Company: KANG CAR			VIN SMM2866H			
License NO:			Technician:			
Odometer:			Order NO:			
VEHICLE ALIGNMENT REPORT						
TOYOTA, VIOS, 07-12 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	0°39'	2°09'	----
		Right	----	0°39'	2°09'	----
	Camber	Left	-0°42'	-0°58'	0°32'	-0°42'
		Right	-0°42'	-0°58'	0°32'	-0°42'
	Toe	Left	-0°12'	-0°03'	0°09'	-0°12'
		Right	1°51'	-0°03'	0°09'	1°51'
Total		1°39'	-0°05'	0°18'	1°39'	
Rear	Camber	Left	-1°06'	-1°45'	-0°15'	-1°06'
		Right	-0°24'	-1°45'	-0°15'	-0°24'
	Toe	Left	0°12'	0°06'	0°18'	0°12'
		Right	0°12'	0°06'	0°18'	0°12'
		Total	0°24'	0°11'	0°35'	0°24'
	Thrust Angle		0°00'	----		0°00'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	----	----	----	----
		Right	----	----	----	----
Included Angle		Left	----	----	----	----
		Right	----	----	----	----
Toe Out On Turns		Left	----	----	----	----
		Right	----	----	----	----
Max Turn Inside		Left	----	----	----	----
		Right	----	----	----	----
Toe Curve Change		Left	----	----	----	----
		Right	----	----	----	----
Setback		Front	-0.2"	----	----	-0.2"
		Rear	-0.0"	----	----	-0.0"
Track Width Diff.			0.7"			0.7"
			-0.2"			-0.2"
Front Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Rear Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Frame Angle						----