



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

29/12/2020

ESTIMATED REPAIR CHECKLIST

TO : INDIA INSURANCE	VEHICLE REGISTRATION NO.: SMR2560M
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: HONDA / FIT
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER: GK33420703
ACCIDENT DATE/TIME :	CONTACT PERSON : NIGEL (97253727)

PARTS	QTY	PER UNIT	PRICES
1 FRONT BUMPER <i>Rehnd</i>	1	\$ 584.20	\$ 584.20 ✓
2 FRONT BUMPER SIDE HOLDER <i>new</i>	2	\$ 25.50	\$ 51.00 ✓
3 FRONT FENDER <i>Dented</i>	2	\$ 435.00	\$ 870.00 ✓
4 FRONT FENDER INNER SHIELD <i>LH Rehnd</i>	2	\$ 138.60	\$ 277.20 <i>138.60</i>
5 HEADLAMP <i>Crashd. LH</i>	2	\$ 1,170.60	\$ 2,341.20 <i>1170.60</i>
6 HEADLAMP LOWER BRACKET <i>LH crashd</i>	2	\$ 65.00	\$ 130.00 <i>65</i>
7 FRONT RH DOOR <i>Dented</i>	1	\$ 966.20	\$ 966.20 ✓
8 FRONT RH DOOR WING MIRROR <i>Damaged</i>	1	\$ 527.50	\$ 527.50 ✓
9 FRONT RH DOOR HINGE <i>new</i>	2	\$ 95.00	\$ 190.00 +
10 FRONT RH DOOR INNER TRIM BOARD <i>new</i>	1	\$ 605.20	\$ 605.20 +
11 FRONT RH DOOR GLASS REGULATOR GEAR <i>new</i>	1	\$ 392.00	\$ 392.00 +
12 FRONT RH DOOR LOCK <i>new</i>	1	\$ 375.00	\$ 375.00 +
13 FRONT RH DOOR WEATHERSTRIPE <i>new</i>	1	\$ 138.40	\$ 138.40 +
14 REAR RH DOOR <i>Dented</i>	1	\$ 845.40	\$ 845.40 ✓
15 REAR RH DOOR HINGE <i>new</i>	2	\$ 95.00	\$ 190.00 +
16 REAR RH DOOR WEATHERSTRIPE <i>new</i>	1	\$ 122.30	\$ 122.30 +
17 FRONT LOWER ARM <i>Best</i>	2	\$ 395.00	\$ 790.00 ✓
18 FRONT KNUCKLE ARM <i>Dented</i>	2	\$ 505.20	\$ 1,010.40 ✓
19 FRONT WHEEL HUB C/W BEARING <i>Best</i>	2	\$ 188.30	\$ 376.60 ✓
20 FRONT SHOCK ABSORBER <i>Best</i>	2	\$ 366.00	\$ 732.40 ✓
21 STEERING RACK & PINION <i>new</i>	1	\$ 1,885.30	\$ 1,885.30 ✓

8127.90

6502.32

SUBTOTAL :	\$ 11,895.10
LESS 20% :	\$ 2,379.02
PARTS TOTAL :	\$ 9,516.08

SPECIAL NETT	QTY	PER UNIT	PRICES
1 FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 <i>30</i>
2 FRONT FENDER INNER SHIELD CLIPS <i>new</i>	2 SET	\$ 30.00	\$ 60.00 <i>30</i>
3 FRONT RH DOOR BLACK TAPE <i>new</i>	1 SET	\$ 60.00	\$ 60.00 ✓
4 FRONT RH DOOR INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 +
5 REAR RH DOOR BLACK TAPE <i>new</i>	1 SET	\$ 60.00	\$ 60.00 ✓
6 FRONT WHEEL RIM <i>cut</i>	2	\$ 800.00	\$ 1,600.00 <i>1000</i>
7 FRONT TYRE <i>new</i>	2	\$ 250.00	\$ 500.00 X.
S/N TOTAL :			\$ 2,380.00

1180



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

LABOUR CHARGES		PRICES	ADJUSTMENT
1	PANEL BEATING	\$ 1,600.00	100
2	SPRAY PAINTING	\$ 1,600.00	1300
3	WIRING	\$ 50.00	30
4	TO TRANSFER FRONT RH DOOR FITTINGS	\$ 150.00	80
5	TO TRANSFER REAR RH DOOR FITTINGS	\$ 150.00	80
6	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80
7	TO REMOVE FRONT LH & RH UNDERCARRIAGE	\$ 700.00	440
8	TOWING FEES	\$ 60.00	
LABOR TOTAL :		\$ 4,460.00	

3170.

ESTIMATE REPORT	
TOTAL PARTS COST:	\$ 11,896.08
TOTAL LABOUR COST:	\$ 4,460.00
TOTAL REPAIR COST:	\$ 16,356.08
PART BY PART / LUMP SUM:	
NO. OF REPAIR DAYS:	

SURVEYOR DETAILS	
SURVEYOR NAME:	_____
CONTACT:	_____
EMAIL:	_____
DATE :	_____
TIME :	_____

total: 10852.32
L/S: 8650.
09 Days