

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Shawn Ngo Sau Wei

Date: 22 Feb 2021

**Preliminary Advice**

|                    |                                                                                             |                         |              |
|--------------------|---------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLG5264T                                                                                  | Accident Date           | : 15/01/2021 |
| TP Vehicle No      | : SMK6587Y                                                                                  | Assignment Date         | : 28/01/2021 |
| Make               | : HONDA SHUTTLE                                                                             | Est. Duration of Repair | : 2          |
| Date of Inspection | : 19/01/2021                                                                                |                         |              |
| Inspection At      | : FASTECH AUTO PTE LTD (HQ)<br>1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |          |              |
|-----------------------------|----------|--------------|
| Repairer's Estimate (Gross) | :S\$     | 7,852.60     |
| Revised Amount              | :S\$     | 3,284.16     |
| Check Items (Estimated)     | :S\$     | 0.00         |
| Total                       | :S\$     | 3,284.16     |
| <br>Repair Sum              | <br>:S\$ | <br>2,950.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.