



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC19022934/Qtf3e2-1	Date: 20/01/2021
			Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJZ 2893X		Veh. Inspected	SLL 7730A
Policy No.			Coverage (\$)	0.00
Claim No.	19/19/20/VP05/022830		Excess (\$)	0.00
Assign From	ONG LI LI		Assign Date	12/11/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CITY 1.5 SV		c.c	1497
Engine No.	HIDDEN		Year of Reg.	2017
Chassis No.	MRHGM6660HP000598		Colour	RED
Odometer	-		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	FAIR			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
R/H Front Tyre		185/55 R16	BRIDGESTONE	5 mm
L/H Front Tyre		185/55 R16	BRIDGESTONE	5 mm
R/H Rear Tyre		185/55 R16	BRIDGESTONE	5 mm
L/H Rear Tyre		185/55 R16	BRIDGESTONE	5 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/12/2019		Inspection Date	31/12/2019
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	