

ACS REC BY: Sun Pin

REP:

JPC

PRS

ASSIGNMENT

From

Date:

31/12/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLL 7730A

at Workshop m/s

My car consultant

of

53 Ubi Ave 1 # 01-33

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLL 7730A

Yr Regn: 09/Mar/2017

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda City 1.5 SV

c.c 1497

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

-

C/No:

MRHGM6660HP000598

Gen. Cond: Good (Fair) Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/55 R16

R: 185/55 R16

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 25/12/2019

D.O.I. 31/12/2019

Survey held at

My Car.

1148AM

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 57,000

PV: 45,491

NV: 11,503

Repair Range

3K - 4K

RECEIVED 17 JAN 2020

LUMP SUM \$3200, 5DAY
(RED: 960;23%)

Date/Time, File Pass to?



: Preli. Report

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

120

Transportation:

Photos

Others

TOTAL

120

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Insp (\$)

Weekend (\$)

Report Format: PRS

Lump Sum / L.R. / C