



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 9932E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	RH FRONT DOOR	TO REPAIR SEE LABOUR	6,500.00	-
1	RH SIDE STEP PANEL	DISTORTED	4,500.00	1,150.00
1	RH SIDE STEP PANEL GARNISH	DISTORTED	2,500.00	450.00
	LESS 10% DISCOUNT		-1,350.00	-160.00
			12,150.00	1,440.00
<u>SPECIAL NETT ITEMS</u>				
10	RH SIDE STEP PANEL GARNISH CLIPS (SN)	NECESSARY	50.00	50.00
1	RH REAR SPORT RIM (SN)	NOT NECESSARY	1,200.00	-
			1,250.00	50.00
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF RH FRONT DOOR.		1,200.00	300.00
	TO SPRAY PAINT ON ACCIDENT AREAS.		1,200.00	500.00
	TO REMOVE AND REFIT LH STEP PANEL,COMPARTMENT.	NOT NECESSARY	100.00	-
	TO RUST PROOFING ACCIDENT AREAS.		150.00	30.00
			2,650.00	830.00
GRAND TOTAL			16,050.00	2,320.00
RECOMMENDED COST OF REPAIRS				2,320.00

Report Ref No. CS/AGI21000898/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.