



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/III20011028/R1tf3e2-1	
			Date: 22/01/2021	
			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 3292D	Veh. Inspected	SGQ 1260L	
Policy No.	MCOM0015	Coverage (\$)	0.00	
Claim No.	MCT20100173	Excess (\$)	0.00	
Assign From	CARINE KEK PHEI SER	Assign Date	19/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS 1.6L	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	MR053REH104515311	Colour	GREY	
Odometer	156830 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	6 mm	
L/H Front Tyre	205/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/10/2020	Inspection Date	13/10/2020	
Survey held at	B'S PERFORMANCE PTE LTD 7 SOON LEE STREET ISPACE #01-38 SINGAPORE 627668			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	