

Re —

Survey had inspected the vehicle yesterday.

~~L.H. wing~~

~~Co. Area~~. L.H. wing mirror found to be in working condition. Can fold and ~~unf~~ open without any ~~difficulty~~ ^{difficulty}.
Some ~~some~~ minor scratches found on the outer cover and not related to this incident.

For the ~~first~~ suspension, owner inform workshop that he heard noises coming from the front left side when ~~driving~~ ^{driving} the vehicle after the accident. ~~the~~ ^{owner} workshop informed him that it could be due to the front fender inner shield ~~brushing~~ ^{brushing} against the wheel. Vehicle had almost completed repair and our ~~survey~~ ^{surveyor} had tested the vehicle and there ~~was no~~ ^{was no} abnormal sound heard.

We ~~is~~ will close ~~at~~ case and submit our bill for for inspection. done.