

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 20 January 2021 4:01 PM  
**To:** AXA - Peter Wang; SUR  
**Subject:** SLC 5430B-DOA: 5/1/2021 (AXA REF: S1M02ZWM)  
**Attachments:** LKKPhotosIn4.pdf

Dear Peter,

We refer to the above mentioned.

Surveyor had inspected the vehicle yesterday.

LH wing mirror found to be in working condition can fold and open without any difficulty. Some minor scratches found on the outer cover and not related to this incident.

For the suspension, owner inform workshop that he heard noise coming from the front left side when driving the vehicle after the accident, workshop informed owner that it could be due to the front fender inner shield brushing against the wheel.

Vehicle had almost completed repair and our surveyor had tested the vehicle and there was no abnormal sound heard.

We will close case and submit our bill for inspection done.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)