

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLC 5430B

Vehicle Model : MAZDA 6

Chassis Number : JM6GJ1072G0232084

Estimated Repair Cost

S/N	Parts Description	Qty		Cost Price
1	BONNET	1	\$	500.00
2	BONNET HINGES LHS	1	\$	40.00
3	FRONT GRILLE (SHORT)	8	\$	320.00
4	FRONT GRILLE (LONG)	2	\$	120.00
5	FRONT GRILLE CLIPS	10	\$	30.00
6	FRONT GRILLE BASED	1	\$	90.00
7	FRONT GRILLE CHROME MOULDING	2	\$	240.00
8	FRONT GRILLE TOP GARNISH	1	\$	250.00
9	FRONT GRILLE TOP GARNISH CLIPS	10	\$	50.00
10	FRONT GRILLE LOGO	1	\$	50.00
11	FRONT BUMPER	1	\$	500.00
12	FRONT BUMPER CLIPS	10	\$	30.00
13	FRONT BUMPER RETAINER LHS	1	\$	10.00
14	FOG LAMP LHS	1	\$	400.00
15	FOG LAMP COVER LHS	1	\$	20.00
16	FOG LAMP CHROME MOULDING LHS	1	\$	100.00
17	FRONT LHS FENDER	1	\$	380.00
18	FRONT LHS SPLASH SHIELD	1	\$	103.00
19	FRONT LHS SPLASH SHIELD CLIPS	10	\$	30.00
20	LHS HEADLAMP	1	\$	1500.00
21	SUPPORT PANEL	1	\$	280.00
22	FRONT LHS TYRE	1	\$	350.00

Spare Parts Total Price

\$ 5393.00

Cost Price +10%

\$ 539.30

\$ 5,932.30

ELITE AM PTE LTD

280 Woodlands Industrial Park E5, #01-17,
Harvest @ Woodlands Singapore 757322
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLC 5430B
Vehicle Model : MAZDA 6
Chassis Number : JM6GJ1072G0232084

S/N	Labour Descriptions	Charges	
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIR FRONT SUPPORT PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$	1800.00
2	TO SPRAY PAINTING ON: FRONT BUMPER, BONNET (INNER & OUTER), FRONT LHS FENDER, SUPPORT PANEL.	\$	1500.00
3	TO CHECK ELECTRICAL WIRINGS & LIGHTS FUNCTION, INCLUSIVE FOCUS HEADLIGHTS.	\$	120.00
4	CHECK & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	\$	280.00
5	WHEEL ALIGNMENT	\$	120.00
Labour Total		\$	3820.00
Parts & Labour Total		\$	9752.30