

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0059/2021/NS
DATE : 19-Jan-21
WIP : 12010

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR TONG SENG FATT DAVID
ADDRESS : 86 BEDOK TERRACE
SINGAPORE 469245
TELEPHONE : HP +65 96837898
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070051671
VEHICLE NO : **SGV 1006 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8W
MODEL YEAR : 25/2/2020
ENGINE NO : CHZ C35246
CHASSIS NO : WAUZZZ8V9LA002732
MILEAGE : 14905KM
DATE IN : 18-Jan-21
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jan-21
PLACE OF ACCIDENT : PIE

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGV 1006 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	
4	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG.	S/N \$ 3,600.00	
5	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00	
6	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$ 400.00	
SUB TOTAL LABOUR CHARGES		: \$ 6,320.00	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGV 1006 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW FRONT WINDSCREEN FOIL AND RESET SYSTEM.	S/N \$ 300.00	
8	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00	
9	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS.	S/N \$ 560.00	
10	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS. CUT OUT AND REWELD BOTH FRONT FENDER TOP SUPPORTS. TO REPAIR BOTH FRONT DOORS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 9,100.00	
11	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT FENDER TOP SUPPORTS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	\$ 8,200.00	
12	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK.	S/N \$ 384.00	
TOTAL LABOUR CHARGES		: \$ 25,064.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 1,987.00	
2	FRONT BUMPER FIXING PARTS		\$ 187.00	
3	FRONT BUMPER GUIDE SECTIONB - LH/RH	2	\$ 78.00	
4	FRONT BUMP[ER GRILLE - CENTRE		\$ 160.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 536.00	
6	FRONT BUMPER CLOSING ELEMENT - LH/RH	2	\$ 594.00	
7	FRONT BUMPER COVER TRIM - LH/RH	2	\$ 326.00	
8	WHEEL HOUSING LINER ADAPTER - LH/RH	2	\$ 76.00	
9	RADIATOR GRILLE		\$ 1,406.00	
10	RADIATOR GRILLE CLOSING ELEMENT		\$ 191.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2	\$ 376.00	
12	FRONT REINFORCEMENT BEAM		\$ 795.00	
13	FRONT BUMPER FOAM FILLER PIECE		\$ 189.00	
14	FOAM FILER PIECE COVER		\$ 122.00	
15	AIRCON STICKER	NEC	\$ 8.00	
16	CAUTION SIGN STICKER	NEC	\$ 14.00	
17	SIGNAL HORN - LH HIGH TONE		\$ 200.00	
18	SIGNAL HORN - RH LOW TONE		\$ 200.00	
19	FRONT FENDER - LH/RH	2	\$ 1,702.00	
20	FRONT FENDER ATTACHMENT PARTS		\$ 72.00	
SUB TOTAL SPARE PARTS		:	\$ 9,219.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT FENDER CENTRE BRACKET - LH/RH	2	\$	78.00
22 FRONT FENDER BRACKET - LH/RH	2	\$	56.00
23 FRONT FENDER BRACE - LH/RH	2	\$	192.00
24 WHEEL HOUSING LINER - LH/RH	2	\$	338.00
25 WHEEL HOUSING LINER ATTACHMENT PARTS		\$	89.00
26 BONNET		\$	3,134.00
27 BONNET ATTACHMENT PARTS		\$	165.00
28 BONNET LID HINGE - LH/RH	2	\$	124.00
29 BONNET GAS FILLED STRUT		\$	104.00
30 BONNET CATCH HOOK		\$	90.00
31 BONNET STRIKER - LH/RH	2	\$	220.00
32 BONNET EDGE PROTECTION		\$	28.00
33 TOP FENDER LEDGE COVER - LH/RH	2	\$	82.00
34 BONNET CATCH HOOK		\$	63.00
35 BONNET LID LOCK	2	\$	427.00
36 BONNET BOWDEN CABLE - CENTRE		\$	58.00
37 BONNET LID LOCK CABLE		\$	74.00
38 BONNET SOUND ABSORBER		\$	219.00
39 PLENUM CHAMBER COVER		\$	179.00
40 LED HEADLIGHT - LH/RH	2	\$	10,910.00
SUB TOTAL SPARE PARTS	:	\$	16,630.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 LIFT CYLINDER - LH/RH	2	\$ 284.00	
42 LIFT CYLINDER HOSE		\$ 68.00	
43 HEADLIGHT WASHER PUMP		\$ 155.00	
44 WINDSCREEN WASHER PUMP		\$ 125.00	
45 WASH WATER RESERVOIR		\$ 206.00	
46 FRONT FENDER TOP SUPPORT - LH		\$ 72.00	
47 FRONT FENDER TOP SUPPORT - RH		\$ 74.00	
48 A-PILLAR CONNECTING PLATE - LH INNER		\$ 227.00	
49 A-PILLAR CONNECTING PLATE - RH INNER		\$ 329.00	
50 LOCK CARRIER		\$ 727.00	
51 AIRCON CONDENSER		\$ 529.00	
52 REFRIGERANT LINE		\$ 475.00	
53 REFRIGERANT LINE		\$ 619.00	
54 REFRIGERANT LINE		\$ 518.00	
55 EXTERNAL TEMPERATURE SENSOR BRACKET		\$ 19.00	
56 EXTERNAL TEMPERATURE SENSOR		\$ 59.00	
57 RADIATOR		\$ 951.00	
58 ADDITIONAL RADIATOR		\$ 859.00	
59 READY MIX COOLANT		\$ 179.00	
60 RADIATOR BRACKET	2	\$ 82.00	
SUB TOTAL SPARE PARTS	:	\$ 6,557.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
61 RADIATOR BUSH - LOWER	2	\$	19.00
62 RADIATOR AIR GUIDE - LH/RH	2	\$	50.00
63 RADIATOR AIR GUIDE - UPPER CENTRE		\$	12.00
64 AIR INTAKE AIR DUCT COVER		\$	29.00
65 AIR INTAKE AIR GUIDE		\$	56.00
66 AIR INTAKE AIR GUIDE		\$	66.00
67 INTER COOLER GASKET		\$	14.00
68 AIR INTAKE AIR GUIDE		\$	20.00
69 AIR INTAKE WATER DRAINAGE HOSE		\$	33.00
70 AIR INTAKE AIR FILTER		\$	272.00
71 AIR INTAKE MANIFOLD - OUTER		\$	139.00
72 AIR INTAKE MANIFOLD - INNER		\$	666.00
73 AIR INTAKE MANIFOLD - INNER SEAL		\$	14.00
74 CHARGE AIR COOLER		\$	752.00
75 CHARGE AIR COOLER SEAL		\$	14.00
76 CHARGE AIR COOLER SEAL		\$	14.00
77 FRONT WINDSCREEN		\$	1,072.00
78 RAIN SENSOR GEL FOIL		\$	137.00
79 INTERIOR MIRROR SPRING CLIP		\$	21.00
80 PRIMER		\$	20.00
SUB TOTAL SPARE PARTS	:	\$	3,420.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
81	STEERING WHEEL AIRBAG		\$ 3,421.00	
82	AIRBAG UNIT		\$ 4,414.00	
83	HEAD AIRBAG UNIT - LH/RH	2	\$ 3,726.00	
84	KNEE AIRBAG UNIT		\$ 1,863.00	
85	AIRBAG CONTROL UNIT		\$ 1,647.00	
86	AIRBAG CRASH SENSOR	3	\$ 1,167.00	
87	STEERING WHEEL		\$ 2,374.00	
88	DASHBOARD		\$ 4,259.00	
89	AIR VENT		\$ 151.00	
90	LOUDSPEAKER COVER		\$ 94.00	
91	SEAT BELT - LH/RH		\$ 2,206.00	
92	SEAT BELT HEIGHT ADJUSTER	2	\$ 383.00	
93	MOULDED HEADLINER		\$ 1,771.00	
94	FRONT FOLDING GRAB HANDLE - LH/RH	2	\$ 283.00	
95	REAR FOLDING GRAB HANDLE - LH/RH	2	\$ 284.00	
96	A-PILLAR TRIM - LH/RH	2	\$ 322.00	
97	B-PILLAR TRIM - LH/RH	2	\$ 434.00	
98	C-PILLAR TRIM - LH/RH	2	\$ 302.00	
99	D-PILLAR TRIM - LH/RH	2	\$ 232.00	
100	WATER DEFLECTOR STRIP - LH/RH	2	\$ 186.00	
SUB TOTAL SPARE PARTS		:	\$ 29,519.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
101	TRIM STRIP STRIP - LH/RH	2	\$	514.00
102	WINDOW SLOT SEAL - LH/RH FRONT	2	\$	618.00
103	FRONT WINDSCREEN SEALANT	S/N	\$	200.00
104	METAL FILLER POWDER	S/N	\$	280.00
105	STONE CHIP	S/N	\$	180.00
106	CAVITY WAX	S/N	\$	140.00
107	ACRYLIC SEALANT	S/N	\$	180.00
108	FRONT NO PLATE	S/N	\$	60.00
109	SUNDRIES		\$	500.00
TOTAL SPARE PARTS		:	\$	68,017.00
TOTAL LABOUR CHARGES		:	\$	25,064.00
GRAND TOTAL		:	\$	93,081.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT