

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0059/2021/NS  
**DATE** : 19-Jan-21  
**WIP** : 12010

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

**Hi Adrian**

**23 days exclude 2 PH and 5 Sunda  
8-Jun-21**

**ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT**

**TEL: 6841 0055 - FAX: 6256 4315**

**OWNER'S NAME** : MR TONG SENG FATT DAVID  
**ADDRESS** : 86 BEDOK TERRACE  
SINGAPORE 469245  
**TELEPHONE** : HP +65 96837898  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2070051671  
**VEHICLE NO** : **SGV 1006 D**  
**MODEL CODE** : AUDI A3 SEDAN 1.0 TFSI 8W  
**MODEL YEAR** : 25/2/2020  
**ENGINE NO** : CHZ C35246  
**CHASSIS NO** : WAUZZZ8V9LA002732  
**MILEAGE** : 14905KM  
**DATE IN** : 18-Jan-21  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 18-Jan-21  
**PLACE OF ACCIDENT** : PIE

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGV 1006 D**

| S/N                             | NATURE OF JOBS                                                                                                                                                                                                                          |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|---------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                               | TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.                                                                                                                                                                                      | S/N \$ | 280.00               |                               |
| 2                               | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                                                                                                          | S/N \$ | 360.00               | \$ 360.00                     |
| 3                               | TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.                                                               | S/N \$ | 1,200.00             | \$ 1,200.00                   |
| 4                               | TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG. | S/N \$ | 3,600.00             | \$ 3,600.00                   |
| 5                               | TO RENEW FRONT WINDSCREEN.                                                                                                                                                                                                              | S/N \$ | 480.00               | \$ 480.00                     |
| 6                               | TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.                                                                                                                                                                                             | S/N \$ | 400.00               | \$ 400.00                     |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                         | :      | <b>\$ 6,320.00</b>   | <b>\$ 6,040.00</b>            |

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGV 1006 D**

| S/N                         | NATURE OF JOBS                                                                                                                                                                                                                                                                               | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
|                             |                                                                                                                                                                                                                                                                                              | <i>c/f</i>            | <i>\$ 6,040.00</i>         |
| 7                           | TO RENEW FRONT WINDSCREEN FOIL AND RESET SYSTEM.                                                                                                                                                                                                                                             | S/N \$ 300.00         |                            |
| 8                           | TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.                                                                                                                                                                                                                                        | S/N \$ 200.00         | <i>\$ 150.00</i>           |
| 9                           | TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS.                                                                                                                                                                                      | S/N \$ 560.00         | <i>\$ 280.00</i>           |
| 10                          | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS. CUT OUT AND REWELD BOTH FRONT FENDER TOP SUPPORTS. TO REPAIR BOTH FRONT DOORS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 9,100.00           | <i>\$ 5,500.00</i>         |
| 11                          | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT FENDER TOP SUPPORTS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.                                                                                            | \$ 8,200.00           | <i>\$ 3,500.00</i>         |
| 12                          | TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK.                                                                                                                                                                                                                                           | S/N \$ 384.00         | <i>\$ 384.00</i>           |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                                                                                              | <b>: \$ 25,064.00</b> | <b><i>\$ 15,854.00</i></b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D**

| S/N                          | PARTS DESCRIPTION                           | QTY | DAMAGED PARTS & PRICES |                    |
|------------------------------|---------------------------------------------|-----|------------------------|--------------------|
|                              |                                             |     | S/NETT                 | REMARKS            |
| 1                            | FRONT BUMPER                                |     | \$ 1,987.00            | \$ <b>1,589.60</b> |
| 2                            | FRONT BUMPER FIXING PARTS                   |     | \$ 187.00              |                    |
| 3                            | FRONT BUMPER GUIDE SECTIONB - LH/RH         | 2   | \$ 78.00               | \$ <b>60.96</b>    |
| 4                            | FRONT BUMPER GRILLE - CENTRE                |     | \$ 160.00              | \$ <b>128.00</b>   |
| 5                            | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE |     | \$ 536.00              |                    |
| 6                            | FRONT BUMPER CLOSING ELEMENT - LH/RH        | 2   | \$ 594.00              | \$ <b>474.40</b>   |
| 7                            | FRONT BUMPER COVER TRIM - LH/RH             | 2   | \$ 326.00              |                    |
| 8                            | WHEEL HOUSING LINER ADAPTER - LH/RH         | 2   | \$ 76.00               |                    |
| 9                            | RADIATOR GRILLE                             |     | \$ 1,406.00            | \$ <b>1,124.80</b> |
| 10                           | RADIATOR GRILLE CLOSING ELEMENT             |     | \$ 191.00              | \$ <b>152.40</b>   |
| 11                           | FRONT BUMPER AIR GUIDE GRILLE - LH/RH       | 2   | \$ 376.00              | \$ <b>300.00</b>   |
| 12                           | FRONT REINFORCEMENT BEAM                    |     | \$ 795.00              | \$ <b>636.00</b>   |
| 13                           | FRONT BUMPER FOAM FILLER PIECE              |     | \$ 189.00              | \$ <b>151.20</b>   |
| 14                           | FOAM FILER PIECE COVER                      |     | \$ 122.00              | \$ <b>97.20</b>    |
| 15                           | AIRCON STICKER                              | NEC | \$ 8.00                | \$ <b>5.68</b>     |
| 16                           | CAUTION SIGN STICKER                        | NEC | \$ 14.00               | \$ <b>10.88</b>    |
| 17                           | SIGNAL HORN - LH HIGH TONE                  |     | \$ 200.00              |                    |
| 18                           | SIGNAL HORN - RH LOW TONE                   |     | \$ 200.00              |                    |
| 19                           | FRONT FENDER - LH/RH                        | 2   | \$ 1,702.00            | \$ <b>1,360.80</b> |
| 20                           | FRONT FENDER ATTACHMENT PARTS               |     | \$ 72.00               |                    |
| <b>SUB TOTAL SPARE PARTS</b> |                                             | :   | <b>\$ 9,219.00</b>     | <b>\$ 6,091.92</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D**

| S/N PARTS DESCRIPTION        |                                     | QTY | DAMAGED PARTS & PRICES |           |                  |
|------------------------------|-------------------------------------|-----|------------------------|-----------|------------------|
|                              |                                     |     | S/NETT                 | REMARKS   |                  |
|                              | <i>c/f</i>                          |     |                        | \$        | <b>6,091.92</b>  |
| 21                           | FRONT FENDER CENTRE BRACKET - LH/RH | 2   | \$ 78.00               | \$        | <b>61.44</b>     |
| 22                           | FRONT FENDER BRACKET - LH/RH        | 2   | \$ 56.00               | \$        | <b>43.68</b>     |
| 23                           | FRONT FENDER BRACE - LH/RH          | 2   | \$ 192.00              | \$        | <b>152.96</b>    |
| 24                           | WHEEL HOUSING LINER - LH/RH         | 2   | \$ 338.00              |           |                  |
| 25                           | WHEEL HOUSING LINER ATTACHMENT PART |     | \$ 89.00               |           |                  |
| 26                           | BONNET                              |     | \$ 3,134.00            | \$        | <b>2,507.20</b>  |
| 27                           | BONNET ATTACHMENT PARTS             |     | \$ 165.00              |           |                  |
| 28                           | BONNET LID HINGE - LH/RH            | 2   | \$ 124.00              | \$        | <b>97.76</b>     |
| 29                           | BONNET GAS FILLED STRUT             |     | \$ 104.00              |           |                  |
| 30                           | BONNET CATCH HOOK                   |     | \$ 90.00               | \$        | <b>71.28</b>     |
| 31                           | BONNET STRIKER - LH/RH              | 2   | \$ 220.00              | \$        | <b>175.20</b>    |
| 32                           | BONNET EDGE PROTECTION              |     | \$ 28.00               | \$        | <b>22.00</b>     |
| 33                           | TOP FENDER LEDGE COVER - LH/RH      | 2   | \$ 82.00               |           |                  |
| 34                           | BONNET CATCH HOOK                   |     | \$ 63.00               | \$        | <b>50.32</b>     |
| 35                           | BONNET LID LOCK                     | 2   | \$ 427.00              | \$        | <b>341.60</b>    |
| 36                           | BONNET BOWDEN CABLE - CENTRE        |     | \$ 58.00               | \$        | <b>46.00</b>     |
| 37                           | BONNET LID LOCK CABLE               |     | \$ 74.00               |           |                  |
| 38                           | BONNET SOUND ABSORBER               |     | \$ 219.00              | \$        | <b>175.20</b>    |
| 39                           | PLENUM CHAMBER COVER                |     | \$ 179.00              |           |                  |
| 40                           | LED HEADLIGHT - LH/RH               | 2   | \$ 10,910.00           | \$        | <b>8,728.00</b>  |
| <b>SUB TOTAL SPARE PARTS</b> |                                     | :   | <b>\$ 16,630.00</b>    | <b>\$</b> | <b>18,564.56</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D**

| S/N                          | PARTS DESCRIPTION                    | QTY        | DAMAGED PARTS & PRICES |                     |
|------------------------------|--------------------------------------|------------|------------------------|---------------------|
|                              |                                      |            | S/NETT                 | REMARKS             |
|                              |                                      | <i>c/f</i> |                        | <b>\$ 18,564.56</b> |
| 41                           | LIFT CYLINDER - LH/RH                | 2          | \$ 284.00              |                     |
| 42                           | LIFT CYLINDER HOSE                   |            | \$ 68.00               |                     |
| 43                           | HEADLIGHT WASHER PUMP                |            | \$ 155.00              |                     |
| 44                           | WINDSCREEN WASHER PUMP               |            | \$ 125.00              |                     |
| 45                           | WASH WATER RESERVOIR                 |            | \$ 206.00              | <b>\$ 164.40</b>    |
| 46                           | FRONT FENDER TOP SUPPORT - LH        |            | \$ 72.00               |                     |
| 47                           | FRONT FENDER TOP SUPPORT - RH        |            | \$ 74.00               |                     |
| 48                           | A-PILLAR CONNECTING PLATE - LH INNER |            | \$ 227.00              | <b>\$ 181.60</b>    |
| 49                           | A-PILLAR CONNECTING PLATE - RH INNER |            | \$ 329.00              | <b>\$ 262.80</b>    |
| 50                           | LOCK CARRIER                         |            | \$ 727.00              | <b>\$ 581.60</b>    |
| 51                           | AIRCON CONDENSER                     |            | \$ 529.00              | <b>\$ 422.80</b>    |
| 52                           | REFRIGERANT LINE                     |            | \$ 475.00              |                     |
| 53                           | REFRIGERANT LINE                     |            | \$ 619.00              |                     |
| 54                           | REFRIGERANT LINE                     |            | \$ 518.00              |                     |
| 55                           | EXTERNAL TEMPERATURE SENSOR BRACKET  |            | \$ 19.00               | <b>\$ 14.56</b>     |
| 56                           | EXTERNAL TEMPERATURE SENSOR          |            | \$ 59.00               |                     |
| 57                           | RADIATOR                             |            | \$ 951.00              | <b>\$ 760.40</b>    |
| 58                           | ADDITIONAL RADIATOR                  |            | \$ 859.00              | <b>\$ 686.80</b>    |
| 59                           | READY MIX COOLANT                    |            | \$ 179.00              | <b>\$ 143.04</b>    |
| 60                           | RADIATOR BRACKET                     | 2          | \$ 82.00               | <b>\$ 65.28</b>     |
| <b>SUB TOTAL SPARE PARTS</b> |                                      | :          | <b>\$ 6,557.00</b>     | <b>\$ 21,847.84</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D**

| S/N                          | PARTS DESCRIPTION                 | QTY        | DAMAGED PARTS & PRICES |                     |
|------------------------------|-----------------------------------|------------|------------------------|---------------------|
|                              |                                   |            | S/NETT                 | REMARKS             |
|                              |                                   | <i>c/f</i> |                        | <b>\$ 21,847.84</b> |
| 61                           | RADIATOR BUSH - LOWER             | 2          | \$ 19.00               | <b>\$ 15.04</b>     |
| 62                           | RADIATOR AIR GUIDE - LH/RH        | 2          | \$ 50.00               | <b>\$ 38.88</b>     |
| 63                           | RADIATOR AIR GUIDE - UPPER CENTRE |            | \$ 12.00               | <b>\$ 9.44</b>      |
| 64                           | AIR INTAKE AIR DUCT COVER         |            | \$ 29.00               | <b>\$ 22.72</b>     |
| 65                           | AIR INTAKE AIR GUIDE              |            | \$ 56.00               | <b>\$ 44.48</b>     |
| 66                           | AIR INTAKE AIR GUIDE              |            | \$ 66.00               | <b>\$ 52.32</b>     |
| 67                           | INTER COOLER GASKET               |            | \$ 14.00               |                     |
| 68                           | AIR INTAKE AIR GUIDE              |            | \$ 20.00               | <b>\$ 15.36</b>     |
| 69                           | AIR INTAKE WATER DRAINAGE HOSE    |            | \$ 33.00               |                     |
| 70                           | AIR INTAKE AIR FILTER             |            | \$ 272.00              |                     |
| 71                           | AIR INTAKE MANIFOLD - OUTER       |            | \$ 139.00              |                     |
| 72                           | AIR INTAKE MANIFOLD - INNER       |            | \$ 666.00              |                     |
| 73                           | AIR INTAKE MANIFOLD - INNER SEAL  |            | \$ 14.00               |                     |
| 74                           | CHARGE AIR COOLER                 |            | \$ 752.00              |                     |
| 75                           | CHARGE AIR COOLER SEAL            |            | \$ 14.00               |                     |
| 76                           | CHARGE AIR COOLER SEAL            |            | \$ 14.00               |                     |
| 77                           | FRONT WINDSCREEN                  |            | \$ 1,072.00            | <b>\$ 857.60</b>    |
| 78                           | RAIN SENSOR GEL FOIL              |            | \$ 137.00              | <b>\$ 109.20</b>    |
| 79                           | INTERIOR MIRROR SPRING CLIP       |            | \$ 21.00               |                     |
| 80                           | PRIMER                            |            | \$ 20.00               | <b>\$ 15.76</b>     |
| <b>SUB TOTAL SPARE PARTS</b> |                                   | :          | <b>\$ 3,420.00</b>     | <b>\$ 23,028.64</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D**

| S/N                          | PARTS DESCRIPTION                 | QTY        | DAMAGED PARTS & PRICES |                     |
|------------------------------|-----------------------------------|------------|------------------------|---------------------|
|                              |                                   |            | S/NETT                 | REMARKS             |
|                              |                                   | <i>c/f</i> |                        | <b>\$ 23,028.64</b> |
| 81                           | STEERING WHEEL AIRBAG             | \$         | 3,421.00               | <b>\$ 2,736.80</b>  |
| 82                           | AIRBAG UNIT                       | \$         | 4,414.00               | <b>\$ 3,531.20</b>  |
| 83                           | HEAD AIRBAG UNIT - LH/RH          | 2 \$       | 3,726.00               | <b>\$ 2,980.80</b>  |
| 84                           | KNEE AIRBAG UNIT                  | \$         | 1,863.00               | <b>\$ 1,490.40</b>  |
| 85                           | AIRBAG CONTROL UNIT               | \$         | 1,647.00               | <b>\$ 1,317.60</b>  |
| 86                           | AIRBAG CRASH SENSOR               | 3 \$       | 1,167.00               | <b>\$ 933.60</b>    |
| 87                           | STEERING WHEEL                    | \$         | 2,374.00               | <b>\$ 1,899.20</b>  |
| 88                           | DASHBOARD                         | \$         | 4,259.00               | <b>\$ 3,407.20</b>  |
| 89                           | AIR VENT                          | \$         | 151.00                 |                     |
| 90                           | LOUDSPEAKER COVER                 | \$         | 94.00                  |                     |
| 91                           | SEAT BELT - LH/RH                 | \$         | 2,206.00               | <b>\$ 1,764.80</b>  |
| 92                           | SEAT BELT HEIGHT ADJUSTER         | 2 \$       | 383.00                 | <b>\$ 306.40</b>    |
| 93                           | MOULDED HEADLINER                 | \$         | 1,771.00               | <b>\$ 1,416.80</b>  |
| 94                           | FRONT FOLDING GRAB HANDLE - LH/RH | 2 \$       | 283.00                 | <b>\$ 226.40</b>    |
| 95                           | REAR FOLDING GRAB HANDLE - LH/RH  | 2 \$       | 284.00                 | <b>\$ 226.40</b>    |
| 96                           | A-PILLAR TRIM - LH/RH             | 2 \$       | 322.00                 | <b>\$ 256.80</b>    |
| 97                           | B-PILLAR TRIM - LH/RH             | 2 \$       | 434.00                 |                     |
| 98                           | C-PILLAR TRIM - LH/RH             | 2 \$       | 302.00                 |                     |
| 99                           | D-PILLAR TRIM - LH/RH             | 2 \$       | 232.00                 | <b>\$ 184.80</b>    |
| 100                          | WATER DEFLECTOR STRIP - LH/RH     | 2 \$       | 186.00                 |                     |
| <b>SUB TOTAL SPARE PARTS</b> |                                   | :          | <b>\$ 29,519.00</b>    | <b>\$ 45,707.84</b> |

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D**

| S/N                         | PARTS DESCRIPTION                 | QTY        | DAMAGED PARTS & PRICES |                     |
|-----------------------------|-----------------------------------|------------|------------------------|---------------------|
|                             |                                   |            | S/NETT                 | REMARKS             |
|                             |                                   | <i>c/f</i> |                        | <b>\$ 45,707.84</b> |
| 101                         | TRIM STRIP STRIP - LH/RH          | 2          | \$ 514.00              |                     |
| 102                         | WINDOW SLOT SEAL - LH/RH FRONT    | 2          | \$ 618.00              |                     |
| 103                         | FRONT WINDSCREEN SEALANT          | S/N        | \$ 200.00              | <b>\$ 200.00</b>    |
| 104                         | METAL FILLER POWDER               | S/N        | \$ 280.00              | <b>\$ 280.00</b>    |
| 105                         | STONE CHIP                        | S/N        | \$ 180.00              | <b>\$ 180.00</b>    |
| 106                         | CAVITY WAX                        | S/N        | \$ 140.00              | <b>\$ 140.00</b>    |
| 107                         | ACRYLIC SEALANT                   | S/N        | \$ 180.00              | <b>\$ 180.00</b>    |
| 108                         | FRONT NO PLATE                    | S/N        | \$ 60.00               | <b>\$ 60.00</b>     |
| 109                         | <b>ADDED PARTS - SEE ATTACHED</b> |            | <b>\$ 1,265.00</b>     | <b>\$ 1,012.00</b>  |
| 110                         | SUNDRIES                          |            | \$ 500.00              | <b>\$ 144.96</b>    |
| <b>TOTAL SPARE PARTS</b>    |                                   | :          | <b>\$ 85,470.84</b>    | <b>\$ 47,904.80</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                   | :          | <b>\$ 25,064.00</b>    | <b>\$ 15,854.00</b> |
| <b>GRAND TOTAL</b>          |                                   | :          | <b>\$ 110,534.84</b>   | <b>\$ 63,758.80</b> |

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

BL-09/03/21



55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183  
Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)



## Supplementary Estimate

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br>Attn: Mr. Adrian Ling - Motor Claims Dept<br><b>Tel: 6841 0055 / Fax: 6256 4315</b> |                            | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0059/2021/NS<br>27-Jan-21<br>CHANG<br>1 of 1<br>SGV 1006 D<br>AUDI A3 SEDAN 1.0 TFSI |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|-------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------|
| Quantity                                                                                                                                                                                      | Description                | Unit Price                                                                                                        | Amount                                                                                     |
| <u>Parts</u>                                                                                                                                                                                  |                            |                                                                                                                   |                                                                                            |
| 1                                                                                                                                                                                             | RADIATOR FAN WITH FAN RING | \$ 1,265.00                                                                                                       | \$ <b>1,012.00</b>                                                                         |
|                                                                                                                                                                                               | <b>GRAND TOTAL</b>         | \$ <b>1,265.00</b>                                                                                                | \$ <b>1,012.00</b>                                                                         |

For Premium Automobiles Pte Ltd

---

Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT