

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0059/2021/NS
DATE : 19-Jan-21
WIP : 12010

Xiao Chun

6375880

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 • FAX: 6256 4315

OWNER'S NAME	:	MR TONG SENG FATT DAVID
ADDRESS	:	86 BEDOK TERRACE SINGAPORE 469245
TELEPHONE	:	HP +65 96837898
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070051671
VEHICLE NO	:	SGV 1006 D
MODEL CODE	:	AUDI A3 SEDAN 1.0 TFSI 8W
MODEL YEAR	:	25/2/2020
ENGINE NO	:	CHZ C35246
CHASSIS NO	:	WAUZZZ8V9LA002732
MILEAGE	:	14905KM
DATE IN	:	18-Jan-21
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	18-Jan-21
PLACE OF ACCIDENT	:	PIE

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGV 1006 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	S/N \$ 280.00	X
2	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓ ✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	✓ ✓
4	TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING, BOTH CURTAIN AIR BAGS AND KNEE AIRBAG.	S/N \$ 3,600.00	✓ ✓
5	TO RENEW FRONT WINDSCREEN.	S/N \$ 480.00	✓ ✓
6	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN.	S/N \$ 400.00	✓ ✓
SUB TOTAL LABOUR CHARGES		: <u>\$ 6,320.00</u>	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGV 1006 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW FRONT WINDSCREEN FOIL AND RESET SYSTEM.	S/N \$ 300.00	X
8	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00	150 ✓
9	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS.	S/N \$ 560.00	280 ✓
10	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS. CUT OUT AND REWELD BOTH FRONT FENDER TOP SUPPORTS. TO REPAIR BOTH FRONT DOORS. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 9,100.00	5500. ✓ Hinge x 2 = 200 5 x 550 = 2750 2 x Fender Top Support = 550 3500 ✓
11	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, BOTH FRONT FENDER TOP SUPPORTS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT.	\$ 8,200.00	
12	TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK.	S/N \$ 384.00	✓ ✓

TOTAL LABOUR CHARGES

: \$ 25,064.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Distorted</i>	1	\$ 1,987.00	✓ 1589.60
2 FRONT BUMPER FIXING PARTS <i>Not nec</i>	1	\$ 187.00	✗ ?
3 FRONT BUMPER GUIDE SECTIONB - LH/RH <i>Damaged</i>	1	\$ Damaged 78.00	60.96 ✓
4 FRONT BUMPER GRILLE - CENTRE <i>Cracked</i>	1	\$ cracked 160.00	✗ 128 ✓
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 536.00	✗
6 FRONT BUMPER CLOSING ELEMENT - LH/RH <i>Cracked</i>	2	\$ cracked 594.00	✗ 474.40 ✓
7 FRONT BUMPER COVER TRIM - LH/RH <i>Not nec</i>	2	\$ 326.00	✗
8 WHEEL HOUSING LINER ADAPTER - LH/RH	2	\$ 76.00	✗
9 RADIATOR GRILLE <i>Cracked</i>	1	\$ 1,406.00	✓ 1124.80
10 RADIATOR GRILLE CLOSING ELEMENT <i>Cracked</i>	1	\$ 191.00	✓ 152.40
11 FRONT BUMPER AIR GUIDE GRILLE - LH/RH <i>Split</i>	2	\$ 376.00	✓ 300
12 FRONT REINFORCEMENT BEAM <i>Bent</i>	1	\$ 795.00	✓ 636 ✓
13 FRONT BUMPER FOAM FILLER PIECE <i>Cracked</i>	1	\$ 189.00	✓ 151.20 ✓
14 FOAM FILLER PIECE COVER <i>deformed</i>	1	\$ 122.00	✓ 97.20 ✓
15 AIRCON STICKER <i>Free</i>	1	NEC \$ 8.00	✓ 5.68
16 CAUTION SIGN STICKER	1	NEC \$ 14.00	✓ 10.88
17 SIGNAL HORN - LH HIGH TONE <i>Not nec</i>	1	\$ 200.00	✗
18 SIGNAL HORN - RH LOW TONE <i>Not nec</i>	1	\$ 200.00	✗
19 FRONT FENDER - LH/RH <i>Distorted</i>	2	\$ 1,702.00	✓ 1360.80
20 FRONT FENDER ATTACHMENT PARTS <i>Not nec</i>	1	\$ 72.00	✗
SUB TOTAL SPARE PARTS	:	\$ 9,219.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
21 FRONT FENDER CENTRE BRACKET - LH/RH <i>and 2</i>	2	\$ Damaged	78.00	61.44 ✓
22 FRONT FENDER BRACKET - LH/RH <i>?</i> Damaged	2	\$	56.00	43.68 ✓
23 FRONT FENDER BRACE - LH/RH <i>?</i> Bent	2	\$	192.00	152.96 ✓
24 WHEEL HOUSING LINER - LH/RH <i>new</i>	2	\$	338.00	<i>x</i>
25 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$	89.00	<i>x</i>
26 BONNET <i>Distorted</i>		\$	3,134.00	✓ 2507.20
27 BONNET ATTACHMENT PARTS <i>new</i>		\$	165.00	<i>x</i>
28 BONNET LID HINGE - LH/RH <i>Bent</i>	2	\$	124.00	✓ 97.76
29 BONNET GAS FILLED STRUT <i>new</i>		\$	104.00	<i>x</i>
30 BONNET CATCH HOOK new Bent		\$	90.00	<i>x</i> 71.28 ✓
31 BONNET STRIKER - LH/RH <i>Bent</i>	2	\$	220.00	✓ 175.20
32 BONNET EDGE PROTECTION <i>new</i>		\$	28.00	✓ 22
33 TOP FENDER LEDGE COVER - LH/RH <i>new</i>	2	\$	82.00	<i>x</i>
34 BONNET CATCH HOOK <i>Bent</i>		\$	63.00	50.32
35 BONNET LID LOCK <i>2nd</i>	2	\$	427.00	✓ 341.60
36 BONNET BOWDEN CABLE - CENTRE <i>?</i> Damaged		\$	58.00	<i>?</i> 46 ✓
37 BONNET LID LOCK CABLE <i>new</i>		\$	74.00	<i>?</i> X
38 BONNET SOUND ABSORBER <i>crumpled</i>		\$	219.00	✓ 175.20
39 PLENUM CHAMBER COVER <i>new</i>		\$	179.00	<i>x</i>
40 LED HEADLIGHT - LH/RH <i>combined</i>	2	\$	10,910.00	✓ 8728
SUB TOTAL SPARE PARTS	:	\$	16,630.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 LIFT CYLINDER - LH/RH <i>Not new</i>	2	\$	284.00	? X
42 LIFT CYLINDER HOSE <i>new</i>		\$	68.00	X
43 HEADLIGHT WASHER PUMP <i>Not new</i>		\$	155.00	? X
44 WINDSCREEN WASHER PUMP <i>Not new</i>		\$	125.00	? X
45 WASH WATER RESERVOIR <i>Repaired</i>		\$	206.00	? 164.40 ✓
46 FRONT FENDER TOP SUPPORT - LH <i>? Buckled</i>		\$	72.00	✓ X NN
47 FRONT FENDER TOP SUPPORT - RH <i>? Buckled</i>		\$	74.00	✓ X NN
48 A-PILLAR CONNECTING PLATE - LH INNER <i>? Buckled</i>		\$	227.00	✓ 181.60
49 A-PILLAR CONNECTING PLATE - RH INNER <i>? Buckled</i>		\$	329.00	✓ 262.80
50 LOCK CARRIER <i>crushed</i>		\$	727.00	✓ 581.60
51 AIRCON CONDENSER <i>Dented</i>		\$	529.00	? 422.80 ✓
52 REFRIGERANT LINE <i>? Not new</i>		\$	475.00	? X
53 REFRIGERANT LINE <i>? Not new</i>		\$	619.00	? X
54 REFRIGERANT LINE <i>? Not new</i>		\$	518.00	? X
55 EXTERNAL TEMPERATURE SENSOR BRACKET <i>Dented</i>		\$	19.00	? 14.56 ✓
56 EXTERNAL TEMPERATURE SENSOR <i>Not new</i>		\$	59.00	? X
57 RADIATOR <i>Dented</i>		\$	951.00	? 760.40 ✓
58 ADDITIONAL RADIATOR <i>Dented</i>		\$	859.00	? 686.80 ✓
59 READY MIX COOLANT <i>new</i>		\$	179.00	✓ 143.04
60 RADIATOR BRACKET <i>crushed</i>	2	\$	82.00	? 65.28 ✓
SUB TOTAL SPARE PARTS		:	\$	<u>6,557.00</u>

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
61 RADIATOR BUSH - LOWER ? Nec	2	\$ 19.00 ? 15.04	✓
62 RADIATOR AIR GUIDE - LH/RH ? cracked	2	\$ 50.00 ? 38.88	✓
63 RADIATOR AIR GUIDE - UPPER CENTRE <i>cracked</i>		\$ 12.00 ✓ 9.44	
64 AIR INTAKE AIR DUCT COVER <i>cracked</i>		\$ 29.00 ✓ 22.72	
65 AIR INTAKE AIR GUIDE <i>cracked</i>		\$ 56.00 ✓ 44.48	
66 AIR INTAKE AIR GUIDE <i>cracked</i>		\$ 66.00 ✓ 52.32	
67 INTER COOLER GASKET <i>Not nec</i>		\$ 14.00 ? X	
68 AIR INTAKE AIR GUIDE <i>cracked</i>		\$ 20.00 ✓ 15.36	
69 AIR INTAKE WATER DRAINAGE HOSE <i>Not nec</i>		\$ 33.00 ? X	
70 AIR INTAKE AIR FILTER <i>Not nec</i>		\$ 272.00 +	
71 AIR INTAKE MANIFOLD - OUTER <i>Not nec</i>		\$ 139.00 +	
72 AIR INTAKE MANIFOLD - INNER <i>Not nec</i>		\$ 666.00 +	
73 AIR INTAKE MANIFOLD - INNER SEAL <i>Not nec</i>		\$ 14.00 + X	
74 CHARGE AIR COOLER		\$ 752.00 ? X	
75 CHARGE AIR COOLER SEAL <i>Not nec</i>		\$ 14.00 S X	
76 CHARGE AIR COOLER SEAL <i>Not nec</i>		\$ 14.00 ? X	
77 FRONT WINDSCREEN <i>cracked</i>		\$ 1,072.00 ✓ 857.60	
78 RAIN SENSOR GEL FOIL <i>Not nec</i>		\$ 137.00 ✓ 109.20	
79 INTERIOR MIRROR SPRING CLIP <i>Not nec</i>		\$ 21.00 ? X	
80 PRIMER <i>Not nec</i>		\$ 20.00 ✓ 15.76	
SUB TOTAL SPARE PARTS :		\$ 3,420.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
81	STEERING WHEEL AIRBAG	1	\$ 3,421.00 ✓	2736.80
82	AIRBAG UNIT	1	\$ 4,414.00 ✓	3531.20
83	HEAD AIRBAG UNIT - LH/RH	2	\$ 3,726.00 ✓	2980.80
84	KNEE AIRBAG UNIT	1	\$ 1,863.00 ✓	1490.40
85	AIRBAG CONTROL UNIT	1	\$ 1,647.00 ✓	1317.60
86	AIRBAG CRASH SENSOR	3	\$ 1,167.00 ✓	933.60
87	STEERING WHEEL <i>new int.</i>	1	\$ 2,374.00 ✗	1899.20 ✓
88	DASHBOARD <i>After</i>	1	\$ 4,259.00 ✓	3407.20
89	AIR VENT <i>new</i>	1	\$ 151.00 +	
90	LOUDSPEAKER COVER <i>new</i>	1	\$ 94.00 +	
91	SEAT BELT - LH/RH <i>Activated</i>	1	\$ 2,206.00 ✓	1764.80
92	SEAT BELT HEIGHT ADJUSTER <i>new</i>	2	\$ 383.00 ?	306.40 ✓
93	MOULDED HEADLINER <i>cracked</i>	1	\$ 1,771.00 ✓	1416.80
94	FRONT FOLDING GRAB HANDLE - LH/RH <i>new</i>	2	\$ 283.00 ?	226.40 ✓
95	REAR FOLDING GRAB HANDLE - LH/RH <i>new</i>	2	\$ 284.00 ?	226.40 ✓
96	A-PILLAR TRIM - LH/RH <i>int</i>	2	\$ 322.00 ?	256.80 ✓
97	B-PILLAR TRIM - LH/RH <i>new</i>	2	\$ 434.00 +	
98	C-PILLAR TRIM - LH/RH <i>new</i>	2	\$ 302.00 +	
99	D-PILLAR TRIM - LH/RH <i>new int.</i>	2	\$ 232.00 +	184.80 ✓
100	WATER DEFLECTOR STRIP - LH/RH <i>new</i>	2	\$ 186.00 ✗	
SUB TOTAL SPARE PARTS			\$	29,519.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N	PARTS DESCRIPTION	QTY		DAMAGED PARTS & PRICES S/NETT	REMARKS
101	TRIM STRIP STRIP - LH/RH	2	\$	514.00	X
102	WINDOW SLOT SEAL - LH/RH FRONT <i>new</i>	2	\$	618.00	+
103	FRONT WINDSCREEN SEALANT <i>new</i>	S/N	\$	200.00	✓ ✓
104	METAL FILLER POWDER <i>new</i>	S/N	\$	280.00	✓ ✓
105	STONE CHIP <i>new</i>	S/N	\$	180.00	✓ ✓
106	CAVITY WAX <i>new</i>	S/N	\$	140.00	✓ ✓
107	ACRYLIC SEALANT <i>new</i>	S/N	\$	180.00	✓ ✓
108	FRONT NO PLATE <i>dented</i>	S/N	\$	60.00	✓ ✓
109	SUNDRIES <i>new</i>		\$	500.00	✓ 144.96 ✓
TOTAL SPARE PARTS		:	\$	68,017.00	
TOTAL LABOUR CHARGES		:	\$	25,064.00	
GRAND TOTAL		:	\$	93,081.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian
19/01/21

Not Authorized, ~~23 Days~~ 23 Days.
H.S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT