

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Xiao Chen

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0059/2021/NS

27-Jan-21

CHANG

1 of 1

SGV 1006 D

AUDI A3 SEDAN 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	RADIATOR FAN WITH FAN RING <i>checked</i>	\$ 1,265.00	<i>✓</i> 1012
GRAND TOTAL		\$ 1,265.00	

For Premium Automobiles Pte Ltd

Adrian Ling
28/01/21
H.S.



Authorised Signature

Car-in wip: 12010.

Kiam/Keang

Adrian

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER Distal	1	\$ 1,987.00	✓
2 FRONT BUMPER FIXING PARTS	1	\$ 187.00	✓
3 FRONT BUMPER GUIDE SECTIONB LH/RH 2	2	\$ 78.00	✓
4 FRONT BUMPER GRILLE - CENTRE	1	\$ 160.00	✓
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 536.00	✓
6 FRONT BUMPER CLOSING ELEMENT - LH/RH	2	\$ 594.00	✓
7 FRONT BUMPER COVER TRIM LH/RH	2	\$ 326.00	✓
8 WHEEL HOUSING LINER ADAPTER - LH/RH	2	\$ 76.00	✓
9 RADIATOR GRILLE	1	\$ 1,406.00	✓
10 RADIATOR GRILLE CLOSING ELEMENT	1	\$ 191.00	✓
11 FRONT BUMPER AIR GUIDE GRILLE - LH/RH	2	\$ 376.00	✓
12 FRONT REINFORCEMENT BEAM	1	\$ 795.00	✓
13 FRONT BUMPER FOAM FILLER PIECE	1	\$ 189.00	✓
14 FOAM FILLER PIECE COVER	1	\$ 122.00	✓
15 AIRCON STICKER	NEC	\$ 8.00	✓
16 CAUTION SIGN STICKER	NEC	\$ 14.00	✓
17 SIGNAL HORN - LH HIGH TONE	1	\$ 200.00	?
18 SIGNAL HORN - RH LOW TONE	1	\$ 200.00	?
19 FRONT FENDER - LH/RH	2	\$ 1,702.00	✓
20 FRONT FENDER ATTACHMENT PARTS	1	\$ 72.00	✓
SUB TOTAL SPARE PARTS	:	\$ 9,219.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5GV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT FENDER CENTRE BRACKET - LH/RH <i>Dist</i>	2	\$	78.00 ✓
22 FRONT FENDER BRACKET - LH/RH <i>Dist</i>	2	\$	56.00 ✓
23 FRONT FENDER BRACE - LH/RH <i>Bent</i>	2	\$	192.00 ✓
24 WHEEL HOUSING LINER - LH/RH <i>new</i>	2	\$	338.00 +
25 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$	89.00 +
26 BONNET <i>Disturbed</i>		\$	3,134.00 ✓
27 BONNET ATTACHMENT PARTS <i>new</i>		\$	165.00 +
28 BONNET LID HINGE - LH/RH <i>Bent</i>	2	\$	124.00 ✓
29 BONNET GAS FILLED STRUT <i>new</i>		\$	104.00 +
30 BONNET CATCH HOOK <i>new Bent</i>		\$	90.00 ✓
31 BONNET STRIKER - LH/RH <i>Bent</i>	2	\$	220.00 ✓
32 BONNET EDGE PROTECTION <i>Disturbed</i>		\$	28.00 ✓
33 TOP FENDER LEDGE COVER - LH/RH <i>new</i>	2	\$	82.00 ✓
34 BONNET CATCH HOOK <i>Bent</i>		\$	63.00 ✓
35 BONNET LID LOCK <i>Dist</i>	2	\$	427.00 ✓
36 BONNET BOWDEN CABLE - CENTRE <i>Dist</i>		\$	58.00 ✓
37 BONNET LID LOCK CABLE <i>?</i>		\$	74.00 ✓
38 BONNET SOUND ABSORBER <i>crushed</i>		\$	219.00 ✓
39 PLENUM CHAMBER COVER <i>new</i>		\$	179.00 +
40 LED HEADLIGHT - LH/RH <i>crushed</i>	2	\$	10,910.00 ✓
SUB TOTAL SPARE PARTS	:	\$	16,630.00

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
61 RADIATOR BUSH - LOWER <i>new</i>	2	\$ 19.00	✓
62 RADIATOR AIR GUIDE (LH/RH) <i>could</i>	2	\$ 50.00	✓
63 RADIATOR AIR GUIDE - UPPER CENTRE <i>could</i>		\$ 12.00	✓
64 AIR INTAKE AIR DUCT COVER <i>could</i>		\$ 29.00	✓
65 AIR INTAKE AIR GUIDE <i>could</i>		\$ 56.00	✓
66 AIR INTAKE AIR GUIDE <i>could</i>		\$ 66.00	✓
67 INTER COOLER GASKET ?		\$ 14.00	?
68 AIR INTAKE AIR GUIDE <i>could</i>		\$ 20.00	✓
69 AIR INTAKE WATER DRAINAGE HOSE ?		\$ 33.00	?
70 AIR INTAKE AIR FILTER <i>new</i>		\$ 272.00	+
71 AIR INTAKE MANIFOLD - OUTER <i>new</i>		\$ 139.00	+
72 AIR INTAKE MANIFOLD - INNER <i>new</i>		\$ 666.00	+
73 AIR INTAKE MANIFOLD - INNER SEAL <i>new</i>		\$ 14.00	+
74 CHARGE AIR COOLER ?		\$ 752.00	?
75 CHARGE AIR COOLER SEAL ?		\$ 14.00	?
76 CHARGE AIR COOLER SEAL ?		\$ 14.00	?
77 FRONT WINDSCREEN <i>could</i>		\$ 1,072.00	✓
78 RAIN SENSOR GEL FOIL <i>new</i>		\$ 137.00	✓
79 INTERIOR MIRROR SPRING CLIP ?		\$ 21.00	?
80 PRIMER <i>new</i>		\$ 20.00	✓
SUB TOTAL SPARE PARTS	:	\$ 3,420.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
101	TRIM STRIP STRIP - LH/RH	2	S	514.00	
102	WINDOW SLOT SEAL - LH/RH FRONT <i>new</i>	2	S	618.00	<i>+</i>
103	FRONT WINDSCREEN SEALANT <i>new</i>	S/N	S	200.00	<i>✓</i>
104	METAL FILLER POWDER <i>new</i>	S/N	S	280.00	<i>✓</i>
105	STONE CHIP <i>new</i>	S/N	S	180.00	<i>✓</i>
106	CAVITY WAX <i>new</i>	S/N	S	140.00	<i>✓</i>
107	ACRYLIC SEALANT <i>new</i>	S/N	S	180.00	<i>✓</i>
108	FRONT NO PLATE <i>Dented</i>	S/N	S	60.00	<i>✓</i>
109	SUNDRIES		S	500.00	<i>✓</i>
TOTAL SPARE PARTS		:	\$	68,017.00	
TOTAL LABOUR CHARGES		:	\$	25,064.00	
GRAND TOTAL		:	\$	93,081.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Add
N 016 185 7 X 11

PREMIUM AUTOMOBILES



55 UET ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
81	STEERING WHEEL AIRBAG	1	\$ 3,421.00	✓
82	AIRBAG UNIT	1	\$ 4,414.00	✓
83	HEAD AIRBAG UNIT - LH/RH	2	\$ 3,726.00	✓
84	KNEE AIRBAG UNIT	1	\$ 1,863.00	✓
85	AIRBAG CONTROL UNIT	1	\$ 1,647.00	✓
86	AIRBAG CRASH SENSOR	3	\$ 1,167.00	✓
87	STEERING WHEEL	1	\$ 2,374.00	✓
88	DASHBOARD	1	\$ 4,259.00	✓
89	AIR VENT	1	\$ 151.00	+
90	LOUDSPEAKER COVER	1	\$ 94.00	+
91	SEAT BELT - LH/RH	1	\$ 2,206.00	✓
92	SEAT BELT HEIGHT ADJUSTER	2	\$ 383.00	?
93	MOULDED HEADLINER	1	\$ 1,771.00	✓
94	FRONT FOLDING GRAB HANDLE - LH/RH	2	\$ 283.00	?
95	REAR FOLDING GRAB HANDLE - LH/RH	2	\$ 284.00	?
96	A-PILLAR TRIM - LH/RH	2	\$ 322.00	?
97	B-PILLAR TRIM - LH/RH	2	\$ 434.00	+
98	C-PILLAR TRIM - LH/RH	2	\$ 302.00	+
99	D-PILLAR TRIM - LH/RH	2	\$ 232.00	+
100	WATER DEFLECTOR STRIP - LH/RH	2	\$ 186.00	x
SUB TOTAL SPARE PARTS		:	\$ 29,519.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGV 1006 D

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
		S/NETT		
41 LIFT CYLINDER - LH/RH ?	2	\$	284.00	?
42 LIFT CYLINDER HOSE <i>new</i>		\$	68.00	x
43 HEADLIGHT WASHER PUMP ?		\$	155.00	?
44 WINDSCREEN WASHER PUMP ?		\$	125.00	?
45 WASH WATER RESERVOIR <i>reld</i>		\$	206.00	✓
46 FRONT FENDER TOP SUPPORT - LH ?		\$	72.00	✓
47 FRONT FENDER TOP SUPPORT - RH <i>Buckled</i>		\$	74.00	✓
48 A-PILLAR CONNECTING PLATE - LH INNER <i>Buckled</i>		\$	227.00	✓
49 A-PILLAR CONNECTING PLATE - RH INNER <i>Buckled</i>		\$	329.00	✓
50 LOCK CARRIER <i>crushed</i>		\$	727.00	✓
51 AIRCON CONDENSER <i>Deated</i>		\$	529.00	✓
52 REFRIGERANT LINE ?		\$	475.00	?
53 REFRIGERANT LINE ?		\$	619.00	?
54 REFRIGERANT LINE ?		\$	518.00	?
55 EXTERNAL TEMPERATURE SENSOR BRACKET ?		\$	19.00	?
56 EXTERNAL TEMPERATURE SENSOR ?		\$	59.00	?
57 RADIATOR <i>Deated</i>		\$	951.00	✓
58 ADDITIONAL RADIATOR <i>Deated</i>		\$	859.00	✓
59 READY MIX COOLANT <i>new</i>		\$	179.00	✓
60 RADIATOR BRACKET <i>crushed</i>	2	\$	82.00	✓
SUB TOTAL SPARE PARTS	:	\$	6,557.00	