

KENT SENG CAR SERVICES

Blk 1017 Yishun Industrial Park A #01-240
Singapore 768759 HP 91004390/HP 91254449 Fax 64841482
Email:kentsengcarservices@gmail.com

M/s China Taiping Insurance (S) Pte Ltd DATE 18.01.2021
3 Anson Road #16-00 Spring leaf Tower CAR NO SKM 4382 Y
Singapore 079909 MAKE Lexus SC430

ESTIMATE COST OF REPAIR FOR THE ABOVE MENTIONED VEHICLE.
YOUR INSURED : SGW 9599 B

Pc	Pcs	JTHFN48Y900068731	UNIT PRICE	AMOUNT
1	DC	Front bumper / CRU		\$1,061.80 980
1	DC	Front right hand side retainer - BN		\$72.80
1	PC	Front bumper fog lamp (right) X SVC		\$286.00 X
1	PC	Front bumper fog lamp cover garnish (right) X SVC		\$86.00 X
1	DC	Front right side fender / PB		\$1,115.00 1,063.20
1	DC	Front right side fender cowl X SVC		\$283.00 X
1	PC	Front right side head lamp / SCR.		\$3,193.00 2,498.05
1	DC	Front right side tyre rim X SVC		\$1,896.00 X
				<u>-10%</u> 4,614.05
		To spray anti-rust coating on new & affected panels.		\$100.00 40
		To check electrical wiring system.		\$80.00 70
		Straightening, repairing and realigning onto front top panel, front bonnet, cutting front right side fender, dismantle & replace the above mentioned parts.		\$900.00 400
		Labour for respray right side front fender, front bonnet, front bumper and front top panel.		\$900.00 400
Page 1 of 1			Total	\$9,973.60

Susan Lim

KENT SENG CAR SERVICES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair dy 7 dys

L/S

After purm phw

Sm Pin (Ldr)

20/01/2021

TP insurance

4,614.05

-10%

4,152.65

870

5,022.65

-20%

4,018.12

L/S

\$4,000

3 dys