

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64 , Cecil Street # 04 - 05
 IOB Building
 Singapore 049711
 Tel : 6347 - 6100
 Fax : 6224 - 4174

Quotation

DATE : 19.01.2021
 VEH NO : GZ5532D
 MODEL : Toyota Hiace
 D O A : 19.01.2021
 YR REF : GBH819P

Cecilia.

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR GZ5532D (TOYOTA HIACE)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Deformed</i>	1	548.40 ✓
2	Front Bumper Side Holder - LH & RH <i>new</i>	2	110.00 ✓
3	Front Bumper Side Grille - LH & RH <i>new</i>	2	144.00 x ✓
4	Front Bumper Reinforcement <i>Best</i>	1	341.70 ✓
5	Front Bumper Reinforcement Stay - LH & RH <i>Best</i>	2	379.00 ✓
6	Front Bumper Towing Cover <i>Dehd</i>	1	20.10 ✓
7	Front Bumper Bracket - LH & RH <i>Best</i>	2	286.20 ✓
8	Front Bumper Top Beam <i>Best</i>	1	281.40 ✓
9	Front Grille <i>crushed</i>	1	442.80 ✓
10	Head Lamp - LH & RH <i>crushed</i>	2	1,179.60 ✓
11	Bonnet <i>Dented</i>	1	655.90 ✓
12	Bonnet Lock <i>Damaged</i>	1	75.10 ✓
13	Bonnet Hinges - LH & RH <i>new</i>	2	138.20 x ✓
14	Bonnet Logo <i>new</i>	1	61.80 ✓
15	Front Support Panel <i>Buckled.</i>	1	374.10 ✓
16	Front support Panel Cover <i>Deformed</i>	1	136.80 ✓
17	Wiper Washer Tank <i>crushed</i>	1	81.20 ✓
18	Front Brace Panel <i>new</i>	1	86.20 x ✓
19	Air Con Condenser <i>Dented.</i>	1	1,216.00 ✓
20	Radiator <i>Leak</i>	1	1,745.00 ✓
21	Radiator Spare Tank <i>crushed</i>	1	203.90 ✓
22	Horn <i>Damaged.</i>	2	208.60 ✓
23	Rear Bumper <i>Distorted.</i>	1	695.90 ✓
24	Rear Bumper Side Holder - LH & RH <i>new</i>	2	120.40 ✓
25	Rear Bumper Lower Bracket <i>Best</i>	4	82.00 ✓
26	Rear End Panel Outer <i>Dislud</i>	1	388.30 ✓
27	Rear End Panel Inner <i>Dislud</i>	1	859.50 ✓
28	Rear End Panel Top Metal Strip <i>Best</i>	1	180.70 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR GZ5532D (TOYOTA HIACE)

29	Tail Lamp - LH & RH	LH Smashed, RH cracked	2	791.60 ✓
30	Tail Lamp Panel - LH & RH	LH Distorted	2	683.20 341.60 ✓
31	Tail Lamp Panel Inner - LH & RH	LH Distorted	2	923.80 461.90 ✓
32	Tail Lamp Lower Apron - LH & RH	LH Distorted	2	177.20 88.60 ✓
33	Rear Number Plate Lamp - LH & RH	Not new	2	118.00 X ✓
34	Tailgate	Distorted	1	1,890.50 ✓
35	Tailgate Lock	Jammed	1	235.00 ✓
36	Tailgate Lock Striker	Bent	1	68.60 ✓
37	Tailgate Weatherstripe	At	1	395.90 ✓
38	Tailgate Outer Garnish	Behind	1	155.90 ✓
39	Tailgate Outer Garnish Opener	Damaged	1	65.90 ✓
40	Tailgate Damper - LH & RH	Bent.	2	590.00 ✓
41	Tailgate Inner Trim Board	torn	1	168.90 ✓
42	Tailgate Glass	Shattered	1	1,227.90 ✓
43	Tailgate Glass Moulding	new	1	110.40 ✓
44	Tailgate Mirror	crackd.	1	399.10 ✓
45	Tailgate Wiper Motor	} new ✓ 21338.80	1	369.20 X ✓
46	Tailgate Wiper Arm		1	68.90 X ✓
47	Tailgate Wiper Blade		1	45.10 X ✓
48	Tailgate Brake Lamp	new ✓	1	110.40 X ✓
49	Tailgate Nozzle	new ✓	1	58.90 X ✓
50	Toyota Logo	new	1	55.90 ✓
51	Rear Body Panel - LH	Buckled	1	1,308.10 ✓
52	Rear Body Panel Inner Trim - LH	new ✓	1	288.90 X ✓
53	Rear Body Panel Air Vent - LH	crackd	1	45.90 ✓
54	Sliding Door Rail - LH	new ✓	1	387.20 X ✓
55	Sliding Door Rail End Cover - LH	Damaged	1	51.20 ✓
56	Spare Tyre Carrier	Bent	1	284.20 ✓
57	Spare Tyre Lock Screw	Bent	1	44.90 ✓
58	Rear Exhaust Pipe	} new ✓	1	716.00 X ✓
59	Rear Exhaust Mounting		1	35.40 X ✓
60	Floor Panel	Distorted	1	1,882.50 ✓

25%
Less 10%

24,797.40
(2,479.74)
\$ 22,317.66

S/NET ITEMS

1	Front Number Plate	} cracked	1	30.00 ✓
2	Front Number Plate Holder		1	30.00 ✓
3	Front Bumper Clips	} new	1 set	30.00 ✓
4	Front Grille Clips		1 set	30.00 ✓
5	Front Support Panel Cover Clips	new	1 set	20.00 ✓
6	Radiator Coolant	new	1	50.00 ✓
7	Rear Bumper Clips	new	1 set	30.00 ✓
8	Reverse Sensor	Damaged	1	280.00 new ✓

RE : ESTIMATE FOR ACCIDENT REPAIR GZ5532D (TOYOTA HIACE)

9	Rear End Panel Sealant <i>New</i>	1	60.00	✓
10	Rear Number Plate <i>crackd</i>	1	30.00	✓
11	Rear Number Plate Holder <i>crackd</i>	1	30.00	✓
12	Tailgate Inner Trim Board Clips <i>New</i>	1 set	30.00	✓
13	Tailgate Glass Sealant <i>New</i>	1	60.00	✓
14	70km/h Sticker <i>New</i>	1	10.00	✓
15	8 pax Sticker <i>New</i>	1	10.00	✓
16	Tailgate Advertisement Sticker <i>New</i>	1	280.00 200	
17	Rear Body Panel Inner Trim Clips - LH <i>new</i>	1	30.00	+
18	Floor Panel Carpet <i>New</i>	1	600.00	+
19	Floor Panel Carpet Clips <i>New</i>	1	50.00	+
			1,690.00	

Total Parts

\$ 24,007.66

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts <i>(Front)</i>	\$	1,000.00 800
2	To putty & spray up paint works (front)	\$	1,000.00 800
3	To check wiring <i>(front)</i>	\$	50.00 30
4	To remove condenser & top up aircon gas	\$	120.00 60
5	To remove radiator & to up coolant	\$	120.00 60
6	To spray tuff coat (front)	\$	150.00 50
7	To knocking & pull out rear portion & renew above parts <i>(Rear)</i>	\$	2,000.00 1800
8	To putty & spray up paint works (rear)	\$	1,600.00 1400
9	To check wiring (rear)	\$	50.00 30
10	To spray tuff coat (rear)	\$	280.00 200
11	To remove upholstery	\$	280.00 80
12	To remove reverse sensor	\$	100.00 50
13	To transfer tailgate fittings	\$	150.00 80
14	To replace tailgate glass	\$	180.00 120
15	To remove exhaust pipe	\$	150.00 X

RE : ESTIMATE FOR ACCIDENT REPAIR GZ5532D (TOYOTA HIACE)

5620.

16 Towing fees

\$ 60.00 ✓

Total Labour \$ 7,290.00

Grand Total \$ 31,297.66

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 22474170.
L/s: 166K (Nett Value)
18 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: