

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page # :- 1

Veh # :- SJL2872E

Veh Model :- HONDA JAZZ 1.3L AT

Estimate# :- CK421458

Claim # :-

ACC. Date :- 17/01/21

Terms :- C.O.D Days

Remarks :-



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008
Bukit Merah Lane 3
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033C
GST Reg. M2-0088864-2

Estimate

19/01/2021

LONPAC INSURANCE
300 BEACH ROAD
#17-04/07 The Colonnade
SINGAPORE 199555.

Attention :- XA025

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1.	HEADLAMP ASSY RH <i>cm</i>	1	PC	376.90	376.90 ✓
2.	HEADLAMP LOWER BRACKET RH <i>? XSVL</i>	1	PC	27.50	27.50 ✓
3.	FRONT BUMPER <i>de</i>	1	PC	503.20	503.20 ✓
4.	FRONT BUMPER RETAINER RH <i>? XSVL</i>	1	PC	18.10	18.10 ✓
5.	FRONT BUMPER CLIPS <i>lee</i>	10	PC	3.00	30.00 ✓
6.	FRONT FENDER RH <i>bt</i>	1	PC	430.40	430.40 ✓
7.	FRONT FENDER COWLING RH <i>XSVL</i>	1	PC	67.70	67.70 ✓
8.	FRONT FENDER COWLING CLIPS <i>Xm</i>	10	PC	3.00	30.00 ✓
9.	FRONT KNUCKLE ARM RH <i>? bt</i>	1	PC	222.50	222.50 ✓
10.	FRONT KNUCKLE BEARING RH <i>? bt</i>	1	PC	122.70	122.70 ✓
11.	FRONT LOWER ARM RH <i>? bt</i>	1	PC	198.90	198.90 ✓
12.	FRONT DRIVE SHAFT RH - CHECK <i>NN</i>	1	PC		
13.	STEERING RACK & PINION - CHECK <i>NN</i>	1	PC		
14.	ENGINE MOUNTING RH - CHECK <i>IS 280 NN</i>	1	PC		
15.	ENGINE MOUNTING LH - CHECK <i>NN</i>	1	PC		
16.	FRONT CROSS MEMBER - CHECK <i>NN</i>	1	PC		

LIST TOTAL S\$

2,027.90

20% DISCOUNT S\$

-405.58

1,622.32

SPECIAL NET ITEMS :

1.	FRONT SPORT RIM RH <i>su</i>	1	PC	380.00	380.00 <i>300</i>
----	------------------------------	---	----	--------	-------------------

SPECIAL NET TOTAL S\$

380.00

LABOUR :

TO KNOCK & STRAIGHTEN HEADLAMP PANEL RH,
REMOVE & REPLACE ACCIDENT DAMAGED PARTS.
REALIGN ALL CONNECTION

400.00 ✓

SPRAY PAINT FRONT BUMPER, FRONT FENDER RH,
HEADLAMP PANEL

400.00 ✓

REMOVE & REPLACE UNDER CARRIAGE SUSPENSION

250.00 ✓

COMPUTER WHEEL ALIGNMENT *(Report)*

60.00 ✓

RUST PROOF AFFECTED AREAS

30.00 ✓

LABOUR TOTAL S\$

1,140.00

1507.68
300.00
990.00
2797.68
209
2238.14

40-2,200
5 days