

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21000926/QBA3Q2
Date: 31/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900057869
Claimant Vehicle No :	SLS2181E	Insured Vehicle No :	SMU6688L
Date of Loss:	18/01/2021	Nature of Claim:	TP
		Claim No:	9532300891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2181E		
Make & Model:	KIA FORTE K3, 1.6 (A)	Engine No:	G4FGHH679007
Reg. Date:	14/09/2017 (Man. Year: 2017)	Chassis No:	KNAFJ411MJ5739468
Colour:	White	Odometer:	215944 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,952.72	860.40	1,092.32	55.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	450.00	900.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,302.72	1,310.40	1,992.32	60.32
Approved Total (Overridden) (S\$)		1,050.00		

(S\$)	3,302.72	1,050.00	2,252.72	68.21
+ GST 7.00/7.00% (S\$)	231.19	73.50	157.69	68.21
Nett Amount (S\$)	3,533.91	1,123.50	2,410.41	68.21
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,365.50		
Global Sum Settlement (S\$)		1,240.00		

INSPECTION

Date of Assignment: 19/01/2021

Date Inspected: 19/01/2021

Estimated Period of Repair: 2.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
 60 Jalan Lam Huat, #04-35/36 Carros Centre
 Singapore 737569

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,200.50 FL	*688.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Crumpled	880.30 FL	*350.00 FL
3	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,160.801,068.00
					- List Item Discount on L Items 10.00/20.00% (\$\$)	208.08207.60
					Total Parts (\$\$)	1,952.72860.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING REAR BUMPER ,REAR END PANEL OUT TO FACILITATE REPAIRS	New	750.00	250.00
2	TO RESPRAY REAR BUMPER AND REAR END PANEL	New	600.00	200.00
Gross Labour Cost (\$\$)			1,350.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >