888C
ES. REC. BY: PUSUL 1 MEF: CC3 ALG 21000928 RHd3 1 888C ASSIGNMENT ASSIGNMENT
ASSIGNMENT SLO 1233A Yr Regn: 2019 1 MAY
Veh No: SLD 1235H Yr Regnt
From: Date: Veh No: Veh No: Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
O NI CEDAN DUE TEN EN TROIS C.C. [16]
AC: Moderate Mo:
7 PO FMILIAN
1 0 00 01 011 000
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
(ACI) Door Burns
400 361 9905 361 \$800 Gell, collection of the large and 11 eaked Burnit or
Excess:
Sum Insured: Brake: (norder / Jammed / Leaked / Burit of
(Client's Record) Modi: Nil / S/Rim 1 STD A/Rim or
Make of Veh: Tyre Size: F: 245 46R18
(Policy Condition) N/S O/S BS / DUN / EXNOVATOR FS / LIZA / NIIC / OHTSU / PIR / SUM! /
Pomark: The yeh had commenced its
repair at the time of inspection. Rear Front Front Rear
Ribal, Ri
Consistent?; Yes of No
Consistent?: Yes or NO
Cat Papairs' days Res.: Yes of No
Est. Repairs: Survey held at Survey held at Des. of Damages: Frt Rear OIS NIS UIC Rooftop of
The U.C. I Chassis frame I Body Structure anested dot to
Date: Person Contacted: Mie 0/0 / Citation
Date / Time Action / Instruction
Repair Init-644
70.5 hr. Dart & 17511.20, 6 days
1 Part by Part \$15511.20, 55%)
· CACA.
Days Of Repair:
Date/Time, File Pass to / Survey Fee:
Transportation:
Date/Time, File Return to?
Add Fee: Site Insp (9) Photos
i illieran (a
1. 18011, 11V3 . 1
Learning Season (LEA (Co.)
TOTAL
And the second of the second o

SP0R211G0003 / PREMIUM AUTOMOBILES PTE LTD [408699] ENTRY DATE & TIME: 16/01/2021 16:14 (SGT) SUBMITTED BY: WONG KHONG SENG VERSION: 1 (16/01/2021 16:14 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

1. Please report contecting the declars of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Authorised Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding or material facts may allow insurance companies to reputile policy liability.
 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 Any false reporting may be referred to the Police for investigation.
 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 16/01/2021 16:14 (SGT) Date of Accident 15/01/2021 23:35 (SGT) **Exact Location of Accident** Clarke Quay, Singapore Additional Location Information CLARKE QUAY MULTI STOREY CAR PARK Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLD1233A

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner LEE SHU HUA NRIC No SXXXX888C **Email Address** BBAHBENG@HOTMAIL.COM Mobile Phone No (Phone) +65-98570071 Alternative Phone No (Office) +65-98570071

VEHICLE PARTICULARS

Manufacturer Audi Model A4 Variant Exact purpose for which vehicle was being used at time of

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

INSURANCE COMPANY

Name of Insurance Company Type of Coverage Fleet Policy Policy Number

Cover Note Number

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

LEE SHU HUA SXXXX888C 22/12/1980 Indoor

Comprehensive

1900104268

Private use

Private car

Yes

AIG

No

Date Of Driving Pass 02/05/2002 Driving experience 18 YEARS AND 8 MONTHS Gender Male Mobile Number (Phone) +65-98570071 Alt. Phone Number (Office) +65-98570071 Email Address BBAHBENG@HOTMAIL.COM Address 58 EDGE PLAIN Address complement #09-15 Postcode 828823 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collided into Parked Vehicle Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT I HIT ONTO A PARKED VEHICLE WHEN I WAS DOING A RIGHT TURN TO EXIT. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	_
Vehicle Manufacturer	_
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	Red
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement Postcode	-
Insurance Company Name	-
msurance Company Name	-

Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Funderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: 16/0//2

Driver's Signature (If driver is not the policyholder) Date & Time: Name: (None KHONG SEAL, CLEONGE NRIC/FIN No.: 6, 29871434

SKETCH PLAN		
	B	A-s!
	1 1 1	A-5! B-Un
		B 01
	4 4 4	
	F 7 (P - 7	
	1 1 1	
DESCRIBE CIRCUMSTAN	ICES OF THE ACCIDENT	
7 4	0.201	
	ONTO A PARKED VEHICLE WHE	EN I WAS DOING A
RIGHT	TURN TO EXIT.	
DECLARATION		G PTG \
	particulars are true in every respect.	A PIC ON
	particulars are true in every respect.	PTC O
	particulars are true in every respect.	PTG ST
	particulars are true in every respect. Driver's Signature	Reporting Centre Personnel's Signature Name: World KLALA SENA NRIC/FIN No.: G 2987143X



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

ACCIDENT REPAIRS

6841 1183

WORKSHOP **CONTACT NO** UBI ROAD 1 6366 2323

FAX NO REFERENCE

PA/OD/0058/2021/NS

DATE

18-Jan-21

WIP

12042

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

:

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME

MR LEE SHU HUA

ADDRESS

BLK 58 EDGEDALE PLAINS

AUDI A4 SEDAN 2.0 TFSI 8W

#09-15

SINGAPORE 828823

TELEPHONE

HP +65 98570071

TYPE OF CLAIM

OWN DAMAGE CLAIM

POLICY NO

1900104268

VEHICLE NO

MODEL CODE

SLD 1233 A

31/5/2019

MODEL YEAR ENGINE NO

CVK 078751

CHASSIS NO

WAUZZZF42KA052364

MILEAGE

23990KM

DATE IN

16-Jan-21

ESTIMATED BY

JOHNNY BOO / ALLAN WU

ACCIDENT DATE

15-Jan-21

PLACE OF ACCIDENT

:

:

CLARKE QUAY MULTI-STOREY CARPARK





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00	
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N	\$ 1,200.00	7//
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N	\$ 350.00	250/
4	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	S/N	\$ 280.00	
5	3TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 5,280.00	1100 /. 2350/
	SUB TOTAL LABOUR CHARGES	:]	\$ 7,560.00	





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

S/N	NATURE OF JOBS		ESTIMATED CHARGES		JRVEYOR'S MMENDATIONS
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS UPPER A-PILLAR.		\$ 4,400.00	1650	
7	TO RENEW LHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT TEST.	S/N	\$ 280.00	?xt	nn
8	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N	\$ 384.00		324
	TOTAL LABOUR CHARGES	:	\$ 12,624.00	:	





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

S/N PARTS DESCRIPTION			DAMAGED PARTS	S & PRICES REMARKS
1 FRONT BUMPER de/		\$	1,787.00	1429.60
2 FRONT BUMPER FIXING PARTS ? n ? ×		\$	587.00	X
3 FRONT BUMPER SECURING STRIP 4/LH	71	P \$		28.16
4 FRONT BUMPER GRILLE - CENTRE X 52	,	\$	196.00	X
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$		167.60
6 FRONT BUMPER AIR GUIDE - LH ? CM		\$	63.00	50.08
7 RADIATOR GRILLE 7. 48 M		\$	1,332.00	X
8 FRONT BUMPER AIR GUIDE GRILLE - LH M()		\$	135.00	108
9 FRONT BUMPER CARRIER 7 X3VC		\$	845.00	X
10 FRONT BUMPER FOAM FILLER PIECE 7. 4500		\$	124.00	×
11 FRONT BUMPER TOP COVER 🗴 💃		\$	127.00	Y
12 FRONT BUMPER GUIDE SECTION - LH CA		\$	36.00	73.32
13 CAUTION SIGN STICKER 🗶 🖍	NEC	\$	14.00	X
14 AIRCON STICKER X	NEC	\$	8.00	(
15 LOCK CARRIER BRACKET 7 45VC	001/6	\$	137.00	$\langle \rangle$
16 LOCK CARRIER BRACKWET SUPPORT - LH/RH 7	2	\$	58.00	\ \
17 FRONT PARKING AID SENSOR - INNER/OUTER $^{\ell u}$	ZIP	5	484.00	105.70
18 FRONT PARKING AID SEAL RING /W/	4	\$	14.00	1120
19 HORN - LH HIGH TONE 7 KSVC		\$	126.00	X
20 SPRING SHACKLE-LH 7 45 C		\$	29.00	5
SUB TOTAL SPARE PARTS	:	\$	6,383.00	





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS S/NETT	S & PRICES REMARKS
21 FRONT FENDER - LH	\$	767.00	613.20
22 FRONT FENDER ATTACHMENT PARTS	nn s	202.00	×
23 FRONT FENDER CLOSING ELEMENT - LH LL/	\$	72.00	57.52
24 FRONT FENDER BRACKET - LH 54/	NEC \$	35.00	27.92
25 DEFORMATION ELEMENT BRACKET - LH 2 45	\$	49.00	X
26 FRONT FENDER BRACE - LH 7. 5+/	\$	118.00	94.40
27 WHEEL HOUSING LINER - LH &	\$	240.00	191-60
28 WHEEL HOUSING LINER ATTACHMENT PARTS	exn1 s	233.00	X
29 WHEEL SPOILER - LH de/	\$	73.00	57-40
30 WHEEL SPOILER TRIM - LH ? ASN	\$	35.00	X
31 STONE CHIP GUARD - LH 7. + M	\$	51.00	X
32 TOP FENDER LEDGE COVER - UPPER CA	\$	31.00	24.64
33 TOP FENDER LEDGE COVER - LOWER / L	\$	23.00	17.92
34 BONNET X Su	\$	3,246.00	×
35 BONNET ATTACHMENT PARTS 🗡 🔨	\$	412.00	×
36 BONNET IMPACT PROTECTION - CENTRE	7 \$	28.00	X
37 BONNET IMPACT PROTECTION - LH X	\$	28.00	×
38 BONNET IMPACT PROTECTION - RH	\$	28.00	×
39 BONNET STRIKER - LH 🗡 🔨	2 \$	50.00	*
40 BONNET LID LOCK 🗡 🔨	\$	214.00	*
SUB TOTAL SPARE PARTS	: \$	5,935.00	- -





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 1233 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT REMARKS	
41 LED HEADLIGHT - LH bro /	\$	7,693.00 6154.40)
42 MAIN LIGHT ELECTRONICS POWER MODULE 72	1 fruit 5	761.00 🔀	
43 LIGHT CONTROL SYSTEM CONTROL UNIT 7	2 \$	751.00 🔀	
44 HEADLIGHT HOSE - LH 7 KSVC	\$	36.00 ×	
45 LIFT CYLINDER - LH ? KSM	\$	210.00 🔀	
46 LIFT CYLINDER CORRUGATED PIPE 7. XSVC	\$	93.00 🗴	
47 LOCK CARRIER CM	\$	1,016.00 812.80	
48 COOLANT REGULATOR SUPPORT 7 KSVC	\$	38.00 🗙	
49 READY MIX COOLANT 7 Nee	\$	179.00 143.04	
50 RADIATOR AIR GUIDE - OUTER - XSVC	\$	28.00	
51 RADIATOR AIR GUIDE - LH 7 +3 VC	\$	12.00 💢	
52 RADIATOR AIR GUIDE - UPPER ? FSUC	\$	16.00 🗙	
53 RADIATOR AIR GUIDE - LOWER \$ \text{\$\frac{1}{2}\text{\$\frac{1}\text{\$\frac{1}{2}\text{\$\frac{1}{2}\text{\$\frac{1}{2}\text{\$\frac{1}{2}\text{\$\frac{1}{2}\text{\$\frac{1}\text{\$\frac{1}\$	\$	22.00 🗡	
54 AIRCON CONDENSER X SVC	\$	622.00 ×	
55 TEMPERATURE SENSOR BRACKET X 5 VC	\$	19.00 ×	
56 PRESSURE PIPE ? LSVC	\$	427.00 ×	
57 FRONT BUMPER BRACKET - LH 7 45 VC	\$	228.00	
58 WINDOW GUIDE TRIM STRIP 🗶 🗘	\$	257.00 📉	
59 WINDOW SLOT SEAL - LH 😾 🗥 🗥	\$	307.00 >	
60 FRONT NO PLATE ? LSA	S/N \$	60.00 4	
61 SUNDRIES 7 KAN	\$	400.00	
TOTAL SPARE PARTS	: \$	25,493.00	
TOTAL LABOUR CHARGES	: \$	12,624.00	
GRAND TOTAL	: \$	38,117.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE AUTHORISED DATE

EXCESS COST LIABILITY

REMARKS

PARM - HP 94010068 19/01/2021 @ 1110 6 days EXCESS: THA

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF

REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO

MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY, PREMIUM AUTOMOBILES PTE LTD

> LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10HNNY BOO BODY REPAIR MANAGER

ALLAN WU CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE

:

ACCIDENT REPAIRS

WORKSHOP

CONTACT NO

6366 2323

UBI ROAD 1

FAX NO

6841 1183

REFERENCE

PA/OD/0058/2021/NS

DATE

18-Jan-21

WIP

12042

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

:

.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120

Hi Rasul

6 days - ok - ib - 22 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME

MR LEE SHU HUA

ADDRESS

BLK 58 EDGEDALE PLAINS

#09-15

SINGAPORE 828823

TELEPHONE

HP +65 98570071

TYPE OF CLAIM

OWN DAMAGE CLAIM

POLICY NO

1900104268

VEHICLE NO

MODEL CODE

SLD 1233 A

AUDI A4 SEDAN 2.0 TFSI 8W

MODEL YEAR

31/5/2019

ENGINE NO

CVK 078751

CHASSIS NO

WAUZZZF42KA052364

MILEAGE

23990KM

DATE IN

ESTIMATED BY

16-Jan-21

ACCIDENT DATE

15-Jan-21

PLACE OF ACCIDENT

CLARKE QUAY MULTI-STOREY CARPARK

JOHNNY BOO / ALLAN WU





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S OMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N	\$ 480.00	\$ 480.00
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N	\$ 1,200.00	\$ 1,200.00
3	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N	\$ 350.00	\$ 250.00
4	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY.	S/N	\$ 280.00	\$ 280.00
5	3TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 5,250.00	\$ 2,350.00
	SUB TOTAL LABOUR CHARGES	: [\$ 7,560.00	\$ 4,560.00





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

S/N	NATURE OF JOBS		STIMATED CHARGES		SURVEYOR'S COMMENDATIONS
				\$	4,560.00
6	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT DOOR AND LHS UPPER A-PILLAR.		\$ 4,400.00	\$	1,650.00
7	TO RENEW LHS FRONT RIM. TO CARRY OUT WHEEL ALIGNMENT TEST.	S/N	\$ 280.00	na	
8	Added labour charge - see attached		\$ 280.00	\$	280.00
9	TO CARRY OUT PRE AND POST DIAGNOSTIC CHECK.	S/N	\$ 384.00	\$	384.00
	TOTAL LABOUR CHARGES	:]	\$ 12,904.00	\$	6,874.00





EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

1 FRONT BUMPER \$ 1,787.00 \$ 1,429.60 2 FRONT BUMPER FIXING PARTS \$ 587.00 \$ 28.16 4 FRONT BUMPER SECURING STRIP 2 \$ 71.00 \$ 28.16 4 FRONT BUMPER GRILLE - CENTRE \$ 196.00 \$ 167.60 \$	S/N PARTS DESCRIPTION	DAMAGED PARTS & PRICES QTY S/NETT REMARKS		PRICES REMARKS		
2 FRONT BUMPER FIXING PARTS \$ 587.00 \$ 28.16 \$ 4 FRONT BUMPER SECURING STRIP 2 \$ 71.00 \$ 28.16 \$ 4 FRONT BUMPER GRILLE - CENTRE \$ 196.00 \$ 167.60 \$ 5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE \$ 210.00 \$ 167.60 \$ 5 FRONT BUMPER AIR GUIDE - LH \$ 63.00 \$ 50.08 \$ 7 RADIATOR GRILLE \$ 1,332.00 \$ 108.00 \$ 9 FRONT BUMPER AIR GUIDE GRILLE - LH \$ 135.00 \$ 108.00 \$ 9 FRONT BUMPER CARRIER \$ 845.00 \$ 108.00 \$ 109.00				.,		
3 FRONT BUMPER SECURING STRIP 2 \$ 71.00 \$ 28.16 4 FRONT BUMPER GRILLE - CENTRE 5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE 6 FRONT BUMPER AIR GUIDE - LH 7 RADIATOR GRILLE 8 1,332.00 8 FRONT BUMPER AIR GUIDE GRILLE - LH 9 FRONT BUMPER CARRIER 8 45.00 10 FRONT BUMPER CARRIER 10 FRONT BUMPER TOP COVER 11 FRONT BUMPER GUIDE SECTION - LH 13 CAUTION SIGN STICKER 14 AIRCON STICKER 15 LOCK CARRIER BRACKET 16 LUCK CARRIER BRACKET 17 FRONT PARKING AID SENSOR - 17 FRONT PARKING AID SENSOR - 18 FRONT PARKING AID SEAL RING 19 HORN - LH HIGH TONE 20 SPRING SHACKLE - LH 5 196.00 20 SPRING SHACKLE - LH 5 210.00 \$ 28.16 2 \$ 195.20 2 \$ 126.00 2 \$ 126.00 2 \$ 126.00 2 \$ 126.00 3 \$ 10.00 \$ 10.00 2 \$ 10.00 3 \$ 10.00 5 \$ 10.00	1 FRONT BUMPER		\$	1,787.00	\$	1,429.60
4 FRONT BUMPER GRILLE - CENTRE 5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE 6 FRONT BUMPER AIR GUIDE - LH 7 RADIATOR GRILLE 8 1,332.00 8 FRONT BUMPER AIR GUIDE GRILLE - LH 9 FRONT BUMPER CARRIER 8 135.00 \$ 108.00 9 FRONT BUMPER CARRIER 8 124.00 10 FRONT BUMPER FOAM FILLER PIECE 11 FRONT BUMPER TOP COVER 12 FRONT BUMPER GUIDE SECTION - LH 13 CAUTION SIGN STICKER 14 AIRCON STICKER 15 LOCK CARRIER BRACKET 16 LOCK CARRIER BRACKET 17 INNER/OUTER 18 FRONT PARKING AID SEAL RING 19 HORN - LH HIGH TONE 20 SPRING SHACKLE - LH 10 FRONT BUMPER GUIDE SEAL RING 21 SPRING SHACKLE - LH 21 SPRING SHACKLE	2 FRONT BUMPER FIXING PARTS		\$	587.00		
5 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE 6 FRONT BUMPER AIR GUIDE - LH	3 FRONT BUMPER SECURING STRIP	2	\$	71.00	\$	28.16
LOWER CENTRE \$ 210.00 \$ 167.60 6 FRONT BUMPER AIR GUIDE - LH \$ 63.00 \$ 50.08 7 RADIATOR GRILLE \$ 1,332.00 8 FRONT BUMPER AIR GUIDE GRILLE - LH \$ 135.00 \$ 108.00 9 FRONT BUMPER CARRIER \$ 845.00 10 FRONT BUMPER FOAM FILLER PIECE \$ 124.00 11 FRONT BUMPER TOP COVER \$ 127.00 12 FRONT BUMPER GUIDE SECTION - LH \$ 36.00 \$ 28.72 13 CAUTION SIGN STICKER NEC \$ 14.00 14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKET \$ 137.00 17 INNER/OUTER \$ 484.00 \$ 195.20 18 FRONT PARKING AID SENSOR - 2 \$ 484.00 \$ 195.20 19 HORN - LH HIGH TONE \$ 126.00 20 SPRING SHACKLE - LH \$ 29.00	4 FRONT BUMPER GRILLE - CENTRE		\$	196.00		
7 RADIATOR GRILLE \$ 1,332.00 8 FRONT BUMPER AIR GUIDE GRILLE - LH \$ 135.00 \$ 108.00 9 FRONT BUMPER CARRIER \$ 845.00 10 FRONT BUMPER FOAM FILLER PIECE \$ 124.00 11 FRONT BUMPER TOP COVER \$ 127.00 12 FRONT BUMPER GUIDE SECTION - LH \$ 36.00 \$ 28.72 13 CAUTION SIGN STICKER NEC \$ 14.00 14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - LH/RH FRONT PARKING AID SENSOR - 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00			\$	210.00	\$	167.60
8 FRONT BUMPER AIR GUIDE GRILLE - LH \$ 135.00 \$ 108.00 9 FRONT BUMPER CARRIER \$ 845.00 10 FRONT BUMPER FOAM FILLER PIECE \$ 124.00 11 FRONT BUMPER TOP COVER \$ 127.00 12 FRONT BUMPER GUIDE SECTION - LH \$ 36.00 \$ 28.72 13 CAUTION SIGN STICKER NEC \$ 14.00 14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - 2 \$ 58.00 17 INNER/OUTER 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00	6 FRONT BUMPER AIR GUIDE - LH		\$	63.00	\$	50.08
9 FRONT BUMPER CARRIER \$ 845.00 10 FRONT BUMPER FOAM FILLER PIECE \$ 124.00 11 FRONT BUMPER TOP COVER \$ 127.00 12 FRONT BUMPER GUIDE SECTION - LH \$ 36.00 \$ 28.72 13 CAUTION SIGN STICKER NEC \$ 14.00 14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - LH/RH FRONT PARKING AID SENSOR - 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00	7 RADIATOR GRILLE		\$	1,332.00		
10 FRONT BUMPER FOAM FILLER PIECE \$ 124.00 11 FRONT BUMPER TOP COVER \$ 127.00 12 FRONT BUMPER GUIDE SECTION - LH \$ 36.00 \$ 28.72 13 CAUTION SIGN STICKER NEC \$ 14.00 14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - LH/RH FRONT PARKING AID SENSOR - INNER/OUTER 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00	8 FRONT BUMPER AIR GUIDE GRILLE - LH		\$	135.00	\$	108.00
11 FRONT BUMPER TOP COVER \$ 127.00 12 FRONT BUMPER GUIDE SECTION - LH \$ 36.00 \$ 28.72 13 CAUTION SIGN STICKER NEC \$ 14.00 14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - 2 \$ 58.00 17 FRONT PARKING AID SENSOR - 1 INNER/OUTER 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00	9 FRONT BUMPER CARRIER		\$	845.00		
12 FRONT BUMPER GUIDE SECTION - LH \$ 36.00 \$ 28.72 13 CAUTION SIGN STICKER NEC \$ 14.00 14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - LH/RH FRONT PARKING AID SENSOR - 1 INNER/OUTER 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00	10 FRONT BUMPER FOAM FILLER PIECE		\$	124.00		
13 CAUTION SIGN STICKER 14 AIRCON STICKER NEC \$ 14.00 15 LOCK CARRIER BRACKET LOCK CARRIER BRACKWET SUPPORT - 2 \$ 58.00 16 LH/RH FRONT PARKING AID SENSOR - 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 19 HORN - LH HIGH TONE 20 SPRING SHACKLE - LH \$ 29.00	11 FRONT BUMPER TOP COVER		\$	127.00		
14 AIRCON STICKER NEC \$ 8.00 15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - LH/RH 2 \$ 58.00 17 FRONT PARKING AID SENSOR - INNER/OUTER 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00 20 SPRING SHACKLE - LH \$ 29.00	12 FRONT BUMPER GUIDE SECTION - LH		\$	36.00	\$	28.72
15 LOCK CARRIER BRACKET \$ 137.00 16 LOCK CARRIER BRACKWET SUPPORT - 2 \$ 58.00 17 FRONT PARKING AID SENSOR - 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00	13 CAUTION SIGN STICKER	NEC	\$	14.00		
LOCK CARRIER BRACKWET SUPPORT - 2 \$ 58.00 17 FRONT PARKING AID SENSOR - 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 29.00	14 AIRCON STICKER	NEC	\$	8.00		
16 LH/RH FRONT PARKING AID SENSOR - 2 \$ 484.00 \$ 195.20 17 INNER/OUTER 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 126.00 20 SPRING SHACKLE - LH \$ 29.00			\$	137.00		
17 INNER/OUTER 2 \$ 484.00 \$ 195.20 18 FRONT PARKING AID SEAL RING 4 \$ 14.00 \$ 11.20 19 HORN - LH HIGH TONE \$ 126.00 20 SPRING SHACKLE - LH \$ 29.00	16 LH/RH	2	\$	58.00		
19 HORN - LH HIGH TONE \$ 126.00 20 SPRING SHACKLE - LH \$ 29.00	1/	2	\$	484.00	\$	195.20
20 SPRING SHACKLE - LH \$ 29.00	18 FRONT PARKING AID SEAL RING	4	\$	14.00	\$	11.20
	19 HORN - LH HIGH TONE		\$	126.00		
SUB TOTAL SPARE PARTS : \$ 6,383.00 \$ 2,018.56	20 SPRING SHACKLE - LH		\$	29.00		
	SUB TOTAL SPARE PARTS	:	\$	6,383.00	\$	2,018.56





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

S/N PARTS DESCRIPTION	QTY	DAMAGED PART S/NETT	'S &	PRICES REMARKS
c/f			\$	2,018.56
21 FRONT FENDER - LH		\$ 767.00	\$	613.20
22 FRONT FENDER ATTACHMENT PARTS		\$ 202.00		
23 FRONT FENDER CLOSING ELEMENT - LH		\$ 72.00	\$	57.52
24 FRONT FENDER BRACKET - LH	NEC	\$ 35.00	\$	27.92
25 DEFORMATION ELEMENT BRACKET - LH		\$ 49.00	Ψ	27.32
26 FRONT FENDER BRACE - LH		\$ 118.00	\$	94.40
27 WHEEL HOUSING LINER - LH		\$ 240.00	\$	191.60
28 WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 233.00	Ψ	131.00
29 WHEEL SPOILER - LH		\$ 73.00	\$	58.40
30 WHEEL SPOILER TRIM - LH		\$ 35.00	Ψ	30.40
31 STONE CHIP GUARD - LH		\$ 51.00		
32 TOP FENDER LEDGE COVER - UPPER		\$ 31.00	\$	24.64
33 TOP FENDER LEDGE COVER - LOWER		\$ 23.00	\$	17.92
34 BONNET		\$ 3,246.00	-	77.02
35 BONNET ATTACHMENT PARTS		\$ 412.00		
36 BONNET IMPACT PROTECTION - CENTRE		\$ 28.00		
37 BONNET IMPACT PROTECTION - LH		\$ 28.00		
38 BONNET IMPACT PROTECTION - RH		\$ 28.00		
39 BONNET STRIKER - LH	2	\$ 50.00		
40 BONNET LID LOCK		\$ 214.00		
SUB TOTAL SPARE PARTS	:	\$ 5,935.00	\$	3,104.16





55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLD 1233 A

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT REMARKS				
c/f			\$	3,104.16		
41 LED HEADLIGHT - LH		\$ 7,693.00	\$	6,154.40		
42 MAIN LIGHT ELECTRONICS POWER MODULE		\$ 761.00				
43 LIGHT CONTROL SYSTEM CONTROL UNIT		\$ 751.00				
44 HEADLIGHT HOSE - LH		\$ 36.00				
45 LIFT CYLINDER - LH		\$ 210.00				
46 LIFT CYLINDER CORRUGATED PIPE		\$ 93.00				
47 LOCK CARRIER		\$ 1,016.00	\$	812.80		
48 COOLANT REGULATOR SUPPORT		\$ 38.00				
49 READY MIX COOLANT		\$ 179.00	\$	143.04		
50 RADIATOR AIR GUIDE - OUTER		\$ 28.00				
51 RADIATOR AIR GUIDE - LH		\$ 12.00				
52 RADIATOR AIR GUIDE - UPPER		\$ 16.00				
53 RADIATOR AIR GUIDE - LOWER		\$ 22.00				
54 AIRCON CONDENSER		\$ 622.00				
55 TEMPERATURE SENSOR BRACKET		\$ 19.00				
56 PRESSURE PIPE		\$ 427.00				
57 FRONT BUMPER BRACKET - LH		\$ 228.00				
58 WINDOW GUIDE TRIM STRIP		\$ 257.00				
59 WINDOW SLOT SEAL - LH		\$ 307.00				
60 FRONT NO PLATE	S/N	\$ 60.00				
61 SUPPLEMENTARY		\$ 529.00	\$	422.80		
62 SUNDRIES		\$ 400.00				
TOTAL SPARE PARTS	:	\$ 26,022.00	\$	10,637.20		
TOTAL LABOUR CHARGES	:	\$ 12,904.00	\$	6,874.00		
GRAND TOTAL	:	\$ 38,926.00	\$	17,511.20		

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.



55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

Estimate No. PA/OD/0058/2021/NS AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way **Date** 25-Jan-21 #07-16 AIG Building Service Advisor CHANG **Pages** 1 of 1 Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Regn No **SLD 1233 A** Tel: 6841 0055 / Fax: 6256 4315 **Model No** AUDI A4 SEDAN 2.0 TFSI 8W Description Quantity **Unit Price Amount**

	GRAND TOTAL	\$ 809.00	\$ 702.80
Parts 1 2	HEADLIGHT WASHER CYLINDER BRACKET	\$ 6.00 523.00	\$ 4.80 418.00
Labour 1	TO RENEW AIRCON CONDENSER REFRIGERANT (S/N) PIPE.	\$ 280.00	\$ 280.00

For Premium Automobiles Pte Ltd

Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF

THE AFFECTED VEHICLE. SHOULD WE REQUIRE

FURTHER LAOUR CHARGES AND SPARE PARTS IN THE

PROGRESS OF REPAIR, WE SHALL INFORM YOU

ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY. PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO **BODY REPAIR MANAGER** **ALLAN WU** CLAIMS CONSULTANT