

趙源摩 嚙

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007

To: Sompo Insurance Singapore Pte Ltd

Accident Date : 15.01.2021

Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Third Party

19.01.2021

Specialised in Car Painting, Welding, Panel-Beating and Insurance Claim.

Acknowledged by Repairer
 Signature:

ESTIMATE

承接汽车烧焊喷漆及代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount \$	银 Amount cts.
<p>Estimate Cost of Repair to "Hyundai Accent" Reg. No. SMJ1439E Claiming Against Your Insured Veh. No. SJH8619C</p>				
1pc	Boot			
2pcs	Boot Hinges	99.00		1,223.90
1pc	Boot Center Emblem			198.00 X
1pc	Boot Badge "Accent"			26.70
1pc	Boot Outer Garnish			31.20
1pc	Boot Lock			35.70 X
1pc	Boot Lock Catch			166.80
1pc	Boot Weatherstrip			10.00 X
1pc	Boot Stopper RH			79.50
1pc	Boot Trim Board			6.70
10pcs	Boot Trim Board Clips	3.50		84.80
1pc	Boot Key Sensor			35.00
1pc	Rear Bumper			80.20
1pc	Rear Bumper Clips			443.00
10pcs	Rear Bumper Brackets	3.50		35.00
2pcs	Rear Bumper Reinforcement	33.50		67.00
1pc	Rear Bumper Sensors			376.50
3 4pcs	Rear Bumper Sensor Holders	195.90		783.60
4pcs	Rear Bumper Sensor Wiring Harness	15.00		60.00
1pc	Rear Bumper Reflectors			191.50
2pcs	Rear Bumper Corner Retainers	44.60		89.20
1pc	End Panel	23.20		46.40
1pc	End Panel Garnish			499.30
2pc	Taillamp X2	776		115.10
2pcs	Taillamp Panel	171.90		388.00
2pcs	Taillamp Gasket	38.00		343.80
1pc	Rear Fender Splash Guard RH			76.00
2pcs	Rear Fender Trim Board	171.70		95.00
1pc	Spare Tyre Panel			95.00
1pc	Spare Tyre Panel Insulation			343.40
1pc	Spare Tyre Top Board			222.20
1pc	Rear Styrofoam Storage Box			180.00
1pc	Bonnet			242.00
1pc	Front Bumper			138.00
14pcs	Front Bumper Clips			1,282.00
2pcs	Front Bumper Brackets	3.00		474.40
1pc	Front Bumper Sponge	95.00		42.00
1pc	Front Bumper Reinforcement			190.00
1pc	Front Bumper Center Air Grille			110.70
				269.50
				48.80
		CIF		9,130.90

Not Notified
 Anthony Bepelm
 12 days
 13, 583.52

趙源摩托

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Sompso Insurance Singapore Pte Ltd

Policy No: Third Party

Accident Date : 15.01.2021

Date: 19.01.2021

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

承接汽车烧焊喷漆及
 代理各种车辆赔偿

ESTIMATE

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount \$ cts.
Estimate Cost of Repair to "Hyundai Accent" Reg. No. SMJ1439E Claiming Against Your Insured Veh. No. SJH8619C			
2pcs	Front Bumper Fog Lamps	B/F	9,130.90
1pc	Front Bumper Number Plate Holder	186.90	373.80 ✓
1pc	Front Bumper Tow Cover		18.00 ✓
2pcs	Front Bumper Corner Retainer	11.00	22.00 X
1pc	Front Bumper Top Rubber Seal		41.60 ✓
1pc	Grille		62.50 ✓
1pc	Grille Emblem		25.60 ✓
1pc	Grille Chrome Surround		157.80 ✓
2pcs	Headlamps	703.80	1,407.60 ✓
1pc	Horn		49.00 X
1pc	Support Panel		781.80 ✓
1pc	Support Panel Top Garnish		49.20 ✓
1pc	Air Con Condensor		746.80 ✓
2pcs	Air Con Condensor Side Air Guide	28.30	56.60 ✓
1pc	Radiator		594.90 X
1pc	Radiator Fan Assy		618.80 X
	Less 10% 201		14,143.90
			1,414.39
			12,729.51
	Rear Number Plate		45.00 SN ✓
	Front Number Plate		45.00 SN ✓
	Portable Tyre Pressure Inflator		150.00 SN X
	Roadside Signage		55.00 SN X
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00 1001
	To Remove / Refit, Radiator System, Bleed, Refill Coolant		60.00 501
	To Dismantle / Transfer Boot Fittings / Ancillary Accessories		80.00 601
	To Dismantle / Refit Trunk Compartment Boards & Trims		100.00 301
	To Supply Rear End Body Panel Sealant		100.00 601
		C/F	13,514.51

趙源摩哆

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: Z21880/00C GST Reg. No: MX-0486007-A0

To: Sompo Insurance Singapore Pte Ltd

Third Party

Policy No: _____

Accident Date : 15.01.2021

Date: 19.01.2021

Specialised in Car Painting, Welding,
 Panel-Beating and Insurance Claim.

承接汽车烧焊喷漆及
 代理各种车辆赔偿

ESTIMATE

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银金额 Amount \$ cts.
	Estimate Cost of Repair to "Hyundai Accent" Reg. No. SMJ1439E Claiming Against Your Insured Veh. No. SJH8619C		
	To Conduct Rear Electric Check, Replace Reverse Sensors, Reprogram System	B/F	13,514.51
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel	(B,11)	120.00 601
	To Provide Transportation (Towing)		150.00 1201
	Labour Charge - Panel Beating, Repairing Of Front Chassis Member, Front LH Fender, Rear Floor Panel, Chassis, Rear Fender x2 etc. Cnt, Weld End Panel, Spare Tyre Panel, Taillamp Panel And Part Replacement.		120.00 2
	To Spray Painting Affected Areas		1,800.00 1501
			1,650.00 14001
	Total :		17,354.51
			17,703.71