

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 19-Jan-21

INSURANCE: ALG

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHC3126R

Description	Qty	List Price	Amount
Rear Door (LH) <i>Dent</i>	1	\$ 1,789.90	\$ 1,789.90
Rear Door Rubber(LH) <i>SVL</i>	1	\$ 280.00	\$ 280.00
Rear Door Gear/Regulator(LH) <i>HH</i>	1	\$ 367.84	\$ 367.84
Rear Door Power Motor (LH) <i>HH</i>	1	\$ 256.80	\$ 256.80
Rear Door Lock Assy <i>SVL</i>	1	\$ 306.40	\$ 306.40
Rear Door Trim Board (LH) <i>HH</i>	1	\$ 613.60	\$ 613.60
Rear Door Protector(LH) <i>Cut</i>	1	\$ 166.20	\$ 166.20
Rocker Panel Outer Garnish <i>Cut / mainly broken</i>	1	\$ 715.60	\$ 715.60
Rocker Panel Outer <i>HH</i>	1	\$ 1,799.60	\$ 1,799.60
Rear Bumper <i>Cut / mainly broken</i>	1	\$ 459.40	\$ 459.40
Rear Bumper Side retainer (LH) <i>SVL</i>	1	\$ 85.80	\$ 85.80
Rear Bumper Cover Clips <i>Neo</i>	1	\$ 22.00	\$ 22.00
Rear Fender(LH) <i>Dent</i>	1	\$ 1,768.30	\$ 1,768.30
Rear Tyre Rim (LH) <i>2 distors</i>	1	\$ 1,124.20	\$ 1,124.20
Rear Wheel Hub-Cap (LH) <i>Cut</i>	1	\$ 346.40	\$ 346.40
Rear Wheelbearing & Hub assy <i>2 Daw</i>	1	\$ 554.00	\$ 554.00
Rear Trailing Arm(LH) <i>2 distors</i>	1	\$ 265.40	\$ 265.40
Rear Assist (LH) <i>2 distors</i>	1	\$ 227.90	\$ 227.90
Rear shock Absorber(LH) <i>2 distors</i>	1	\$ 230.50	\$ 230.50
Rear Shock Absorber Mounting (LH) <i>HH</i>	1	\$ 133.10	\$ 133.10
Rear Absorber stopper (LH) <i>HH</i>	1	\$ 137.60	\$ 137.60
Rear Absorber Cover (LH) <i>HH</i>	1	\$ 175.60	\$ 175.60
Rear Crossmember <i>HH</i>	1	\$ 1,468.70	\$ 1,468.70
Stabilizer Bar <i>HH</i>	1	\$ 387.30	\$ 387.30
Stabilizer Link (LH) <i>HH</i>	1	\$ 147.30	\$ 147.30
Rear Upper Arm(LH) <i>2 distors</i>	1	\$ 239.50	\$ 239.50
Rear Lower Arm(LH) <i>2 distors</i>	1	\$ 393.10	\$ 393.10
Rear Knuckle Arm (LH) <i>2 distors</i>	1	\$ 538.10	\$ 538.10
SUB TOTAL			\$ 15,000.14
LESS 20%			\$ 3,000.03
DISCOUNTED TOTAL			\$ 12,000.11
Rear Door Tel No.Sticker(LH) <i>Hec</i>	SN 1	\$ 10.00	\$ 10.00
Rear Door Comfortdelgro & Apps Sticker(LH) <i>Hec</i>	SN 1	\$ 80.00	\$ 80.00
Rear Bumper Rubber Mat <i>Hec</i>	SN 1	\$ 50.00	\$ 50.00
Rear Tyre(LH) <i>SVL</i>	SN 1	\$ 216.00	\$ 216.00
SUB TOTAL			\$ 356.00
Labour Charge			
Panel Beating	1	\$1,600.00	\$1,600.00
Spray Painting Charge	1	\$1,400.00	\$1,400.00

✓

X

X

X

X

X

✓

✓

X

✓

X

✓

✓

✓

✓

✓

✓

✓

✓

✓

X

X

X

X

X

X

✓

✓

✓

✓

✓

✓

✓

✓

✓

X

8840.50

7072.40

140.00

600 - 700 -

600 - 700 -

Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$120.00	\$120.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00
Re-set Rear ABS System	1	\$400.00	\$400.00
Remove/Refix Fuel Tank	1	\$80.00	\$80.00
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00
Re-set Rear Power Window System	1	\$200.00	\$200.00
Four Wheel Alignment	1	\$120.00	\$120.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$5,480.00
ESTIMATE TOTAL			\$ 17,836.11
This is an initial			

24
 40/-
 24
 80/-
 40/-
 150/-
 24
 24
 24
 60/-
 24
 60/-
 150/-
 1980.00

20/01/2021 @ 1600hrs

P/P 9192.40

Not Actual

Part by Part.

7 days.

1 year

LKK Auto

Photo after repair with damaged parts

8

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: