



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN : JEFFREY NG		Ref: CS3/AIG20012051/Gvf3e2-1 Date: 04/03/2021 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SFB 887B	Veh. Inspected	SMR 1608S
Policy No.	2100480420	Coverage (\$)	0.00
Claim No.	7983114540SG	Excess (\$)	0.00
Assign From	JEFFREY NG	Assign Date	20/01/2021
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ B180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2462422J261505	Colour	WHITE
Odometer	86520 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEXEN	6 mm
L/H Front Tyre	205/55 R16	NEXEN	6 mm
R/H Rear Tyre	205/55 R16	NEXEN	6 mm
L/H Rear Tyre	205/55 R16	NEXEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/11/2020	Inspection Date	05/11/2020
Survey held at	JP CONCEPTZ PTE LTD 160 SIN MING DRIVE #07-11 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	