

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

TO	: ERGO	DATE	: 20/1/2021
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SLX6600K		
VEHICLE MODEL	: BMW 320i		
CHASSIS NO	: WBAB16030NS51471		Veron.
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	XAVIER / 90079247	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER SIDE HOLDER RH <i>new</i>	1	\$ 92.00	\$ 92.00
2	FRONT BUMPER SPONGE <i>could</i>	1	\$ 85.00	\$ 85.00
3	FRONT BUMPER REINFORCEMENT <i>best</i>	1	\$ 468.00	\$ 468.00
4	FRONT BUMPER FOG LAMP RH <i>could</i>	1	\$ 295.00	\$ 295.00
5	FRONT BUMPER FOG LAMP GRILLE RH <i>new</i>	1	\$ 89.00	\$ 89.00
6	FRONT BUMPER NOZZLE COVER RH <i>missing</i>	1	\$ 35.00	\$ 35.00
7	FRONT BUMPER NOZZLE PUMP RH <i>could</i>	1	\$ 249.00	\$ 249.00
8	FRONT BUMPER INNER AIR DUCT RH <i>could</i>	1	\$ 65.00	\$ 65.00
9	FRONT BUMPER LOGO <i>new</i>	1	\$ 78.00	\$ 78.00
10	FRONT BUMPER TOP INNER FRAME <i>could</i>	1	\$ 148.00	\$ 148.00
11	FRONT GRILLE <i>RH could</i>	2	\$ 145.00	\$ 290.00
12	HEADLAMP RH <i>could</i>	1	\$ 2,083.00	\$ 2,083.00
13	BONNET <i>new</i>	1	\$ 1,659.00	\$ 1,659.00
14	FRONT RH FENDER <i>new</i>	1	\$ 699.00	\$ 699.00
15	FRONT RH FENDER INNER SHIELD <i>could</i>	1	\$ 186.00	\$ 186.00
16	FRONT RH FENDER INNER SHIELD LOWER COVER <i>new</i>	1	\$ 68.00	\$ 68.00
17	FRONT RH WHEEL RIM <i>new</i>	1	\$ 150.00	\$ 1,250.00
18	FRONT RH LOWER ARM <i>new</i>	1	\$ 450.00	\$ 450.00
19	FRONT RH UPPER ARM <i>new</i>	1	\$ 488.00	\$ 488.00
20	FRONT RH STAY ARM <i>new</i>	1	\$ 329.00	\$ 329.00
21	FRONT RH KNUCKLE ARM <i>new</i>	1	\$ 899.00	\$ 899.00
22	FRONT RH WHEEL HUB C/W BEARING <i>new</i>	1	\$ 354.00	\$ 354.00
23	FRONT RH SHOCK ABSORBER <i>new</i>	1	\$ 695.00	\$ 695.00

TOTAL PRICE: \$ 11,054.00
LESS 10% \$ 1,105.40

3929
3536 10

S.N. 700

SUB TOTAL PRICE:

\$ 9,948.60

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Dischd</i>	1	\$ 2,000.00	\$ 2,000.00 <i>1500</i>
2	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 <i>30</i>
3	FRONT RH FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00 ✓
6	FRONT RH FENDER INNER SHIELD LOWER COVER CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00 ✓
TOTAL :				\$ 2,100.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	<i>400</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	<i>600</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>40</i>	
5	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	<i>x</i>	
6	TO REMOVE FRONT UNDERCARRIAGE	\$ 380.00	<i>x</i>	
7	TO PERFORM DIAGNOSTIC TEST	\$ 150.00	<i>100</i>	
TOTAL:		\$ 2,880.00	<i>1170</i>	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 12,048.60

TOTAL LABOUR COST: \$ 2,880.00

TOTAL REPAIR COST: \$ 14,928.60

APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 6966.10
2/s: 5.5 K.

05 Days

5.5 K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: