

AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 Kaman Koh: 9769 9299 Email: motoricarzgarage@gmail.com

UEN:201919765N

Estimation

NKE1657140274

VEHICLE NO.: **EZ5671J**
MAKE/MODEL: **TOYOTA/AXIO**
DATE OF ACCIDENT: **18/1/2021**

DATE OF SURVEY: **20/1/2021**
SURVEYOR NAME: **ADRIAN LING (LKK)**
SURVEYOR CONTACT NO.: **9689 3735**

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BOOTLID	1	972.00	972.00
2	BOOTLID OUTER CHROME GARNISH	1	374.45	374.45
3	BOOTLID HINGE	2	55.00	110.00
4	BOOTLID STOPPER	2	30.00	60.00
5	BOOTLID INSULATOR	1	161.70	161.70
6	BOOTLID EMBLEM-LOGO	1	121.25	121.25
7	BOOTLID EMBLEM-AXIO	1	131.35	131.35
8	BOOTLID EMBLEM - COROLLA	1	85.30	85.30
9	REAR TAILLAMP PANEL RH	1	278.45	278.45
10	REAR FENDER RH	1	1,072.40	1,072.40
11	REAR FENDER INNER TRIM RH	1	561.60	561.60
12	REAR TAILLAMP RH	1	490.50	490.50
13	REAR BUMPER	1	1,218.50	1,218.50
14	REAR BUMPER RETAINER	2	65.60	131.20
15	REAR BUMPER REINFORCEMENT	1	391.45	391.45
16	REAR BUMPER REFLECTOR RH	1	131.35	131.35
17	REAR END PANEL	1	781.90	781.90
18	REAR END PANEL TOP GARNISH	1	274.45	274.45
19	SPARE TYRE TOP BOARD	1	581.90	581.90
20	REAR EXHAUST SILENCER	1	781.45	781.45
21	REAR EXHAUST MOUNTING	2	30.00	60.00
22	REAR WINDSCREEN MOULDING	1	190.00	190.00
				8,961.20
				Less 25%
				2,240.30
				6,720.90
S/Nett items:				
23	REAR BUMPER CLIP	1 SET	30.00	30.00
24	BOOTLID INNER TRIM CLIP	1 SET	20.00	20.00
25	REAR SENSOR	1 SET	400.00	400.00
26	JOINT SEALANT	1	120.00	120.00
27	WINDSCREEN SEALANT	1	120.00	120.00
				690.00
Labour to:				
28	CHECK ALL WIRING AND LIGHTNING SYSTEM		90.00	90.00
29	REMOVE AND RENEW REAR SENSOR		120.00	120.00
30	REMOVE AND RENEW REAR EXHAUST		150.00	150.00
31	REMOVE AND REFIT REAR WINDSCREEN		120.00	120.00
32	REMOVE, REFIT TRIM, LINING AND GARNISH		200.00	200.00
33	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW		200.00	200.00
34	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS		1,600.00	1,600.00
35	SPRAY PAINTING ON AFFECTED AREAS		1,800.00	1,800.00
36	APPLY ANTI RUST ON AFFECTED AREAS		120.00	120.00
				4,400.00

LKK Auto Consultants hence notify the Reparer of the following:

- To survey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
Signature: _____
Date: _____

Parts Replacement Amount \$ 7,410.90
Total Amount for Labour \$ 4,400.00
Total Amount(SGD) \$ 11,810.90

total: 2225.82
CP/P)

Adrian Ling
P/P 20/01/21 04 Dgs