



8 Kaki Bukit Ave 4
#04-20 Premier
Singapore 415875

Car Reg No: GBJ1019P
Make & Model : Toyota Hiace

Repair Detail

Recommended Parts

No	Qty	Description	
1	1	Rear left Taillamp <i>✓ CPA</i>	\$ 785.00

354.8

Total Parts

\$ 785.00

25% = 266.1

Recommended Labour

No	Qty	Description	Amount
1		To remove and install Rear Left Tailamp	\$ 250.00
2		To check rear lighting and wiring	\$ 200.00
3		To putty and spray painting rear left portion	\$ 200.00

50

50

X NN

Total labour

\$ 650.00

Total Parts

\$ 785.00

Total labour

\$ 650.00

Total repair cost

\$ 1,435.00

366.1

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Day

P/P

Gue Qiang

25/1/2021