

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21000974/UTF3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00070532003
Claimant Vehicle No :	FBR9064M	Insured Vehicle No :	YP7391U
Date of Loss:	12/01/2021	Nature of Claim:	TP
		Claim No:	SNM21D200308/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR9064M	Engine No:	G3H6E0016912
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG431000013497
Reg. Date:	26/11/2020 (Man. Year: 2019)	Odometer:	7110 km
Colour:	Blue		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,310.40	1,310.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	320.00	180.00	140.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,630.40	1,490.40	140.00	8.59
Approved Total (Overridden) (S\$)		1,100.00		
Nett Amount (S\$)	1,630.40	1,100.00	530.40	32.53

INSPECTION

Date of Assignment:	25/02/2021	
Date Inspected:	21/01/2021	Inspected At: Teo Spray Painting (HQ) BLK 6 DEFU LANE 10, DEFU IND PARK C #01-558 Singapore 539187
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Mar 2021)	
Parts:	N/A	YAMAHA NMAX155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR9064M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	75.00 FL	*75.00 FL
2	1		*FRONT SIGNAL LH	Cracked	58.00 FL	*58.00 FL
3	1		*FRONT SIDE COVER RH	Cut	85.00 FL	*85.00 FL
4	1		*LOGO LEFT SIDE COVER	Necessary	65.00 FL	*65.00 FL
5	1		*LOGO RIGHT SIDE COVER	Necessary	65.00 FL	*65.00 FL
6	1		*FRONT LOWER COVER LH	Cracked	75.00 FL	*75.00 FL
7	1		*FRONT LOWER COVER RH	Cut	75.00 FL	*75.00 FL
8	1		*FLOOR STEP LH	Cut	85.00 FL	*85.00 FL
9	1		*FLOOR STEP RH	Cut	85.00 FL	*85.00 FL
10	1		*BRAKE LEVER	Scratched	28.00 FL	*28.00 FL
11	1		*SIDE MIRROR RH	Cut	35.00 FL	*35.00 FL
12	1		*EXHAUST PROTECTOR	Cut	70.00 FL	*70.00 FL
13	1		*LOWER CENTER BLACK COVER	Cut	75.00 FL	*75.00 FL
14	1		*FORK HOLD SET	Cracked/Twisted	580.00 FL	*580.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	1,456.00	1,456.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	145.60	145.60
Total Parts (\$\$)	1,310.40	1,310.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSPORT	New	70.00	0.00
2	LABOUR CHARGES	New	250.00	180.00
Gross Labour Cost (S\$)			320.00	180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >