

BIKE PRODUCTION PTE LTD
610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 20 Jan 2021

ASSESSMENT FOR REPAIR: YAMAHA XABRE TFX150 - FBN6789X

Chassis No.:

Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front fender	\$145.00
1 pc	Front wheel shaft	\$75.00
1 pc	Left front foot rest	\$75.00
1 pc	Front left fork assy	\$680.00
1 pc	Side stand	\$85.00
1 pc	Steering stem	\$220.00
1 pc	Steering bridge	\$195.00
2 pcs	Steering bearings	\$90.00
1 set	Gear pedal	\$78.00
1 pc	Front left signal	\$125.00
1 pc	Left view mirror	\$95.00
1 pc	IU bracket	\$45.00
1 pc	Handle bar	\$175.00
1 pc	Left balancer	\$48.00
1 pc	Clutch lever	\$55.00
1 pc	Left handgrip	\$35.00
1 pc	Fuel tank left cover	\$205.00
1 pc	Fuel tank emblems	\$75.00
1 pc	Left rear signal	\$115.00
1 pc	Left side cover emblem	\$70.00
1 pc	Left side cover	\$175.00
		<hr/>
		\$2,861.00
	Less discount 10%	\$286.10
		<hr/>
		\$2,574.90
	<u>Special nett items</u>	
1 pc	Sport rim front	\$580.00
1 pc	Front number plate	\$20.00
1 pc	ERP IU	\$157.00
1)	Towing charges	\$100.00
	Replace, realign and adjust above damaged parts, check wiring and	
2)	lighting system	\$800.00
	To knock, straighten chassis & body	
3)	balancing	\$380.00
	To remove/refit, replace (if damage) check and	
4)	straighten front fork tubes.	\$180.00
	To remove/refit, replace (if damage) check and	
4)	straighten front sport rims.	\$150.00
6)	Spray painting	\$280.00
	Total Estimate	<hr/>
		\$5,221.90

Note: The above estimate is subjected to the prevailing GST of 7%

