

Section A - Accident Details

Registration Number	SHC4576T
Case Reference Number	TAX/01/21/2027
Registration Date	10/12/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN JOO SENG
Type of Accident	Side Swipe
Accident Date and Time	16/1/2021 9:15 AM
Accident Reported Date and Time	18/1/2021 10:03 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109491
Special Instruction to ARC, if any	TP /TOWED \$40
Prepared Date and Time	18/1/2021 1:50 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,264.00	\$600.00
Total Spray Cost	\$2,970.00	\$1,010.00
Total Spare Part Cost	\$15,483.56	\$3,255.70
Total Other Cost	\$1,586.00	\$230.00
TOTAL COST	\$21,303.56	\$5,095.70
Lump Sum Total	\$21,300.00	\$5,100.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	21/01/2021 1:21 PM	21/01/2021 9:57 AM
Signature		
Remarks	Total number of repair days = 5 days. SUP = +1 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2102-0073	Invoice Number	
Quotation Date	08.02.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT SUPPORT PANEL	\$250.00	\$100.00
TO REPAIR FRONT LH PORTION	\$1,014.00	\$500.00
Total Labour	\$1,264.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY APRON PANEL LH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$80.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$80.00
Total Spray Painting & Panel Beating	\$2,970.00	\$1,010.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	\$30.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$250.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$250.00	\$100.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$1,586.00	\$230.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	25.00	\$361.50	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace

CRU
Nec

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63855592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 08/02/2021

User ID : PohSuan

52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Check	X	SVC
52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Check	X	SVC
57014-47030	ARM SUB-ASSY, FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Check	X	SVC
57013-47030	ARM SUB-ASSY, FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Check	X	SVC
52114-47140	BRACKET, FR BUMPER	1.00	\$110.40	25.00	\$82.80	Replace	Replace		BR
	NUMBER PLATE	1.00	\$15.00	0.00	\$15.00	Replace	Replace		SCR
	NUMBER PLATE FRAME	1.00	\$12.00	0.00	\$12.00	Replace	Replace		SCR
52128-47903	COVER, FR BUMPER HOLE LH	1.00	\$18.50	25.00	\$13.88	Replace	Replace		SCR
52127-47903	COVER, FR BUMPER HOLE RH	1.00	\$18.50	25.00	\$13.88	Replace	Replace		SCR
52116-47040	BUMPER SUPPORT F/LH	1.00	\$76.40	25.00	\$57.30	Replace	Replace		BR
52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace		BR
53102-47020	BUMPER GRILLE SUB-ASSY, LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Check	X	SVC
81220-12230	FOG LAMP LH	0.00	\$280.10	10.00	\$0.00	Replace	Not Given	X	SVC
81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Check	X	SVC
81519-47050	BRACKET, FR TURN LOWER RH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X	SVC
81519-47060	BRACKET, FR TURN UPPER RH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X	SVC
81519-47060	BRACKET, FR TURN CENTER RH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X	SVC
81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Check	X	SVC
81529-47060	BRACKET, FR TURN CENTER LH	0.00	\$58.20	0.00	\$0.00	Replace	Check	X	SVC
81529-47050	BRACKET, FR TURN LOWER LH	0.00	\$26.00	0.00	\$0.00	Replace	Check	X	SVC
81529-47040	BRACKET, FR TURN UPPER LH	0.00	\$24.40	0.00	\$0.00	Replace	Check	X	SVC
81521-47050	LENS & BODY, FR TURN LH	0.00	\$511.80	0.00	\$0.00	Replace	Not Given	X	SVC
53113-47040	GRILLE RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Check	X	SVC
53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Check	X	SVC
75310-47010	EMBLEM FRONT	1.00	\$86.50	25.00	\$64.88	Replace	Replace		NEC
76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Check	X	SVC
52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Not Given	X	SVC
82113-47180	WIRE, ENGINE ROOM, NO.3	0.00	\$242.00	0.00	\$0.00	Replace	Not Given	X	SVC
88790-22131	THERMISTOR ASSY	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X	SVC
53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair		R
53420-47070	HOOD HINGE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X	SVC
53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given	X	SVC
53395-47020	HOOD END PANEL SEAL	0.00	\$35.50	0.00	\$0.00	Replace	Not Given	X	SVC
53201-47902	SUPPORT SUB-ASSY	0.00	\$1,460.40	0.00	\$0.00	Replace	Check	X	SVC
81170-47500	HEAD LAMP LH	1.00	\$945.20	10.00	\$850.68	Replace	Replace		CR4
81130-47500	HEAD LAMP RH	0.00	\$945.20	0.00	\$0.00	Replace	Check	X	SVC
85315-47140	WIPER WASHER JAR	0.00	\$180.10	0.00	\$0.00	Replace	Check	X	SVC
53802-47050	FENDER FRT/LH	1.00	\$723.40	25.00	\$542.55	Replace	Replace		CR4
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace		NEC
53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check	X	SVC
53852-47020	FENDER LINER PAD, FR WHEEL LH	0.00	\$49.30	0.00	\$0.00	Replace	Check	X	SVC
53826-47010	FENDER PROTECTOR FRT/LH UPPER	0.00	\$46.10	0.00	\$0.00	Replace	Check	X	SVC

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63585592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 08/02/2021

User ID PohSuan

		5328-47060	PROTECTOR, FRONT FENDER SIDE PANEL LH	0.00	\$114.50	0.00	\$0.00	Replace	Check	X	SUC
		53702-47050	FENDER APRON SUB FRT/LH	0.00	\$637.80	0.00	\$0.00	Replace	Check	X	SUC
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	Replace		BR
		42611-47140	WHEEL DISC. FRONT	1.00	\$1,484.20	100.00	\$0.00	Replace	Repair	R	R
		45047-49165	TIE ROD END LH	0.00	\$159.30	0.00	\$0.00	Replace	Check	X	SUC
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Check	X	SUC
		48619-28010	SHOCK ABSORBER BEARING, FRT LH/RH	0.00	\$34.00	0.00	\$0.00	Replace	Check	X	SUC
		48520-80294	SHOCK ABSORBER FRT/LH	0.00	\$394.20	0.00	\$0.00	Replace	Check	X	SUC
		48609-47040	SHOCK ABSORBER MOUNTNG FRT, RH/LH	0.00	\$193.80	0.00	\$0.00	Replace	Check	X	SUC
		48820-47020	STABILIZER BAR LINK FRT/RH/LH	0.00	\$195.00	0.00	\$0.00	Replace	Check	X	SUC
		43202-47030	STEERING KNUCKLE LH FRT	0.00	\$580.80	0.00	\$0.00	Replace	Check	X	SUC
		43420-47030	DRIVE SHAFT LH	0.00	\$1,543.80	0.00	\$0.00	Replace	Check	X	SUC
		48069-47050	LOWER ARM FRT/LH	0.00	\$625.90	0.00	\$0.00	Replace	Check	X	SUC
		43330-49185	JOINT ASSY, LWR BALL	0.00	\$195.60	0.00	\$0.00	Replace	Check	X	SUC
		45510-47070	STEERING RACK ASSY	0.00	\$1,597.50	0.00	\$0.00	Replace	Check	X	SUC
		67002-47070	DOOR FRT/LH	1.00	\$894.40	100.00	\$0.00	Replace	Repair	R	R
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace		Nec
		87940-47310	MIRROR ASSY, LH	0.00	\$1,224.90	0.00	\$0.00	Replace	Not Given	X	SUC
		81740-52040	MIRROR LAMP LH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given	X	SUC
		87945-74010	COVER, OUTER MIRROR, LH	1.00	\$107.40	100.00	\$0.00	Replace	Repair	R	R
		53801-47050	FENDER FRT/RH	0.00	\$723.40	0.00	\$0.00	Replace	Not Given	X	SUC
		75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	0.00	\$0.00	Replace	Not Given	X	SUC
		53875-47030	FENDER LINER FRT/RH	1.00	\$171.70	25.00	\$128.78	Replace	Replace		Cut
		53851-47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given	X	SUC
		53341-47020	HOOD PANEL INSULATOR	0.00	\$390.50	0.00	\$0.00	Replace	Not Given	X	SUC
Total					\$22,764.35		\$2,690.39				2,438.30

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		48069-47050	LOWER ARM FRT/LH	1.00	\$625.90	25.00	\$469.43	Replace	Replace	BT
		43202-47030	STEERING KNUCKLE LH FRT	1.00	\$580.80	25.00	\$435.60	Replace	Replace	BT
		81511-47050	LENS & BODY, FR TURN RH	1.00	\$511.80	10.00	\$460.62	Replace	Replace	SCR
		81210-12230	FOG LAMP RH	1.00	\$295.20	10.00	\$265.68	Replace	Replace	CPA
Total					2,013.70		1,631.33			

4069.63 / -20%

3255.70 / 4/5 \$5,100 /

+ 600.00 / + 1240.00 /

5095.70 /



Factory Japan 2020.0.1 : Toyota : Prius : W30 Series : ZVW30
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-2°30'	-2°31'	-0°55' 0°35'
5°34'	5°34'	5°00' 6°30'
0°10'	0°12'	0°00' 0°11'
14°42'	14°42'	11°20' 12°50'
12°11'	12°11'	10°25' 13°25'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°21'	-0°21'	-0°55' 0°35'
5°34'	5°34'	5°00' 6°30'
-0°08'	-0°08'	0°00' 0°11'
12°24'	12°24'	11°20' 12°50'
12°03'	12°03'	10°25' 13°25'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-2°10'	-2°10'	
-0°01'	-0°01'	
2°18'	2°18'	
0°01'	0°04'	0°00' 0°22'

Rear : Left

Actual	Before	Specified Range
-1°32'	-1°32'	-2°00' -1°00'
0°24'	0°24'	-0°03' 0°14'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°13'	-1°13'	-2°00' -1°00'
-0°01'	-0°01'	-0°03' 0°14'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-0°18'	-0°18'	
0°23'	0°23'	-0°06' 0°28'
0°12'	0°13'	
0mm	0mm	



SHC4576T

Toyota : Prius (Modified Specification)
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°34'	-0°37'	-0°55' 0°35'
5°34'	5°34'	5°00' 6°30'
-0°01'	0°03'	-0°06' 0°06'
12°47'	12°51'	11°20' 12°50'
12°13'	12°13'	10°25' 13°25'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°18'	-0°13'	-0°55' 0°35'
5°36'	5°36'	5°00' 6°30'
0°01'	-0°17'	-0°06' 0°06'
12°19'	12°14'	11°20' 12°50'
12°01'	12°01'	10°25' 13°25'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°16'	-0°24'	
-0°02'	-0°02'	
0°28'	0°36'	
0°00'	-0°14'	-0°11' 0°11'

Rear : Left

Actual	Before	Specified Range
-1°39'	-1°43'	-2°00' -1°00'
0°06'	0°06'	-0°03' 0°14'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°09'	-1°04'	-2°00' -1°00'
0°18'	0°17'	-0°03' 0°14'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-0°30'	-0°38'	
0°25'	0°23'	-0°06' 0°28'
-0°06'	-0°06'	
0mm	0mm	