



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2107621
3 ANSON ROAD #16-00	INV Date	05/11/2021
SPRINGLEAF TOWER	Reference	CC6/CTI21000980/Aes3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SMN 6833X
Insured Veh.	XE 819U
Claim No.	SNM21D200283
Policy No.	DMCVSNA00055122000
Accident Date	16/01/2021
Inspection Date	19/01/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Ref: CC6/CTI21000980/Aes3q2

Date: 05/11/2021

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 819U	Veh. Inspected	SMN 6833X
Policy No.	DMCVSNA00055122000	Coverage (\$)	0.00
Claim No.	SNM21D200283	Excess (\$)	0.00
Assign From		Assign Date	19/01/2021

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JHMGK3850KS218220	Colour	BLUE
Odometer	65915 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	DUNLOP	6 mm
L/H Front Tyre	175/65 R15	DUNLOP	6 mm
R/H Rear Tyre	175/65 R15	DUNLOP	6 mm
L/H Rear Tyre	175/65 R15	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/01/2021	Inspection Date	19/01/2021
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 6833X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR RH	DENTED	849.00	849.00
1	REAR DOOR LOCK RH	NOT NECESSARY	235.10	-
1	REAR DOOR OUTER MOULDING RH	NOT NECESSARY	63.60	-
1	REAR DOOR GLASS CHANNEL RH	NOT NECESSARY	92.80	-
1	REAR DOOR RUBBER RH	NOT NECESSARY	77.15	-
1	REAR DOOR LOWER RUBBER RH	NOT NECESSARY	54.40	-
1	REAR DOOR TRIM RH	NOT NECESSARY	424.50	-
1	REAR FENDER RH	DISTORTED	856.90	856.90
1	REAR FENDER COWLING RH	TORN	99.00	99.00
1	REAR FENDER MUDFLAP RH	TORN	71.40	71.40
1	REAR FENDER RH GLASS	NOT NECESSARY	183.60	-
1	REAR FENDER VENTILATION AR COVER RH	NOT NECESSARY	47.20	-
1	REAR FENDER TRIM RH	NOT NECESSARY	224.60	-
1	TAIL LAMP -RH	CRACKED	289.90	289.90
1	TAIL LAMP PANEL -RH	TO REPAIR SEE LABOUR	88.60	-
1	REAR PANEL	TO REPAIR SEE LABOUR	454.60	-
1	REAR AXLE	BENT	1,159.50	1,159.50
1	REAR WHEEL HUB RH	DAMAGED	287.50	287.50
1	REAR SHOCK ABSORBER RH	BENT	247.20	247.20
1	REAR ABS WIRE RH	NOT NECESSARY	81.60	-
1	REAR BUMPER	DISTORTED	492.70	492.70
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	25.70	25.70
1	FRONT SIDE MIRROR RH	DAMAGED	589.70	589.70
1	FRONT SIDE MIRROR OUTER COVER	MISSING	68.30	68.30
	LESS 20% DISCOUNT		-1,412.91	-1,007.36
			5,651.64	4,029.44
<u>SPECIAL NETT ITEMS</u>				
1	REAR DOOR STICKER RH (SN)	NECESSARY	300.00	200.00
1	SET REAR RH FENDER COWLING CLIPS (SN)	NECESSARY	40.00	20.00

Report Ref No. CC6/CTI21000980/Aes3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET REAR FENDER MUDFLAP CLIPS (SN)	NECESSARY	30.00	10.00
1	REAR FENDER RH GRAB STICKER (SN)	NECESSARY	30.00	30.00
1	REAR FENDER RH GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	REAR FENDER RH GLASS SEAL (SN)	NECESSARY	60.00	40.00
1	SET REAR FENDER TRIM CLIPS RH (SN)	NOT NECESSARY	40.00	-
1	REAR SPORTS RIM RH (SN)	CUT	850.00	550.00
1	REAR TYRE RH (SN)	PUNCTURE	300.00	300.00
1	SET REVERSE SENSORS (SN)	DAMAGED	400.00	250.00
1	REAR DOOR SURROUND RUBBER RH (SN)	NECESSARY	150.00	60.00
			2,260.00	1,500.00
	LABOUR			
	TO CHECK WIRING .		50.00	30.00
	TO REMOVE AND REFIT FENDER RH GLASS .		120.00	60.00
	TO REMOVE AND REFIX REAR DOOR FITTINGS.		100.00	80.00
	TO REMOVE AND REFIT SEAT CUSHION .	NOT NECESSARY	240.00	-
	TO REPLACE STICKER .		100.00	50.00
	TO REFIX UPHOLSTERY .		200.00	60.00
	TO REMOVE AND REFIT REVERSE SENSOR .		80.00	50.00
	TO REMOVE AND REFIT UNDERCARRIAGE .		500.00	300.00
	TO CHECK WHEEL ALIGNMENT.		120.00	80.00
	TO SPRAY UNDERSEAL .		100.00	60.00
	(REAR) TO SPRAY PAINTING.		1,300.00	900.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS.INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL -RH AND REAR PANEL .		1,500.00	800.00
			4,410.00	2,470.00
GRAND TOTAL			12,321.64	7,999.44
RECOMMENDED COST OF REPAIRS				7,999.44

Report Ref No. CC6/CTI21000980/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 6833X

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 6833X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 6833X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMN 6833X

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

