

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST: 201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Claim Type: Third Party
 Accident Date: 16/01/2021
 TP Veh Reg No: XE819U

Estimate No: EST2100020
 Date: 18 Jan 2021

Veh Reg No: **SMN6833X**
 Make/Model: HONDA JAZZ 1.3 CVT
 Chasis No: JHMGK3850KS218220
 Reg. Date: 23/08/2019
 Your Ref No: XE819U

Asher.

Estimate Repair Cost to Vehicle No :SMN6833X

Quantity	Description	List Price SS	Amount SS
List Price			
1	1 PC REAR DOOR RH <i>Distal</i>	849.00 ✓	
2	1 PC REAR DOOR LOCK RH <i>new</i>	235.10 +	
3	1 PC REAR DOOR OUTER MOULDING RH <i>new</i>	63.60 +	
4	1 PC REAR DOOR GLASS CHANNEL RH	92.80 +	
5	1 PC REAR DOOR RUBBER RH <i>new</i>	77.15 +	
6	1 PC REAR DOOR LOWER RUBBER RH <i>new</i>	54.40 +	
7	1 PC REAR DOOR TRIM RH <i>new</i>	424.50 +	
8	1 PC REAR FENDER RH <i>Distorted</i>	856.90 ✓	
9	1 PC REAR FENDER COWLING RH <i>new</i>	99.00 ✓	
10	1 PC REAR FENDER MUDFLAP RH <i>new</i>	71.40 ✓	
11	1 PC REAR FENDER RH GLASS <i>new</i>	183.60 +	
12	1 PC REAR FENDER VENTILATION AR COVER RH <i>new</i>	47.20 +	
13	1 PC REAR FENDER TRIM RH <i>new</i>	224.60 +	
14	1 PC TAIL LAMP - RH <i>new</i>	289.90 ✓	
15	1 PC TAIL LAMP PANEL RH <i>new</i>	88.60 +	
16	1 PC REAR PANEL <i>new</i>	454.60 +	
17	1 PC REAR AXLE <i>new</i>	1,159.50 ✓	
18	1 PC REAR WHEEL HUB RH <i>new</i>	287.50 ✓	
19	1 PC REAR SHOCK ABSORBER RH <i>new</i>	247.20 ✓	
20	1 PC REAR ABS WIRE RH <i>new</i>	81.60 +	
21	1 PC REAR BUMPER <i>Distorted</i>	492.70 ✓	
22	1 PC REAR BUMPER SIDE RETAINER RH <i>new</i>	25.70 ✓	
	<i>1pc front side mirror Rtl 589.70</i>	6,406.55	
	<i>1pc " " " outer cover 68.30</i>	1,281.31	5,125.24
	Special Net		
23	1 PC REAR DOOR STICKER RH <i>new</i>	300.00 ✓	
24	1 SET REAR RH FENDER COWLING CLIPS <i>new</i>	40.00 ✓	
25	1 SET REAR FENDER MUDFLAP CLIPS <i>new</i>	30.00 ✓	
26	1 PC REAR FENDER RH GRAB STICKER <i>new</i>	30.00 ✓	

5036.80

+ 029.44

589.70

Missy

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

TEL: 63896111 FAX: 62247175
 ATTN: Motor Claim Department

Claim Type: Third Party
 Accident Date: 16/01/2021
 TP Veh Reg No: XE819U

Estimate No: EST2100020
Date: 18 Jan 2021

Veh Reg No: **SMN6833X**
 Make/Model: HONDA JAZZ 1.3 CVT
 Chasis No: JHMGK3850KS218220
 Reg. Date: 23/08/2019
 Your Ref No: XE819U

Estimate Repair Cost to Vehicle No :SMN6833X

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
27	1 PC REAR FENDER RH GLASS SEALANT <i>3M</i>	60.00 40	
28	1 PC REAR FENDER RH GLASS SEAL	60.00 40	
29	1 SET REAR FENDER TRIM CLIPS RH <i>new</i>	40.00 +	
30	1 PC REAR SPORTS RIM RH <i>lit</i>	850.00 550	
31	1 PC REAR TYRE RH <i>Purchased</i>	300.00 300	
32	1 SET REVERSE SENSORS <i>new</i>	400.00 250	
33	1 PC REAR DOOR SURROUND RUBBER RH <i>new</i>	150.00 60	
		2,260.00	2,260.00
	Labour		
34	1 TO CHECK WIRING	50.00 30	
35	1 TO REMOVE AND REFIT FENDER RH GLASS	120.00 60	
36	1 TO REMOVE AND REFIX REAR DOOR <i>Fittings</i>	100.00 80	
37	1 TO REMOVE AND REFIT SEAT CUSHION <i>new</i>	240.00 +	
38	1 TO REPLACE STICKERS	100.00 50	
39	1 TO REFIX UPHOLSTERY	200.00 60	
40	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 50	
41	1 TO REMOVE AND REFIT UNDERCARRIAGE	500.00 300	
42	1 TO CHECK WHEEL ALIGNMENT	120.00 80	
43	1 TO SPRAY UNDERSEAL <i>2470</i>	100.00 60	
44	1 (REAR) TO SPRAY PAINTING	1,300.00 800	
45	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 800	
		4,410.00	4,410.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department

Estimate No: EST2100020
Date: 18 Jan 2021

Veh Reg No: SMN6833X
Make/Model: HONDA JAZZ 1.3 CVT
Chasis No: JHMGK3850KS218220
Reg. Date: 23/08/2019
Your Ref No: XE819U

Claim Type: Third Party
Accident Date: 16/01/2021
TP Veh Reg No: XE819U

Estimate Repair Cost to Vehicle No :SMN6833X

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
		Total	S\$ 11,795.24
		Add GST @ 7%	825.67
		Total Amount Payable	<u>S\$ 12,620.91</u>

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND SIX HUNDRED TWENTY AND CENTS NINETY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
P/P 19/01/21
0.8 Days

total: 7588.44 (P/P) ✓