

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0069/2021/NS
DATE : 19-Jan-21
WIP : 12208

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

5 days exclude 1 Sunday

jb 16 Mar 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MDM ANG CHU YUN(HONG CHUYUN)
ADDRESS : 10 STIRLING ROAD
#23-07
SINGAPORE 148954
TELEPHONE : HP +65 96709255
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070013391
VEHICLE NO : **SJX 1811 A**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 11/2/2020
ENGINE NO : CVK 086224
CHASSIS NO : WAUZZZF4XKA104808
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Jan-21
PLACE OF ACCIDENT : INTERSECTION OF JURONG WEST ST 93 &
UPPER JURONG ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJX 1811 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	\$ 480.00
2	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECL ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.	S/N \$ 1,200.00	
3	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	\$ 250.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCKC CARRIER AND ALIGN TO PSOTION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,200.00	\$ 500.00
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET.	\$ 2,900.00	\$ 1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
SUB TOTAL LABOUR CHARGES		: \$ 9,322.00	\$ 3,072.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJX 1811 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 1,787.00	\$ 1,429.60
2	FRONT BUMPER FIXING PARTS		\$ 587.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	\$ 28.16
4	FRONT BUMPER GRILLE - CENTRE		\$ 196.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 210.00	\$ 167.60
6	FRONT BUMPER AIR GUIDE - RH		\$ 63.00	\$ 50.08
7	RADIATOR GRILLE		\$ 1,332.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH (Owner)		\$ 804.00	\$ 85.30
9	FRONT BUMPER CARRIER		\$ 845.00	
10	FRONT BUMPER FOAM FILLER PIECE		\$ 124.00	
11	FRONT BUMPER GUIDE SECTION - RH		\$ 38.00	
12	FRONT BUMPER TOP COVER		\$ 127.00	
13	CAUTION SIGN STICKER	NEC	\$ 14.00	
14	AIRCON STICKER	NEC	\$ 8.00	
15	LOCK CARRIER BRACKET		\$ 137.00	
16	LOCK CARRIER BRACKET SUPPORT - LH/RH	2	\$ 58.00	
17	HORTN - RH LOW TONE		\$ 126.00	
18	SPRING SHACKLE - RH		\$ 29.00	
19	FRONT PARKING AID SENSOR-INNER/OUTER	2	\$ 484.00	\$ 193.60
20	FRONT PARKING AID SEAL RING	4	\$ 14.00	
SUB TOTAL SPARE PARTS		:	\$ 7,054.00	\$ 1,954.34

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJX 1811 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 1,954.34
21	FRONT FENDER - RH	\$	767.00	
22	FRONT FENDER ATTACHMENT PARTS	\$	202.00	
23	FRONT FENDER CLOSING ELEMENT - RH	\$	72.00	
24	FRONT FENDER BRACKET - RH	\$	35.00	
25	FRONT FENDER BRACE - RH	\$	118.00	
26	WHEEL HOUSING LINER - RH	\$	241.00	
27	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	233.00	
28	WHEEL SPOILER - RH	\$	73.00	\$ 58.40
29	WHEEL SPOILER TRIM - RH	\$	36.00	\$ 28.56
30	STONE CHIP GUARD - RH	\$	51.00	
31	TOP FENDER LEDGE COVER - UPPER	\$	31.00	
32	TOP FENDER LEDGE COVER - LOWER	\$	23.00	
33	BONNET IMPACT PROTECTION - CENTRE	\$	28.00	
34	BONNET IMPACT PROTECTION - LH	\$	28.00	
35	BONNET IMPACT PROTECTION - RH	\$	28.00	
36	LED HEADLIGHT - RH	\$	7,693.00	\$ 6,154.40
37	LIFT CYLINDER - RH	\$	210.00	
38	LIFT CYLINDER CORRUGATED PIPE	\$	93.00	
39	LOCK CARRIER	\$	1,016.00	
40	COOLANT REGULATOR SUPPORT	\$	38.00	
SUB TOTAL SPARE PARTS		:	\$ 11,016.00	\$ 8,195.70

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJX 1811 A

S/N PARTS DESCRIPTION		QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 8,195.70
41	READY MIX COOLANT		\$ 179.00	
42	RADIATOR AIR GUIDE - OUTER		\$ 28.00	
43	RADIATOR AIR GUIDE - INNER		\$ 12.00	
44	FRONT BUMPER BRCKET - RH		\$ 228.00	
45	PRESSURE HOSE - RH		\$ 357.00	
46	FRONT NO PLATE	S/N	\$ 60.00	
47	SUNDRIES		\$ 300.00	\$ 4.80
TOTAL SPARE PARTS		:	\$ 19,234.00	\$ 8,200.50
TOTAL LABOUR CHARGES		:	\$ 9,322.00	\$ 3,072.00
GRAND TOTAL		:	\$ 28,556.00	\$ 11,272.50

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl=-18/02/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT