# TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGPORE 539186 TEL: 6385 1171 BUS. REG. NO. 53176519M

15th January 2021

Our Ref: CL20083 Your Ref: SHB6235U

India International Insurance Pte Ltd Motor Claims Department
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Dear Sirs.

### ACCIDENT INVOLVING SKV2830L AND SHB6235U ALONG TAMPINES AVE 5 ON 12.09.2020

We are the representative for Lim Ping Guan, whose vehicle registration number SKV2830L was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration SHB6235U. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

 Cost of repairs
 \$4,700.00

 Loss of rental for 04 days @\$128.40
 \$513.60

 Survey fee
 \$568.00

 LTA search fee
 \$7.45

 \$5,789.05

Enclosed are the supporting documents for your perusal:-GIA LTA search Repair bill

Kindly let us have your payment of \$5,789.05 in our workshop's name within the next 14 days.

Please do not hesitate to contact our Ms Tan at 9838 8224 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully

Encl.





No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

21-7068

Date:

8/12/2020

INVOICE NO.

7068

Lim Ping Guan c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Registration No.

SKV2830L

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$568.00
		Total amount	\$568.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

LL. Tan (Ms) Principal Consultant

Subsidiaries of Impact Analysis Consultant:

<sup>•</sup> Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

<sup>●</sup> IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd www.laconsultingsg.com



Our reference:

21-7068

Date:

8/12/2020

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Dear Sirs

RE:

Road Traffic Accident on 12/9/2020

Lim Ping Guan

In accordance with your instructions received in this office or examine the vehicle on

30/11/2020

30/11/2020

, we made arrangements to

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

at above-mentioned address. The following data was

recorded:

#### Vehicle details


Make	Toyota	Registration	SKV2830L
Model	Harrier	Chassis	ZSU600052118
Colour	White	Gearbox	Auto
Odometer	75619km	Paintwork	Good
Steering	Good	Brakes Good	
Condition	Good		

#### Tyre Depths

Front left	235/55R18	85% Michelin	
Front right	235/55R18	85% Michelin	
Rear left	235/55R18	85% Michelin	
Rear right	235/55R18	85% Michelin	

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

### Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,700.00 6 for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
   ◆ Impact Analysis Academy Pte Ltd
   ◆ IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd www.laconsultingsg.com



#06-46 Synergy @KB Singapore 41780

No.25 Kaki Bukit Road 4

Hotline: 6385 1171

Our reference

21-7068

Date

8/12/2020

Page

2

## Section A: Damaged Parts Assessment

Section A: [	Damaged	Parts Assessm	ent	
Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our
List Items:		pasteu	catillate	Adjustment
Rear bumper (orginal)	1	deformed/cut	1024.50	1024.50
Rear end panel	1	repair.respray	758.90	0.00
Rear exhaust pipe	1	rebuild	1425.50	
Rear bumper sponge	1	damaged	112.50	0.00
Rear exhaust pipe headseal @\$185.00	2	grazed	370.00	112.50
	Sub- Total	_	3691.40	370.00 48.3
Percentage		25%	922.85	1507.00
		for parts		376.75
		=	2768.55	1130.25 1061 4
Special Nett Items:				
Rear bumper clips	set	necessary	55.00	FF 00 7 F
Rear bumper lower (bodykit)	1	damaged	677.40	55.00 35
Rear bumper lower lid (bodykit)	1	holder torn	785.00	677.40 400
Rear bumper diffuser (bodykit)	1	damaged		785.00 50C
Reverse sensor	1	malfunction	845.80	845.80 X SVC
Sub-	Total costs		280.00	280.00 200
540	rotal costs	or parts =	2643.20	2643.20
arts Repair				1192
	*			
	Sub- Total c	nete _	0.00	0.00
	Total costs for parts			0.00
700	ur costs jor	parts	5411.75	3773.45

Subsidiaries of Impact Analysis Consultant:

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

<sup>•</sup> IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd www.laconsultingsg.com



Our reference

21-7068

Date

8/12/2020

Page

3

### Section B: Labour Cost Calculation

To dismantle, replace, cut, weld, knock out dents to straighten accident	Hourly rat	e Manhr. Req.		Total	
parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 48.00	14	\$	672.00	
Putty & Spray painting to adjacent panels. Job allowance. Paint / material. (front door, side skirt, bonnet, front bumper / lower lid, front fender)	Sub-co	ntract work.	\$	700.00	
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	50.00	
Remove and rebuild exhaust system	\$ 45.00	2	\$		
Remove and replace rear reverse sensor & conduct distance safety	4 15.00	2	>	90.00	
etting	\$ 48.00	1.7	\$	81.60	
pecialist charges - Dignostic fault code / reset			\$	150.00	
/iring and bulb checking	\$ 48.00	0.5	\$	24.00	
anhour rate and the number of manhours required for each repairing task are	Total la	bour cost	\$ 1	1,767.60	

te and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

3336. F8 20%: 2650 4 Days.

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Subsidiaries of Impact Analysis Consultant:

● Impact Analysis Consulting Pte Ltd ● Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd

● IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd www.iaconsultingsg.com



Our reference

21-7068

Date

8/12/2020

#### Section C: Summary Table of Total Repair Cost

Description  Damaged Parts  Assessment (See section A)		Cost	
		\$3,773.45	
Further discount	20%	\$754.69	
Recommended cost of parts		\$3,018.76	(1)
	t Calculation ection B)	\$1,767.60	(2)
	epair Cost to hundred)	\$4,700.00	(1) + (2)

We would recommend a sum of \$4,700.00 and 6 working days for repair.

No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma. Mechanical Engineering

NTC-2 Automovite Technology

w

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
   Impact Analysis Academy Pte Ltd
   IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd www.laconsultingsg.com

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171