

FREESION AUTODRIVE

BUS. REGN. NO. 53260330C

25 KAKI BUKIT ROAD 4 #03-33 SYNERGY @KB SINGAPORE 417800

TEL: 6702 3533 FAX: 6702 3577

Email: freesionautodrive@gmail.com

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for approval
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #08-16
Singapore 079120

Vehicle Number : SKP1791D
Make / Model : Toyota Prius
Chassis Number : ZVW400009083
Accident Date : 18.01.2021
Reference : FA17506/SKP1791D

THIRD PARTY CLAIM ESTIMATION

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

1	Rear bumper / Lt	\$ 523 977.00
2	Rear bumper brackets @ \$69 X 2	\$ 138.00
1	Rear bumper reflector X	\$ 211.55
1	Rear fender RH X Repair	\$ 1,217.80
1	Rear tyre rim RH X Repair	\$ 1,310.20
1	Rear absorber RH X	\$ 278.10
1	Rear wheel bearing RH X 2	\$ 578.90

392.25

\$ 4,711.55
Less 25% \$ (1,177.89)
Subtotal \$ 3,533.66

PARTS REPLACEMENT- SPECIAL NETT ITEMS

1 set	Rear bumper clips / MC	\$ 30 50.00
1 set	Reverse sensor X NN	\$ 350.00
	Subtotal	\$ 400.00
	Balance C/F	\$ 3,933.66

LABOUR AND MISCELLANEOUS CHARGES

1.	To remove and refit rear undercarriage.	\$ NN 300.00
2.	To remove and refit rear reverse sensor.	\$ 40 120.00
3.	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damage consistent to the accident.	\$ 300 600.00
4.	To respray painting include polishing and waxing on the changed body parts, repair portions where consistent to the accident.	\$ 500 600.00

Subtotal \$ 1,620.00
Grand total \$ 5,553.66

3 Days

part by part

before paint photos
After repair photos

25/1/2021

Chuo Qiq

1262.25