

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0076/2021/NS
DATE : 22-Jan-21
WIP : 12004

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SKU 2868 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR NG SHAO KANG ALOYSIUS
ADDRESS : 112 PUNGGOL WALK
#13-27
SINGAPORE 828766
TELEPHONE : HP +65 96892930
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800045029-02
VEHICLE NO : **SMA 93 Y**
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 30/4/2018
ENGINE NO : CVK 051826
CHASSIS NO : WAUZZZF55JA054195
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Dec-20
PLACE OF ACCIDENT : PUNGGOL WATERWAY POINT CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 93 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER RONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO DISMANILE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	
4	TO RESPRAY REAR BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 5,472.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 93 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,251.00	
2	FRONT BUMPER FIXING PARTS		\$ 407.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 228.00	
5	FRONT BUMPER AIR GUIDE - RH		\$ 63.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 474.00	
7	FRONT BUMPER GUIDE SECTION - RH		\$ 36.00	
8	FRONT PARKING AID SENSOR - OUTER		\$ 242.00	
9	FRONT PARKING AID SEAL RING	4	\$ 14.00	
10	FRONT FENDER - RH		\$ 1,060.00	
11	FRONT FENDER ATTACHMENT PARTS		\$ 53.00	
12	FRONT FENDER CLOSING ELEMENT - RH		\$ 74.00	
13	FRONT FENDER BRACKET - RH		\$ 35.00	
14	FRONT FENDER BRACE - RH		\$ 118.00	
15	WHEEL HOUSING LINER - RH		\$ 275.00	
16	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 169.00	
17	WHEEL SPOILER		\$ 73.00	
18	WHEEL SPOILER TRIM - RH		\$ 36.00	
19	STONE CHIP GUARD - RH		\$ 51.00	
20	FRONT FENDER TRIM - RH		\$ 164.00	
SUB TOTAL SPARE PARTS		:	\$ 5,894.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 93 Y**

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 TOP FENDER LEDGE COVER - UPPER		\$ 36.00	
22 TOP FENDER LEDGE COVER - LOWER		\$ 16.00	
23 LED HEADLIGHT - RH		\$ 7,902.00	
24 LIFT CYLINDER - RH		\$ 198.00	
25 SUNDRIES		\$ 250.00	
TOTAL SPARE PARTS	:	\$ 14,296.00	
TOTAL LABOUR CHARGES	:	\$ 5,472.00	
GRAND TOTAL	:	\$ 19,768.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT