

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0076/2021/NS
DATE : 22-Jan-21
WIP : 12004

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SKU 2868 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

4 days - ok - Jy - 17 Jun 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR NG SHAO KANG ALOYSIUS
ADDRESS : 112 PUNGGOL WALK
#13-27
SINGAPORE 828766
TELEPHONE : HP +65 96892930
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1800045029-02
VEHICLE NO : SMA 93 Y
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 30/04/2018
ENGINE NO : CVK 051826
CHASSIS NO : WAUZZZF55JA054195
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Dec-20
PLACE OF ACCIDENT : PUNGGOL WATERWAY POINT CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 93 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER RONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 500.00
4	TO RESPRAY REAR BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$ 1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,472.00	\$ 2,522.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 93 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 2,251.00	\$ 1,800.80
2	FRONT BUMPER FIXING PARTS		\$ 407.00	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE		\$ 228.00	
5	FRONT BUMPER AIR GUIDE - RH		\$ 63.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH		\$ 474.00	
7	FRONT BUMPER GUIDE SECTION - RH		\$ 36.00	
8	FRONT PARKING AID SENSOR - OUTER		\$ 242.00	
9	FRONT PARKING AID SEAL RING	4	\$ 14.00	
10	FRONT FENDER - RH		\$ 1,060.00	
11	FRONT FENDER ATTACHMENT PARTS		\$ 53.00	
12	FRONT FENDER CLOSING ELEMENT - RH		\$ 74.00	
13	FRONT FENDER BRACKET - RH		\$ 35.00	
14	FRONT FENDER BRACE - RH		\$ 118.00	
15	WHEEL HOUSING LINER - RH		\$ 275.00	
16	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 169.00	
17	WHEEL SPOILER		\$ 73.00	
18	WHEEL SPOILER TRIM - RH		\$ 36.00	
19	STONE CHIP GUARD - RH		\$ 51.00	
20	FRONT FENDER TRIM - RH		\$ 164.00	\$ 130.80
SUB TOTAL SPARE PARTS		:	\$ 5,894.00	\$ 1,931.60

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 93 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
				\$ 1,931.60
21	TOP FENDER LEDGE COVER - UPPER	\$	36.00	
22	TOP FENDER LEDGE COVER - LOWER	\$	16.00	
23	LED HEADLIGHT - RH	\$	7,902.00	\$ 6,321.60
24	LIFT CYLINDER - RH	\$	198.00	
25	SUNDRIES	\$	250.00	
TOTAL SPARE PARTS		:	\$ 14,296.00	\$ 8,253.20
TOTAL LABOUR CHARGES		:	\$ 5,472.00	\$ 2,522.00
GRAND TOTAL		:	\$ 19,768.00	\$ 10,775.20

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED