

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER: 200911678H

20.01.2021

TO:

DIRECTOR

RIAZ QAYYUM LLB HONSI NUS

Our Ref: FBH 9662P (V) EB

:ASSOCIATE:

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS

Your Ref: SJX 1811A

MUHD RIDHWAN ABDUL RAHIM ILLB HONSI LEEDS

78 Shenton Way

IRFAN NASRULHAQ BIN HAMDAN (LLB HONS) SMU

Tower 2 #07-16 Singapore 079120

Attn: Motor Claims Department

AIG Asia Pacific Insurance Pte. Ltd.

BY EMAIL ONLY

## **NOTICE OF ACCIDENT**

Dear Sirs.

We are instructed by our client to *notify* you of a road traffic accident on <u>16 January 2021</u> at about <u>1220</u> hours along <u>Jurong West St 93</u> involving our client's vehicle registration number <u>FBH 9662P</u> and vehicle registration number <u>SJX 1811A</u> driven by you or your authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop ::

**EQUATOR BROTHERHOOD** 

**Address** 

25 KAKI BUKIT ROAD 4 #03-79 SYNERGY @ KB SINGAPORE 417800

Telephone no.

6384 6939/9011 3391 (Wille)

Please let us hear from you by the stipulated time.

**FOR SURVEYOR** 

Please initial here after completion of prerepair inspection. Thank you.

Yours faithfully

Appointed surveyor (Name & signature)

Date & time of inspection

-----CC----Client

