

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : ^M SMP 5243 K
Make : Toyota Noah
Year : 2019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Withheld
1/1/2018 2350h
Resurvey After Paint
4 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear o/s fender	repair photo 1025.00
1 pc	Rear bumper	✓
1 pc	Rear o/s bumper side retainer	✓
1 pc	O/S rocker panel	garnish ✓

R	\$1,850.90	X
material	\$1,550.70	✓
lab	\$103.10	✓
cut/fit	\$755.50	✓
	\$4,260.20	
Less 25 %	\$1,065.05	
	\$3,195.15	

S Nett

1 pc	Rear n/s tyre rim
------	-------------------

Del \$550.00 3 for 2

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$700.00 500

To putty & spray paint rear accident affected portion.

\$800.00 600

Diagnostic check on rear o/s undercarriages and to realign wheel alignment

\$180.00 60

Total \$5,425.15