



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2105159

INV Date 23/07/2021

Reference CC4/LPC21001001/Ubs3q2

Code LPC2

### PROFESSIONAL SERVICE FEE

Vehicle No. PC 2757G  
Insured Veh. YQ 8899K  
Claim No. 20/21/21/VC05/024151  
Policy No. Z20VC05004870  
Accident Date 18/01/2021  
Inspection Date 26/01/2021

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 400.00        |
| <b>Subtotal</b>                | <b>400.00</b> |
| <b>GST (7%)</b>                | <b>28.00</b>  |
| <b>Grand Total</b>             | <b>428.00</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                               |                 |                                                               |  |
|----------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|-----------------|---------------------------------------------------------------|--|
| LONPAC INSURANCE BHD<br>300 BEACH ROAD<br>#17-04/07 THE CONCOURSESINGAPORE 199555                                                      |                                                               |                 | Ref: CC4/LPC21001001/Ubs3q2<br>Date: 23/07/2021<br>Code: LPC2 |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                               |                 |                                                               |  |
| Insured Veh.                                                                                                                           | YQ 8899K                                                      | Veh. Inspected  | PC 2757G                                                      |  |
| Policy No.                                                                                                                             | Z20VC05004870                                                 | Coverage (\$)   | 0.00                                                          |  |
| Claim No.                                                                                                                              | 20/21/21/VC05/024151                                          | Excess (\$)     | 0.00                                                          |  |
| Assign From                                                                                                                            | GERALD                                                        | Assign Date     | 21/01/2021                                                    |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                               |                 |                                                               |  |
| Make & Model                                                                                                                           | TOYOTA HIACE HIGH ROOF COMMUTER (A)                           | c.c             | 2982                                                          |  |
| Engine No.                                                                                                                             | HIDDEN                                                        | Year of Reg.    | 2014                                                          |  |
| Chassis No.                                                                                                                            | JTFST22PX00020415                                             | Colour          | WHITE                                                         |  |
| Odometer                                                                                                                               | 439167 KM                                                     | Steering        | IN ORDER                                                      |  |
| Brakes                                                                                                                                 | IN ORDER                                                      | Modification    | NIL                                                           |  |
| General                                                                                                                                | GOOD                                                          |                 |                                                               |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                               |                 |                                                               |  |
|                                                                                                                                        | Size                                                          | Make            | Balance                                                       |  |
| R/H Front Tyre                                                                                                                         | 195 R15                                                       | YOKOHAMA        | 6 mm                                                          |  |
| L/H Front Tyre                                                                                                                         | 195 R15                                                       | YOKOHAMA        | 6 mm                                                          |  |
| R/H Rear Tyre                                                                                                                          | 195 R15                                                       | YOKOHAMA        | 6 mm                                                          |  |
| L/H Rear Tyre                                                                                                                          | 195 R15                                                       | YOKOHAMA        | 6 mm                                                          |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                               |                 |                                                               |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY.<br>DAMAGES SEE DETAILS.                                           |                                                               |                 |                                                               |  |
| <b>5. General Information</b>                                                                                                          |                                                               |                 |                                                               |  |
| Accident Date                                                                                                                          | 18/01/2021                                                    | Inspection Date | 26/01/2021                                                    |  |
| Survey held at                                                                                                                         | TAN LIM MOTOR PTE LTD<br>NO.1 DEFU LANE 6<br>SINGAPORE 539365 |                 |                                                               |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                               |                 |                                                               |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                               |                 |                                                               |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                               |                 |                                                               |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                               |                 | 4 Working Days                                                |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 2757G

| Qty                                | Description of Parts                                                                                                                                                                                                            | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b><u>REPLACEMENT OF PARTS</u></b> |                                                                                                                                                                                                                                 |                      |                           |                   |
| 1                                  | O/S FRONT DOOR                                                                                                                                                                                                                  | TO REPAIR SEE LABOUR | 1,632.00                  | -                 |
| 1                                  | O/S FRONT PANEL                                                                                                                                                                                                                 | TO REPAIR SEE LABOUR | 2,180.00                  | -                 |
| 1                                  | O/S CENTRE PANEL                                                                                                                                                                                                                | DENTED / BENT        | 1,121.00                  | 1,121.00          |
| 1                                  | O/S REAR PANEL                                                                                                                                                                                                                  | TO REPAIR SEE LABOUR | 1,535.00                  | -                 |
| 1                                  | O/S SIDE MIRROR ASSY                                                                                                                                                                                                            | BROKEN               | 385.70                    | 385.70            |
| 1                                  | O/S FRONT CORNER PANEL                                                                                                                                                                                                          | TO REPAIR SEE LABOUR | 233.90                    | -                 |
|                                    | LESS 25% DISCOUNT                                                                                                                                                                                                               |                      | -1,771.90                 | -376.68           |
|                                    |                                                                                                                                                                                                                                 |                      | 5,315.70                  | 1,130.02          |
| <b><u>SPECIAL NETT ITEMS</u></b>   |                                                                                                                                                                                                                                 |                      |                           |                   |
| 1                                  | O/S SIDE PANEL WINDOW GLASS SEALANT (SN)                                                                                                                                                                                        | NECESSARY            | 80.00                     | 60.00             |
| 1                                  | O/S SIDE PANEL EXCLUSION BUS STICKER (SN)                                                                                                                                                                                       | NECESSARY            | 60.00                     | 40.00             |
|                                    |                                                                                                                                                                                                                                 |                      | 140.00                    | 100.00            |
| <b><u>LABOUR</u></b>               |                                                                                                                                                                                                                                 |                      |                           |                   |
|                                    | TO RUST-PROOFING OF THE AFFECTED AREAS .                                                                                                                                                                                        |                      | 250.00                    | 50.00             |
|                                    | TO REMOVE AND REFIT O/S SIDE MIRROR .                                                                                                                                                                                           | NOT NECESSARY        | 100.00                    | -                 |
|                                    | TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR.}                                                                                                                                         |                      | 250.00                    | 80.00             |
|                                    | TO UPHOLSTERY AND MAKE GOOD REPAIR TO CUSHION SEAT AND SEAT FRAME AND RECLINING MECHANISM.}                                                                                                                                     |                      | 200.00                    | -                 |
|                                    | TO CHECK ELECTIRCAL LIGHTING CONCERNED .                                                                                                                                                                                        |                      | 150.00                    | 20.00             |
|                                    | TO REMOVE AND REFIT O/S SIDE WINDOW GLASS .                                                                                                                                                                                     |                      | 150.00                    | 100.00            |
|                                    | PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME .INCLUSIVE OF THE REPAIR OF O/S FRONT DOOR ,O/S FRONT PANEL ,O/S REAR PANEL AND O/S FRONT CORNER PANEL . |                      | 1,600.00                  | 1,000.00          |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty                                                                  | Description of Parts                               | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------|----------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                      | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION . |           | 1,200.00                  | 800.00            |
|                                                                      |                                                    |           | 3,900.00                  | 2,050.00          |
| GRAND TOTAL                                                          |                                                    |           | 9,355.70                  | 3,280.02          |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |                                                    |           |                           | 2,600.00          |

Report Ref No. CC4/LPC21001001/Ubs3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## PHOTOGRAPHS FOR VEHICLE NO. PC 2757G

## INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. PC 2757G

### RE-INSPECTION

