

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001003/EVD3E2

Date: 26/02/2021

REFERENCE

Insured/Claimant:	KARTHIGESAN S/O MURUKAN	Policy No:	1800096051	
Date of Loss:	19/01/2021	Nature of Claim:	OD	Claim No: 5625851745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD2779Z	Engine No:	G4FGJH703968
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5013597
Reg. Date:	13/08/2018 (Man. Year: 2018)	Odometer:	24495 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$75,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,877.60	1,116.00	2,761.60	71.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,090.00	1,020.00	48.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,987.60	2,206.00	3,781.60	63.16
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	5,687.60	1,906.00	3,781.60	66.49
+ GST 7.00/7.00% (S\$)	398.13	133.42	264.71	66.49
Nett Amount (S\$)	6,085.73	2,039.42	4,046.31	66.49

INSPECTION

Date of Assignment:	21/01/2021	
Date Inspected:	26/01/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER	Cut	633.00 FL	*633.00 FL
3	1		*GRILLE-FRONT BUMPER	Broken	485.00 FL	*485.00 FL
4	1		*COVER-FR BUMPER FOG LAMP, LH	Not Necessary	15.00 FL	*- FL
5	1		*LAMP ASSY-FRONT FOG, LH	Not Necessary	303.00 FL	*- FL
6	1		*MOULDING-FRONT BUMPER, LH	Cut	43.00 FL	*43.00 FL
7	1		*LAMP ASSY-SIDE REPEATER, LH	Cut	143.00 FL	*143.00 FL
8	1		*AIR DUCT-FR BUMPER, LH	Broken	14.00 FL	*14.00 FL
9	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
10	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
11	1		*BBRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
12	1		*WIRING ASSY-BUMPER EXTENSION	Not Necessary	207.00 FL	*- FL
13	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
14	1		*LAMP ASSY-HEAD, LH	Not Necessary	2,210.00 FL	*- FL
15	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
16	10		*CLIPS	Necessary	20.00 FL	*20.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,842.00	1,390.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	964.40	274.00
Total Parts (\$\$)	3,877.60	1,116.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER. REPAIR LHF FENDER	New	1,200.00	400.00
2	RESPRAY FRT BUMPER & LHF FENDER	New	700.00	480.00
3	CHECK WIRING ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
5	REMOVE & REFIT FRT PARKING ASSIST SENSOR	New	60.00	60.00
Gross Labour Cost (\$\$)			2,110.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >