

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel :8112 0307 Fax: 6481 5727 e-mail : ngsmotorsportpteltd@gmail.com

Reg No: 201812604N

SINGAPORE ACCIDENT STATEMENT

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attn: Motor Claims Dept

Dear Sir,

RE: ACCIDENT ON 13/01/2021, INVOLVING VEH NO.: SGM9007X & XD3677Y

CLAIMS AGAINST XD3677Y (Lonpac)

YOUR CLAIM REF: 20/21/21/VC05/024143

We submit herewith our direct claim estimate quotation as follow:-

Replacement parts - Toyota Altis

- 1 Rear Bumper
- 1 Retainer, Side RH
- 1 Panel, Rear Side RH
- 1 Fender, Rear RH
- 1 Taillamp RH
- 1 Taillamp Gasket RH
- 1 Garnish, Taillamp Lower Panel RH

Bulb	\$	326.44	✓
Oil	\$	18.32	✓
R1	\$	39.28	✓
R2	\$	749.15	✓
mgem	\$	279.02	✓
\$m	\$	31.58	✓
\$m	\$	74.90	✓
	\$	1,518.69	
Less 25%	\$	(379.67)	
	\$	1,139.02	

- 4 18 Clips, Taillamp RH
- 1 Sealant

S.Net

S.Net

\$	5.00	\$	50.00	2012
\$		\$	60.00	4012

To remove all damaged parts with all necessary component/attachment straighten chassis member, cut & weld panel, repair/reshape dented body panel, replace damaged parts, refit into position

\$ 1,200.00 65d

To remove & replace rear winscreen

\$ 250.00 12d

To spray painting

\$ 800.00 68d

Check Wiring/proper function on lights and etc.

\$ 50.00 2d
\$ 2,449.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Any other parts which necessitate repair or renewal will incur additional charged.

Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully,

NGS MOTORSPORT PTE LTD

EVELYN NG 2111K0001