

ASS. REC. BY:

REF:

AIG/ 21001018/Kb

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

1. B. / %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HO 98 280

Yr Regn:

07. 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Privs

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

41750

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31F4 903091234

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F: Dun

195/65R15

R: Pirella

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

9

mm

L/Bal.

6

mm

L/Bal.

9

mm

D.O.A.

17/1/21

D.O.I.

19/1/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Fr body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

25/10 @ 3592.90

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Fines

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9828D**AAD2101-081***Not Authorised**Recovery B4 paint
83592.90*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

19 JAN 2021**SHD9828D**

JTDKB3FU903091234

TOYOTA

PRIUS GEN 4

17/01/2021

AIG

22/07/2020

	PART
1	COVER, FRONT BUMPER
1	BRACKET, FRONT BUMPER SIDE, RH
1	SUPPORT, FRONT BUMPER SIDE, RH
1	LINER, FRONT FENDER, RH
1	FENDER SUB-ASSY, FRONT RH
1	EMBLEM, SIDE PANEL, RH
1	MIRROR ASSY, OUTER REAR VIEW, RH
1	PANEL SUB-ASSY, FRONT DOOR, RH
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH
1	WEATHERSTRIP, FRONT DOOR, RH
1	HINGE ASSY, FRONT DOOR, LOWER RH
1	HINGE ASSY, FRONT DOOR, UPPER RH
1	TAPE, BLACK OUT, NO.1 FRT RH
1	TAPE, BLACK OUT, NO.2 FRT RH
1	TAPE, BLACK OUT, NO.3 FRT RH
1	MOULDING ASSY, BODY ROCKER PANEL, RH

	LIST
\$	<i>Bu</i> 521.00 ✓
\$	<i>Rh</i> 59.30 X
\$	<i>Rh</i> 80.10 X
\$	<i>Rh</i> 202.50 X
\$	<i>Rh</i> 977.80 ✓
\$	<i>Rh</i> 54.60 ✓
\$	<i>Rh</i> 1,436.60 X
\$	<i>Rh</i> 1,300.70 ✓
\$	<i>Rh</i> 238.30 X
\$	<i>Rh</i> 926.00 X
\$	<i>Rh</i> 231.30 X
\$	<i>Rh</i> 110.60 X
\$	<i>Rh</i> 97.50 X
\$	<i>Rh</i> 13.30 ✓
\$	<i>Rh</i> 43.50 ✓
\$	<i>Rh</i> 26.30 ✓
\$	<i>Rh</i> 594.80 X
TOTAL	\$ 6,914.20
25%	\$ 2,828.00
	\$ 8,484.00

Special Nett

1	FRT BUMPER CLIP
1SET	FRONT FENDER CLIP
1SET	FRONT FENDER LINER CLIP
1SET	FRONT BUMPER CLIP
1	TYRE
1	RIM

\$	<i>Rh</i> 65.00 <i>506</i> ✓
\$	<i>Rh</i> 65.00 X
\$	<i>Rh</i> 75.00 X
\$	<i>Repair</i> 90.00 X
\$	<i>Rh</i> 350.00 X
\$	<i>Rh</i> 1,879.40 X

Trans-cab Auto Services Pte Ltd

AAD2101-081

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9828D

TOTAL	\$	2,459.40
--------------	-----------	-----------------

TOTAL PARTS	\$	9,530.50
--------------------	-----------	-----------------

LABOUR

Panel Beating, Knocking And Straightening The Necessary Portion,
Remove And Renewal Of Parts, Adjust And Realign The Same
To remove and refit interior fittings, trimmings, garnish, fittings and
other, to enable repair.

\$	1,600.00	500/
----	----------	------

\$	nn 380.00	X
----	-----------	---

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	240.00	60/
----	--------	-----

To check steering geometry and computer wheel alignment

\$	220.00	60/
----	--------	-----

Putty And Spray Painting Of The Affected Portion.

\$	1,600.00	700/
----	----------	------

To transfer of tire, rim and on wheel balancing.

\$	nn 170.00	X
----	-----------	---

To Check Electrical Lighting Concerned.

\$	170.00	20/
----	--------	-----

TOTAL	\$	4,380.00
--------------	-----------	-----------------

Over All Total	\$	15,323.40
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days~~10 days~~

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: