

Surveyor : STEVE LKK
 Claim : AIG OD
 DOA : 20.01.2021
 Emailed : 18.02.2021, 11.15am
 Date Survey : 21.01.2021

VEHICLE NO : SMW 1645 H
 MODEL : MIT SPACE STAR 1.2
 WIP : 62141

Material	:	\$	<u>1,258.95</u>
Labour	:	\$	<u>3,260.00</u>
Sub-Total	:	\$	<u>4,518.95</u>
	:	\$	<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>4,518.95</u>
GST 7%	:	\$	<u>316.33</u>
Grand Total	:	\$	<u>4,835.28</u>
Finalise By/Date	:	<u>LOI / 18/02/2021</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 22/01/2021	<table> <tr> <td>Cust No/Name</td><td>/Ms TEO</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMW1645H / 05/11/2020</td></tr> <tr> <td>Date In/Mileage</td><td>21/01/2021/ 1955</td></tr> <tr> <td>Chassis/Package</td><td>MMBXTA03AMH000289 /#</td></tr> <tr> <td>Engine No</td><td>3A92UJX0529</td></tr> <tr> <td>Make/Model</td><td>MIT/21MY SPACE STAR 1.2 CVT (E12)</td></tr> <tr> <td>Colour/Trim</td><td>P57 WINE RED PEARL / BK BLACK</td></tr> </table>	Cust No/Name	/Ms TEO	Reg No/Reg Date	SMW1645H / 05/11/2020	Date In/Mileage	21/01/2021/ 1955	Chassis/Package	MMBXTA03AMH000289 /#	Engine No	3A92UJX0529	Make/Model	MIT/21MY SPACE STAR 1.2 CVT (E12)	Colour/Trim	P57 WINE RED PEARL / BK BLACK
Cust No/Name	/Ms TEO														
Reg No/Reg Date	SMW1645H / 05/11/2020														
Date In/Mileage	21/01/2021/ 1955														
Chassis/Package	MMBXTA03AMH000289 /#														
Engine No	3A92UJX0529														
Make/Model	MIT/21MY SPACE STAR 1.2 CVT (E12)														
Colour/Trim	P57 WINE RED PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	18/02/2021/ 09:24	BLK	260 / AiTing	62141			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER , TAILGATE, REPAIR REAR END PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME (\$900 + \$450)								✓ 1350.00
E PNT98000 RESPRAY ON REAR BUMPER, TAILGATE, REAR END PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME (\$700 + \$350)								✓ 1050.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								✓ 120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENTS TO FACILITATE REPAIR								? 120.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR								✓ 240.00
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT								✓ 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUPPLY C & C EMBLEM								✓ 40.00
M SUNDRY SUNDRIES								✓ 20.00
S SPECIALISTJOB SUPPLY & REPLACE REAR LICENSE PLATE WITH FRAME								✓ 50.00
M SUNDRY SUPPLY MIVEC EMBLEM								✓ 40.00
X	PANEL ASSY, TAILGATE				1.00	✓ 724.00	23.00	557.48
X	STOPPER, WINDSHIELD GLASS				2.00	✓ 3.00	23.00	4.62
X	MARK, THREE-DIA				1.00	✓ 69.00	23.00	53.13
X	FACE, RR BUMPER				1.00	602.00	23.00	463.54
X	BRACKET, RR BUMPER				2.00	68.00	23.00	104.72
X	SPACER, TAILGATE				2.00	✓ 8.00	23.00	12.32
X	MARK, SPACESTAR				1.00	✓ 82.00	23.00	63.14





Exceptional Journeys


INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.: **SMW 1645 H**

<u>Materials</u>		<u>Cost (\$)</u>	
1	Face, RR bumper		602.00 / DD
2	Bracket, RR bumper x2	136	68.00 / BT
Total			670.00 738.00
Less 23% discount			154.10
Total after discount			515.90 568.26
7% GST			39.11
Grand total			<u>\$ 592.01</u> 608.04

Thank You.

Yours faithfully


LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240