



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Co Reg No : 197701469G

### ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Ms TEO
	Reg No/Reg Date	SMW1645H / 05/11/202
	Date In/Mileage	21/01/2021/ 0
	Chassis No	MMBXTA03AMH000289
	Engine No	3A92UJX0529
	Make/Model	MIT/21MY SPACE STAR 1.2 CVT (E12)
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	21/01/2021/ 11:53	QUK	282 / Kevin Leong	62141			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1800.00
REPALCE REAR BUMPER, TAILGATE, END PANEL & AFFECTED AREA								
E PNT98000								1050.00
PAINT WORK ON REAR BUMPER, TAILGATE & END PANEL								
E PNT88000								120.00
REMOVE & INSTALL REAR PARKING ASSIST								
E PNT88000								120.00
REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								
M SUNDRY								80.00
TO APPLY BODY SEALANT								
M SUNDRY								40.00
PERFORM RUST PREVENTION								
E PNT88000								240.00
REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR								
M SUNDRY								80.00
TO APPLY WINDSCREEN SEALANT								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								50.00
TO SUPPLY REAR NUMBER PLATE WITH FRAME								
M SUNDRY								40.00
TO SUPPLY C & C EMBLEM								
M SUNDRY								40.00
TO SUPPLY 'MIVIC' EMBLEM								
M SUNDRY								50.00
SUNDRIES								
M	PANEL ASSY, TAILGATE	1.00	724.00	23.00				557.48
M	W/STRIP, TAILGATE OPENING	1.00	164.00	23.00				126.28
M	GLASS, TAILGATE WINDOW	1.00	843.00	23.00				649.11
M	STOPPER, WINDSHIELD GLASS	2.00	3.00	23.00				4.62

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Ms TEO
	Reg No/Reg Date	SMW1645H / 05/11/202
	Date In/Mileage	21/01/2021/ 0
	Chassis No	MMBXTA03AMH000289
	Engine No	3A92UJX0529
	Make/Model	MIT/21MY SPACE STAR 1.2 CVT (E12)
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	21/01/2021/ 11:53	QUK	282 / Kevin Leong	62141

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M SPACER, TAILGATE	2.00	8.00	23.00	12.32
M MARK, THREE-DIA	1.00	69.00	23.00	53.13
M MARK, SPACE STAR	1.00	82.00	23.00	63.14
M MARK, THREE-DIA	1.00	69.00	23.00	53.13

# Estimate

Confirm &amp; accepted by

7% GST on	Nett 5379.21	5,379.21 376.54
Total Payable		5,755.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.