



*Not Authorized
L1 Day & 3800k
Penny After Paint*

ESTIMATE

Vehicle : SJG3972U

NISSAN LATIO

YEAR: 2008

Chassis No.: JN1BAAC11Z0009647

Qty	Parts/ Labour	Cond	Part\$	
1	Bonnet	R	\$ 863.00	X
1	Bonnet lower lock	DT	\$ 79.00	✓
2	Bonnet hinges	R	\$ 44.00	X
1	Bonnet insulator	Sn	\$ 178.00	X
1	Bonnet insulator clips (set)	na	\$ 50.00	X
2	Bonnet inner rubber seals	Sn	\$ 56.00	X
1	Front bumper	R	\$ 456.00	✓
1	Front bumper logo	na	\$ 63.00	✓
1	Front bumper clips (set)	na	\$ 50.00	✓
2	Front bumper side retainers	M/DI	\$ 46.00	✓
1	Front bumper tow cover	Sn	\$ 28.00	X
1	Front bumper lower grille	DT	\$ 105.00	✓
1	Front bumper lower garnish	Sn	\$ 93.00	X
2	Front lh & rh bumper fog lamp garnish	Sn	\$ 192.00	✓
1	Front bumper reinforcement	R	\$ 446.00	✓
1	Front bumper sponge 207-20	CM	\$ 215.00	✓
1	Lh headlamp	mg CM	\$ 372.00	✓
1	Rh headlamp	mg CM	\$ 372.00	✓
2	Front grille	mg CM	\$ 268.00	✓
1	Front grille clips (set)	na	\$ 30.00	✓
2	Front horn	Sn	\$ 156.00	X
1	Front support top panel	R	\$ 311.00	X
1	Front support panel assy	R	\$ 523.00	X
1	Front support panel top garnish cover	Sn	\$ 72.00	X
1	Front support panel top garnish cover clips (set)	na	\$ 30.00	X
1	Front lh support panel side garnish	Sn	\$ 26.00	X
1	Front rh support panel side garnish	Sn	\$ 26.00	X
1	Front lh fender	R	\$ 623.00	X
1	Front rh fender	R	\$ 623.00	X
1	Front lh fender inner shield	Sn	\$ 77.00	X
1	Front lh fender inner shield clips (set)	na	\$ 50.00	X
1	Aircon condenser 675-90	BT 1P	\$ 736.00	✓
1	Aircon condenser discharge pipe	Sn	\$ 135.00	X
1	Aircon condenser suction hose	Sn	\$ 299.00	X
1	Radiator assy 896	R	\$ 936.00	✓
1	Radiator top hose	na	\$ 56.00	X

1	Radiator bottom hose			
1	Radiator spare tank	1/2	\$	59.00 X
1	Manifold cover	1/2	\$	87.00 X
1	Front washer tank	1/2	\$	135.00 X
1	Front ruse box assy	1/2	\$	115.00 X
1	Front air cleaner box assy	1/2	\$	295.00 X
1	Front air cleaner air duct	1/2	\$	278.00 X
1	Alternator assy	1/2	\$	142.00 X
			\$	850.00 X
			\$	10,646.00
		Less 10%	\$	1,064.60
			\$	9,581.40
	Special Nett			
1	Front number plate w/casing	nd	\$	35.00 ✓
1	Radiator coolant	nd	\$	60.00 30ln
1	Battery	1/2	\$	180.00 X
	To check wiring.		\$	80.00 20h
	To remove & refit aircon condenser & refill aircon gas.		\$	150.00 100l
	Repair wire harness.	nn	\$	300.00 X
	Labour charges.		\$	1,800.00 500h
	Spray painting.		\$	1,500.00 600l
			\$	13,686.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: