



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

29/12/2020

Justin.

ESTIMATED REPAIR CHECKLIST

TO : CHINA INSURANCE	VEHICLE REGISTRATION NO.: FBL2901A
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL: HONDA / CB400X
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER: JH2NC479EK000407
ACCIDENT DATE/TIME :	CONTACT PERSON : NIGEL (97253727)

PARTS	QTY	PER UNIT	PRICES
1 REAR FENDER <i>Rehd</i>	1	\$ 65.00	\$ 65.00
2 REAR FENDR REFLECTOR <i>new</i>	1	\$ 20.00	\$ 20.00
3 REAR SIGNAL LAMP <i>LH could</i>	2	\$ 95.00	\$ 190.00
4 REAR EXHAUST PIPE <i>Rehd</i>	1	\$ 760.00	\$ 760.00
5 REAR EXHAUST PIPE PROTECTOR <i>Rehd</i>	1	\$ 85.00	\$ 85.00
6 REAR RH FOOTREST <i>new</i>	1	\$ 45.00	\$ 45.00
7 FRONT RH FOOTREST <i>ut</i>	1	\$ 65.00	\$ 65.00
8 FRONT RH ENGINE COVER <i>cut</i>	1	\$ 405.00	\$ 405.00
9 FRONT RH LOWER COVER <i>Rehd</i>	1	\$ 55.00	\$ 55.00
10 FRONT RH TOP CRASH BAR <i>Best</i>	1	\$ 220.00	\$ 220.00
11 BALANCER RH <i>ut</i>	1	\$ 45.00	\$ 45.00
12 HANDLE BAR <i>new</i>	1	\$ 235.00	\$ 235.00
13 CLUTCH LEVER <i>could</i>	1	\$ 45.00	\$ 45.00
14 FRONT RH WING MIRROR <i>cut</i>	1	\$ 85.00	\$ 85.00
15 FRONT FENDER <i>Repair</i>	1	\$ 225.00	\$ 225.00
16 FRONT FORK <i>LH Best</i>	2	\$ 800.00	\$ 1,600.00
17 FRONT FORK UNDER BRACKET <i>new</i>	1	\$ 285.00	\$ 285.00
18 STEERING STEM <i>Rehd</i>	1	\$ 160.00	\$ 160.00
19 FRONT RH SIGNAL LAMP <i>could</i>	1	\$ 95.00	\$ 95.00
20 FRONT BRAKE DISC <i>new</i>	1	\$ 260.00	\$ 260.00
21 HEADLAMP <i>new</i>	1	\$ 275.00	\$ 275.00
22 HEADLAMP COWLING <i>new</i>	1	\$ 240.00	\$ 240.00
23 FRONT RH FAIRING <i>could</i>	1	\$ 305.00	\$ 305.00
		SUBTOTAL :	\$ 5,490.00
		LESS 10% :	\$ 549.00
		PARTS TOTAL :	\$ 4,941.00

3380

3042

SPECIAL NETT	QTY	PER UNIT	PRICES
1 REAR NUMBER PLATE <i>Best.</i>	1	\$ 20.00	\$ 20.00
2 REAR BOX <i>ut</i>	1	\$ 350.00	\$ 350.00
3 FRONT FORK OIL <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4 FRONT FORK OIL SEAL <i>new</i>	1 SET	\$ 30.00	\$ 30.00
5 STEERING CONE & BEARING <i>Rehd</i>	1 SET	\$ 60.00	\$ 60.00
6 HONDA STICKER <i>new</i>	1	\$ 20.00	\$ 20.00
		S/N TOTAL :	\$ 510.00

360



Polymath garage

Polymath Garage Pte Ltd

10 Kaki Bukit Road 2 #01-21

First East Centre, Singapore 417868

24 Hour: +65 8228 9818

Phone: +65 6871 8861 | Fax: +65 6871 8814

Email: enquiry@polymathgarage.com.sg

UEN: 201605123Z

LABOUR CHARGES	PRICES	ADJUSTMENT
1 LABOUR	\$ 400.00	200
2 SPRAY PAINTING	\$ 400.00	200
3 WIRING	\$ 50.00	30
4 TO STRAIGHTEN BODY CHASSIS	\$ 250.00	x
5 TOWING FEES	\$ 40.00	✓
LABOR TOTAL :		\$ 1,140.00

470.

ESTIMATE REPORT	
TOTAL PARTS COST:	\$ 5,451.00
TOTAL LABOUR COST:	\$ 1,140.00
TOTAL REPAIR COST:	\$ 6,591.00
PART BY PART / LUMP SUM:	
NO. OF REPAIR DAYS:	

SURVEYOR DETAILS	
SURVEYOR NAME:	
CONTACT:	
EMAIL:	
DATE :	
TIME :	

total: 3872

h/s: 3K.

04 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____