

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	NTUC INCOME IN:	SURANCE CO-OPERATIVE LTD		Ref:	CS3/INC19012166/T1qd3e2-1	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE		Date:	09/03/2021	
	ATTN: AZHARI			Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKM 1972P	Veh. Inspected		FBL 7115U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1033901-001/CH	Excess (\$)		0.00	
	Assign From	ANNA YEO	Assign Date		21/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA WW150	c.c		153	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	RLHKF18A8HY101424	Colour		WHITE	
	Odometer	50077 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	100/80 R14	PIRELLI		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	110/80 R14	PIRELLI		5 mm	
	L/H Rear Tyre				mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/02/2019	Inspection Date	е	09/07/2019	
	Survey held at TUCK LIFE PTE LTD					
	25 KAKI BUKIT ROAD 4# 01-68 SYNERGY@ KB SINGAPORE 417800					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					