

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMC1066J/2101004

22th January 2021

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

Not Authorized
22/1/20
The above is for
7/2/20
8 days

Date of Accident : 21th January 2021
Location : Junction of Sin Ming Rd & Upper Thomson Rd
Third Party Claim Vehicle No : SBG 8804 J
Repair Cost For Vehicle No : SMC 1066 J Honda Fit

Estimate Cost Plus/ Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts	
1	Rear door assy RH <i>Body</i>	1	799.50	\$ 799.50	✓
2	Rear door hinge (top) RH	1	48.60	\$ 48.60	✓
3	Rear door hinge (bottom) RH	1	48.60	\$ 48.60	?
4	Rear door sticker <i>new</i>	1	26.00	\$ 26.00	✓
5	Rear door weather strip RH (front) <i>7011</i>	1	43.90	\$ 43.90	✓
6	Rear door weather strip RH (lower) <i>7M</i>	1	17.80	\$ 17.80	✓
7	Rear door weather strip RH (rear) <i>11</i>	1	19.50	\$ 19.50	X
8	Rear door power window motor RH	1	156.40	\$ 156.40	✓
9	Rear door lock	1	172.00	\$ 172.00	?
10	Rear door outer frame moulding RH <i>111</i>	1	32.70	\$ 32.70	X
11	Front door assy RH <i>11</i>	1	757.20	\$ 757.20	✓
12	Front door weather strip RH (front) <i>11</i>	1	14.30	\$ 14.30	X
13	Front door weather strip RH (lower) <i>11</i>	1	18.50	\$ 18.50	X
14	Front door lock rubber RH <i>11</i>	1	14.50	\$ 14.50	X
15	Front door sticker (1set) <i>new</i>	1	35.80	\$ 35.80	✓
16	Front door outer frame moulding RH <i>11</i>	1	75.60	\$ 75.60	X
17	Rear fender RH	1	559.30	\$ 559.30	?
18	Rear fender quarter glass RH <i>11</i>	1	280.00	\$ 280.00	X
19	Running board panel RH <i>Body</i>	1	260.00	\$ 260.00	✓
20	Centre door pillar RH <i>new</i>	1	724.00	\$ 724.00	X
21	Front engine dust cover <i>7011</i>	1	237.00	\$ 237.00	✓
22	Front bumper fascia <i>cut/de</i>	1	517.70	\$ 517.70	✓
23	Front bumper clips <i>new</i>	1set	28.00	\$ 28.00	✓
24	Front wheel hub cap LH	1	160.00	\$ 160.00	?
				\$ 5,046.90	

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Damaged part(s) during resurvey are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM/SMC1066J/2101004

22th January 2021

No.	Particulars	Qty	Price	Amounts
	Balance b/f			\$ 5,046.90
25	Front shock absorber L&R	2	298.00	\$ 596.00 ?
26	Front knuckle arm L&R	2	245.00	\$ 490.00 ?
27	Front wheel bearing L&R	2	168.00	\$ 336.00 ?
28	Front lower arm L&R	2	181.00	\$ 362.00 ?
29	Steering rack & pinion assy <i>su</i>	1	1,600.00	\$ 1,600.00 X
30	Rear fender quarter sealant (s/nett) <i>11</i>	1	40.00	\$ 40.00 X
31	Front wheel rim LH(s/nett)	1	350.00	\$ 350.00 ?
32	Front wheel tyre LH(s/nett)	1	380.00	\$ 380.00 ?
				\$ 9,200.90

Labour Charges :-

Towing fee

3.11 Amounts
\$ 180.00 ?

Cut out, renew, knocking & welding front & rear door assy RH, rear RH fender RH, running board panel RH, centre pillar RH, remove & install all damage parts, straighten & re-align body

\$ 2,280.00 *1100*

Remove & install front & rear door board, glass, lock & etc

\$ 220.00 *120*

Remove & install rear quarter glass

11 \$ 80.00 ?

Remove & install rear seats, carpets, upholstery & etc

\$ 280.00 *100*

Remove & install undercarriage to facilitate repairs

\$ 220.00 ✓

Tuff-kote on damage parts

\$ 160.00 *100*

Spray painting on damage parts

\$ 2,700.00 *1200*

Check door wiring after repairs

\$ 50.00 *20*

Computerize wheel alignment

\$ 120.00 *80*

Labour Charge

\$ 6,290.00

Total Amount

\$15,490.90

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.