

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21001030/EVF3Q2

Date: 19/02/2021

REFERENCE

Insured/Claimant:	LINUS LOO KAH MENG	Policy No:	2070128113	
Date of Loss:	11/01/2021	Nature of Claim:	OD	Claim No: 5763119401SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU9028Y		
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Engine No:	4J11CL0583
Reg. Date:	03/09/2020 (Man. Year: 2020)	Chassis No:	GF7W0700518
Colour:	White	Odometer:	6214 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$102,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R18	Rear Tyre Size:	225/55R18
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,840.00	1,834.08	4,005.92	68.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,970.00	2,190.00	3,780.00	63.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,810.00	4,024.08	7,785.92	65.93
+ GST 7.00/7.00% (S\$)	826.70	281.69	545.01	65.93
Nett Amount (S\$)	12,636.70	4,305.77	8,330.93	65.93

INSPECTION

Date of Assignment: 21/01/2021

Date Inspected: 26/01/2021 Inspected At:

Cycle & Carriage Automotive Pte Ltd
(Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRKT,R/BMPR FACE SIDE,LH	Not Necessary	12.00 F	*- FL
2	1		*BRKT,R/BMPR FACE SIDE,RH	Not Necessary	12.00 F	*- FL
3	1		*FACE,RR BUMPER	Dented	807.00 F	*807.00 FL
4	1		*EXTENSION,RR BUMPER	Cut	292.00 F	*292.00 FL
5	1		*PANEL,RR END	Not Necessary	324.00 F	*- FL
6	1		*W/STRIP,TAILGATE OPENING	Not Necessary	213.00 F	*- FL
7	1		*PANEL ASSY,TAILGATE	Dented	984.00 F	*984.00 FL
8	1		*GARNISH,TAILGATE	Not Necessary	494.00 F	*- FL
9	1		*DAM,TAILGATE,LWR	Necessary	41.00 F	*41.00 FL
10	2		*STOPPER,WINDSHIELD GLASS	Necessary	6.00 F	*6.00 FL
11	2		*DAM,TAILGATE SIDE	Necessary	54.00 F	*54.00 FL
12	1		*DAM,TAILGATE,UPR	Necessary	13.00 F	*13.00 FL
13	2		*FASTENER,WINDSHIELD	Necessary	12.00 F	*12.00 FL
14	1		*GLASS,TAILGATE WINDOW	Not Necessary	654.00 F	*- FL
15	1		*MARK,OUTLANDER	Necessary	95.00 F	*95.00 FL
16	1		*TRIM,RR END	Not Necessary	113.00 FS	*- FS
17	1		*BODY KIT,OUTLANDER	Not Necessary	1,554.00 FS	*- FS
18	1		*C&C EMBLEM	Necessary	60.00 FS	*40.00 FS
19	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
20	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,840.00	2,364.00
- List Item Discount on L Items 0.00/23.00% (\$)	0.00	529.92
Total Parts (\$)	5,840.00	1,834.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, TAILGATE & AFFECTED AREA. REPAIR ON REAR END PANEL	New	2,560.00	900.00
2	PAINT WORK ON REAR BUMPER, TAILGATE & END PANEL	New	2,200.00	700.00
3	REMOVE & INSTALL REAR PARKING ASSIST	New	150.00	120.00
4	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR *Check	New	180.00	0.00
5	TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL *Check	New	160.00	0.00
6	REPLACE REAR WINDSCREEN GLASS	New	240.00	240.00
7	TO APPLY WINDSCREEN SEALANT	New	80.00	80.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	120.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	280.00	120.00
Gross Labour Cost (\$\$)			5,970.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >