



CYCLE & CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



MITSUBISHI  
MOTORS

Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LINUS LOO KAH MENG	Cust No/Name KCV15963/LINUS LOO KAH MENG
2 PANDAN VALLEY	Reg No/Reg Date SMU9028Y / 03/09/202
#03-209	Date In/Mileage / 0
SINGAPORE 597626	Chassis No GF7W0700518
Contact No Mobile: 92984208	Engine No 4J11CLO583
	Make/Model MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	19/01/2021/ 09:55	QUK	282 / Kevin Leong	61971			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	REPLACE REAR BUMPER, TAILGATE & AFFECTED AREA	450 X 2			900			2560.00
	REPAIR ON REAR END PANEL				700			2200.00
E PNT98000	PAINT WORK ON REAR BUMPER, TAILGATE & END PANEL	350 X 1			120			150.00
E PNT88000	REMOVE & INSTALL REAR PARKING ASSIST				1			180.00 X
E PNT88000	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR				1			160.00 X
E PNT88000	TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL							240.00
E PNT88000	REPLACE REAR WINDSCREEN GLASS							80.00
M SUNDRY	TO APPLY WINDSCREEN SEALANT				30			120.00
A 54900099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120			280.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				40			60.00
M SUNDRY	TO SUPPLY C & C EMBLEM							50.00
M SUNDRY	TO SUPPLY REAR NUMBER PLATE WITH FRAME				20			50.00
M SUNDRY	SUNDRIES				1.00	12.00	00.00	12.00
M BRKT,R/BMPR FACE SIDE,LH					1.00	12.00	00.00	12.00
M BRKT,R/BMPR FACE SIDE,RH					1.00	807.00	00.00	807.00
M FACE,RR BUMPER					1.00	292.00	00.00	292.00
M EXTENSION,RR BUMPER					1.00	324.00	00.00	324.00
M PANEL,RR END					1.00	213.00	00.00	213.00
M W/STRIP,TAILGATE OPENING					1.00	984.00	00.00	984.00
M PANEL ASSY,TAILGATE								

Estimate

\* Ceramic Coating 80 X 2 = 160  
(provide sales agreement)

# Estimate

\* Ceramic Coating 80 X 2 = 160  
(provide self agreement)

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
LINUS LOO KAH MENG	Cust No/Name KCV15963/LINUS LOO KAH MENG
2 PANDAN VALLEY	Reg No/Reg Date SMU9028Y / 03/09/202
#03-209	Date In/Mileage / 0
SINGAPORE 597626	Chassis No GF7W0700518
Contact No Mobile: 92984208	Engine No 4J11CL0583
	Make/Model MIT/20MY OUTLANDER 2.0 STYLE (999)
	Colour/Trim W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	19/01/2021/ 09:55	QUK	282 / Kevin Leong	61971			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GARNISH, TAILGATE	X NAI			1.00	494.00	00.00	494.00
M	DAM, TAILGATE, LWR	/ NCC			1.00	41.00	00.00	41.00
M	STOPPER, WINDSHIELD GLASS	/ NCC			2.00	3.00	00.00	6.00
M	DAM, TAILGATE SIDE	/ NCC			2.00	27.00	00.00	54.00
M	FASTENER, WINDSHIELD	/ NCC			2.00	6.00	00.00	12.00
M	DAM, TAILGATE, UPR	/ NCC			1.00	13.00	00.00	13.00
M	GLASS, TAILGATE WINDOW	X NAI			1.00	654.00	00.00	654.00
M	MARK, OUTLANDER	/ NCC			1.00	95.00	00.00	95.00
M	TRIM, RR END	X NAI			1.00	113.00	00.00	113.00
M	BODY KIT, OUTLANDER	X NAI			1.00	1554.00	00.00	1554.00

## Estimate

Steve CLKK) OD- NAI AL  
26/1/21, 10.00a EX GRS - ?  
P/P  
My BL Sry  
5 dys

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm &amp; accepted by

Date:

7% GST on **Nett** 11,810.00  
11810.00 826.70  
**Total Payable** 12,636.70

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.